1	Richard D. McCune, State Bar No. 132 rdm@mccunewright.com	124
2	David C. Wright, State Bar No. 177468 dcw@mccunewright.com	
3	McCune Wright Arevalo LLP 3281 Guasti Road, Suite 100	
4	Ontario, California 91761 Telephone: (909) 557-1250	
5	Facsimile: (909) 557-1275	
6	Joseph G. Sauder jgs@mccunewright.com	
7	Matthew D. Schelkopf (pro hac vice) mds@mccunewright.com	
8	Joseph B. Kenney jbk@mccunewright.com	
9	MCCUNE WRIGHT AREVALO LLP 555 Lancaster Avenue	
10	Berwyn, Pennsylvania 19312 Telephone: (610) 200-0581	
11	Attorneys for Plaintiffs and the Putative	e Class
12	Thiorneys for I tunings and me I manve	Ciuss
13	IN THE UNITED S	STATES DISTRICT COURT
14	FOR THE CENTRAI	L DISTRICT OF CALIFORNIA
15		
16	In re: Kia Engine Litigation	Case No.: 8:17-cv-00838-JLS-JDE
17 18		The Honorable Judge Josephine L. Staton Original Complaint filed: May 10, 2017
19		CONSOLIDATED CLASS ACTION COMPLAINT
20		1. Violation of the California Consumer
21		Legal Remedies Act (Cal. Civ. Code § 1750, <i>et seq.</i> ); 2. Violation of California Unfair
22		Competition Laws (Cal. Bus. & Prof.
23		Code § 17200); 3. Violation of California False Advertising Law (Cal. Bus. & Prof. Code §§ 17500, et
24		seq.); 4. Violation of Maine Unfair Trade Practices
25		Act (Me. Rev. Stat. Ann. tit. 5, § 205, <i>et</i>
26		seq.); 5. Breach of Express Warranty; 6. Breach of Implied Warranty;
27		<ul><li>6. Breach of Implied Warranty;</li><li>7. Breach of Written Warranty Under the Magnuson-Moss Warranty Act (15 U.S.C.)</li></ul>
28		§ 2301, et seq.); 8. Common Law Fraud:
	]	J. Common Law Plauu.

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

9. Breach of the Duty of Good Faith and

Fair Dealing;
10. Violation of the Song-Beverly Act –
Breach of Implied Warranty (Cal. Civ.
Code §§ 1792, 1791.1, et seq.)

## **DEMAND FOR JURY TRIAL**

## PLAINTIFFS' CONSOLIDATED CLASS ACTION COMPLAINT

Plaintiffs Christopher Stanczak, Rose Creps, Cara Centko, and Jenn Lazar bring this action against Defendants Kia Motors America, Inc. ("KMA"), and Does 1 through 10 (collectively "Defendants"), by and through their attorneys, individually and on behalf of all others similarly situated, and allege as follows:

## INTRODUCTION

- This is a class action lawsuit brought by Plaintiffs on behalf of themselves and 1. a class of current and former owners and lessees with Theta 2.0-liter and 2.4-liter gasoline direct injection engines (the "GDI Engines") installed in certain 2011-2016 Kia Optima, Sorento and Sportage vehicles (the "Class Vehicles").<sup>1</sup>
- 2. This action arises from Defendants' failure to disclose to Plaintiffs and similarly situated consumers, despite their longstanding knowledge, that the engines in the Class Vehicles contain, *inter alia*, a latent defect that results in the restriction of oil flow through the connecting rod bearings, as well as to other vital areas of the engine. This defect which typically manifests itself during and shortly after the limited warranty period has expired – will cause the Class Vehicles to experience vehicle stalling during operation and catastrophic engine failure.

Plaintiffs reserve the right to amend or add to the vehicle models and model years included in the definitions of Class Vehicles after conducting discovery.

- 3. Significantly, the presence of this defect, resulting in restricted oil flow within the engine, poses a safety risk to the operator and passengers of the Class Vehicles. The failure to have sufficient engine lubrication can cause complete and catastrophic engine failure while the Class Vehicles are in operation at any time and under any driving conditions or speed. This exposes the driver and occupants of the Class Vehicles, as well as others who share the road with them, to an increased risk of accident, injury, or death. As discussed further herein, numerous owners and lessees of the Class Vehicles have experienced engine damage and catastrophic failure while operating the Class Vehicles, thus placing themselves and those around them in immediate danger.
- 4. Not only did Defendants actively conceal the fact that particular components within the Class Vehicles' engines are prone to failure, they did not reveal that the existence of the defect would diminish the intrinsic and resale value of the Class Vehicles and lead to the safety concerns described herein.
- 5. Defendants have long been aware of the defect described herein, yet Defendants have routinely refused to repair the Class Vehicles without charge when the defect manifests. Indeed, in many cases Defendants have even refused to disclose the existence of the defect when Class Vehicles displaying symptoms consistent with the defect are brought in for service, instead choosing to ignore the defect until it has caused significant mechanical problems necessitating costly repairs.
- 6. Many other owners and lessees of the Class Vehicles have communicated with Defendants and/or their agents to request that they remedy and/or address the defect and/or resultant damage at no expense. Defendants have routinely failed to do so even within the warranty period.
- 7. Defendants have also refused to take any action to correct this concealed defect when it manifests in the Class Vehicles outside of the warranty period. Because the defect can manifest shortly outside of the warranty period for the Class Vehicles and given Defendants' knowledge of this concealed, safety-related defect Defendants'

attempt to limit the warranty with respect to the engine defect is unconscionable and unenforceable here.

- 8. Despite notice and knowledge of the defect from the numerous complaints it has received, information received from dealers, National Highway Traffic Safety Administration ("NHTSA") complaints, and their own internal records, including pre-sale durability testing, Defendants have not recalled and/or offered an adequate engine repair to the Class Vehicles, offered their customers suitable repairs or replacements free of charge, or offered to reimburse their customers who have incurred out-of-pocket expenses to repair the defect.
- 9. As a result of Defendants' unfair, deceptive and/or fraudulent business practices, owners and/or lessees of the Class Vehicles, including Plaintiffs, have suffered an ascertainable loss of money and/or property and/or loss in value. The unfair and deceptive trade practices committed by Defendants were conducted in a manner giving rise to substantial aggravating circumstances.
- 10. Had Plaintiffs and other Class Members known of the defect at the time of purchase or lease, they would not have bought or leased the Class Vehicles, or would have paid substantially less for them.
- 11. Plaintiffs are also informed and believe, and on that basis allege, that as the number of complaints increased, and Class Members grew dissatisfied with the performance of the Class Vehicles, Defendants were forced to acknowledge that the Class Vehicles suffer from an inherent defect.
- 12. As a result of the defect and the monetary costs associated with attempting to repair the defect, Plaintiffs and the Class Members have suffered injury in fact, incurred damages, and have otherwise been harmed by Defendants' conduct.
- 13. Accordingly, Plaintiffs bring this action to redress Defendants' violations of the consumer protection statutes of California and Maine and also seek recovery for Defendants' breach of express warranty, breach of implied warranty, breach of the duty of good faith and fair dealing, and common law fraud.

# 

## **JURISDICTION**

- 14. This Court has subject matter jurisdiction of this action pursuant to 28 U.S.C. § 1332 of the Class Action Fairness Act of 2005 because: (i) there are 100 or more class members, (ii) there is an aggregate amount in controversy exceeding \$5,000,000, exclusive of interest and costs, and (iii) there is minimal diversity because at least one plaintiff and one defendant are citizens of different States. This court has supplemental jurisdiction over the state law claims pursuant to 28 U.S.C. § 1367.
- 15. This Court has personal jurisdiction over Defendants because they have conducted substantial business in this judicial district, and intentionally and purposefully placed Class Vehicles into the stream of commerce within the districts of California and throughout the United States.

## **VENUE**

16. Venue is proper in this judicial district pursuant to 28 U.S.C. §1391 because KMA maintains its corporate headquarters in this district, Defendants transact business in this district, are subject to personal jurisdiction in this district, and therefore are deemed to be citizens of this district. Additionally, there are one or more authorized Kia dealers within this district and Defendants have advertised in this district and have received substantial revenue and profits from their sales and/or leasing of Class Vehicles in this district; therefore, a substantial part of the events and/or omissions giving rise to the claims occurred, in part, within this district.

## **PARTIES**

# A. <u>Plaintiff Chris Stanczak</u>

- 17. Plaintiff Chris Stanczak is a citizen of the State of California, and currently resides in Lincoln, California.
- 18. On or about October 8, 2014, Plaintiff Stanczak leased a new 2015 Kia Optima LX (VIN: KNAGM4A73F5554289) from Roseville Mitsubishi-Kia located in Roseville, California. During his lease term, Plaintiff purchased his 2015 Kia Optima LX.

- 19. Plaintiff Stanczak purchased (and still owns) this vehicle, which is used for personal, family and/or household uses.
- 20. On or about August 22, 2016, while driving on the highway, Plaintiff Stanczak began to hear an unusual engine noise upon acceleration. He then brought his vehicle to Roseville Mitsubishi-Kia, an authorized Kia dealership located in Roseville, California, that same day. At the time, his vehicle had approximately 59,787 miles on the odometer.
- 21. Roseville Kia had Plaintiff Stanczak's vehicle in its possession for diagnosis until on or about August 30, 2016. A service technician found, and notated in the repair order, that they had discovered metal shavings inside the vehicle's engine and that the vehicle's engine would need to be replaced. Plaintiff Stanczak then requested that such needed repairs be completed at no charge pursuant to the terms of the factory warranty. Plaintiff Stanczak's request was denied.
- 22. Because Plaintiff Stanczak was denied the requested warranty repair, he then took his vehicle home so that he could obtain a second opinion. On the following day, while Plaintiff Stanczak was merging onto a highway, the engine in his vehicle seized and catastrophically failed while traveling at approximately 35 miles per hour. Fortunately, Plaintiff Stanczak was able to quickly pull his vehicle to the side of the road. He then phoned for road service and paid approximately \$180 to have his vehicle towed back to Roseville Mitsubishi-Kia.
- 23. Plaintiff Stanczak's vehicle remained at Roseville Mitsubishi-Kia from August 31, 2016, until October 3, 2016. Representatives of Roseville Mitsubishi-Kia initially informed Plaintiff Stanczak that the vehicle's long block<sup>2</sup> needed to be replaced, but that the necessary parts were on nationwide backorder.
- 24. Plaintiff Stanczak then contacted Kia's corporate offices and requested that Kia cover the necessary repairs under its warranties. Kia's corporate representative

<sup>&</sup>lt;sup>2</sup> "Long block" is an automotive term for an engine sub-assembly that consists of the assembled engine block, crankshaft, pistons, connecting rods, cylinder head, camshafts, and valve train.

declined to honor Plaintiff Stanczak's request. Plaintiff Stanczak also requested rental car coverage since he was without his vehicle, which Kia also declined. Kia also informed Plaintiff Stanczak that the long block for his vehicle was actually no longer in production and, as a result, they needed to order a used long block.

- 25. Roseville Mitsubishi-Kia quoted Plaintiff Stanczak approximately \$3,200 for the used engine. Plaintiff Stanczak inquired where it was ordering the engine from so he could check the price. Upon further investigation, Plaintiff Stanczak found that the price for the engine was actually \$2,210 and that the dealership was attempting to charge him a \$1,000 "finder's fee" on the engine.
- 26. Plaintiff Stanczak purchased the engine himself from Kia's source and had it shipped to the dealership. Plaintiff Stanczak paid Roseville Mitsubishi-Kia approximately \$1,980.00 for labor to install the used engine in his vehicle.
- 27. At all times relevant herein, Plaintiff Stanczak adhered to Kia's recommended maintenance intervals.
- 28. Plaintiff Stanczak has suffered an ascertainable loss as a result of Defendant's omissions and/or misrepresentations associated with the engine defect, including, but not limited to, out of pocket losses associated with the engine defect, diminished value of his vehicle, and other consequential damages.
- 29. Neither Defendant, nor any of their agents, dealers, or other representatives informed Plaintiff Stanczak of the existence of the defect prior to, or any time after, his purchase.

# B. <u>Plaintiff Rose Creps</u>

- 30. Plaintiff Rose Creps is a citizen of the State of Maine, and currently resides in Auburn, Maine.
- 31. On or about April 21, 2015, Plaintiff Creps purchased a new 2015 Kia Optima EX (VIN: 5XXGN4A79FG394415) from Rowe Kia Auburn, an authorized Kia dealership located in Auburn, Maine.

- 32. Plaintiff Creps purchased (and still owns) this vehicle, which is used for personal, family and/or household uses.
- 33. In or about July 23, 2016, with approximately 43,473 miles on the odometer, while accelerating to merge onto a highway, Plaintiff Creps heard a loud banging noise originating from the engine. Plaintiff Creps immediately pulled over and called Rowe Kia Auburn and made an appointment to bring her vehicle in so that the dealership could evaluate it.
- 34. The dealership informed Plaintiff Creps that her PCV valve was "bad" and needed to be replaced. The dealership also informed Plaintiff Creps that they found sludge in the engine oil. Plaintiff Creps requested warranty repairs and the dealership informed her that the PCV valve would be replaced under Kia's warranty but that it would not "clean the engine" of the sludge under the warranty and required Plaintiff Creps to pay approximately \$294.71 for this service, which Plaintiff Creps paid.
- 35. In or about early August 2016, Plaintiff Creps was driving her vehicle in New Jersey when she accelerated to merge across traffic and her vehicle again made a loud knocking noise before it shut off entirely and stalled during operation.
- 36. Plaintiff Creps had her vehicle towed to a Kia dealership in New Jersey who examined it, filled it with oil, and instructed her to drive it back to her dealership in Auburn, Maine, which Plaintiff Creps did.
- 37. Plaintiff Creps brought her vehicle to Rowe Kia Auburn on or about August 8, 2016, with approximately 44,688 miles on the odometer, and requested no-cost repairs under the terms of Kia's warranties. The dealership informed Plaintiff Creps that her engine needed to be replaced. The dealership also informed Plaintiff Creps that she needed to produce documentation for all oil changes in order to receive warranty repairs, otherwise she would be required to pay out of pocket for any repairs.
- 38. At all times relevant herein, Plaintiff Creps adhered to Kia's recommended maintenance intervals. Plaintiff Creps, however, did not keep receipts of each and every oil change.

- 39. Plaintiff Creps brought the oil change receipts that she did have to Rowe Kia Auburn. Regardless, the dealership denied her warranty claim, and quoted her approximately \$5,324.21 in parts and labor to complete the required engine replacement.
- 40. Plaintiff Creps then contacted Kia's corporate office and again requested her engine be replaced under warranty. Kia corporate denied her request but offered her a credit of approximately \$1,200.00 as a goodwill gesture, which Plaintiff Creps declined.
- 41. During this time, Plaintiff Creps was unable to drive her vehicle and paid approximately \$576.93 for a rental car from August 8, 2017, until August 26, 2017.
- 42. After being denied warranty repairs by both Rowe Kia Auburn and Kia's corporate office, Plaintiff Creps was forced to pay \$5,324.21 to replace her engine.
- 43. Plaintiff Creps has suffered an ascertainable loss as a result of Defendant's omissions and/or misrepresentations associated with the engine defect, including, but not limited to, out-of-pocket losses associated with the engine defect, diminished value of her vehicle, and other consequential damages.
- 44. Neither Defendant, nor any of its agents, dealers, or other representatives informed Plaintiff Creps of the existence of the defect prior to, or any time after, her purchase.

# C. Plaintiff Cara Centko and Plaintiff Jenn Lazar

- 45. Plaintiff Cara Centko is a resident of Oregon, residing in Portland, Oregon.
- 46. Plaintiff Jenn Lazar is a resident of Oregon, residing in Portland, Oregon.
- 47. In September of 2014, Plaintiffs leased a 2015 Kia Sorento from Kia of Valencia in California. Plaintiffs Centko and Lazar leased this vehicle for personal, family and/or household uses.
- 48. Both did so in reliance on Kia's representations that they were receiving a safe, usable vehicle. However, in December 2016, the vehicle began experiencing major issues with the engine and it became noisier and noisier. When Plaintiffs took the vehicle in to be inspected, they were told that oil sludge was causing the performance issues and

ultimately Kia of Portland, an authorized dealership located in Portland, Oregon, recommended they replace the engine long block.

- 49. Plaintiffs presented the car to the dealer for repair and/or inspection on December 19, 2016 with approximately 25,501 miles on the odometer. The dealership informed Plaintiffs that they needed to produce documentation for all oil changes in order to receive warranty repairs, otherwise They would be required to pay out of pocket for any repairs.
- 50. At all times relevant herein, Plaintiffs adhered to Kia's recommended maintenance intervals. Plaintiffs, however, did not keep receipts of each and every oil change. Plaintiffs produced the receipt they had and show the dealer charges to their credit card for other oil change events. Regardless, the dealership denied her warranty claim, and stated unless Plaintiffs paid for a full diagnostic the dealership would not give an estimate.
- 51. Plaintiffs contacted Kia Leasing at least five times and Kia of America at least 3 times seeking resolution. Despite repeated contacts and demands for estimates to make the repairs to the vehicle and install the needed "new engine," as it was referred to by Kia on the phone, no estimate for repairs was provided. Plaintiffs refused to pay for a full diagnostic as all issues should have been resolved under warranty.
- 52. Plaintiffs took the car home and continued to honor their lease and make payments of \$299.30 per month until the contract was fulfilled. At the end of the lease, the car was surrendered and transported to Kia of Portland for preservation and storage during the pendency of this litigation.
- 53. Plaintiffs had performed all things agreed to or required under the lease agreement and warranty, except as may have been excused or prevented by the conduct of Kia. However, Kia refused to honor the warranty on the vehicle.
- 54. Plaintiffs have suffered an ascertainable loss as a result of Defendant's omissions and misrepresentations associated with the Defect, including but not limited to out of pocket loss associated with the repair of the Defect as well as the diminished value of their vehicle occasioned by the engine defect.

8

11 12

13 14

15 16

17 18

19

20

21 22

23 24

25 26 27

28

55. Neither Kia nor any of its agents, dealers, or other representatives informed Plaintiffs of the existence of the Defect or defective vehicle design, manufacture, or materials prior to purchase. Similarly, despite efforts to get Kia to accept responsibility following manifestation of the engine defect in Plaintiffs' vehicle, Kia has continued to deny the existence of a defect and to actively conceal its existence.

#### D. **Defendant KMA**

- 56. Defendant KMA is an automobile design, manufacturing, distribution, and/or service corporation doing business within the United States. Furthermore, Defendant KMA designs, develops, manufactures, distributes, markets, sells, leases, warrants, services, and repairs passenger vehicles, including the Kia Class Vehicles.
- 57. Defendant KMA is incorporated and headquartered in the state of California with its principal place of business at 111 Peters Canyon Road, Irvine, California 92606. KMA is the U.S. sales and marketing division, which oversees sales and other operations across the United States. KMA distributes Kia vehicles and sells these vehicles through its network of more than 700 dealerships. Money received from the purchase or lease of a Kia vehicle from a dealership flows from the dealer to KMA.
- 58. Upon information and belief, the distribution, service, repair, installation, and decisions regarding the GDI Engine as it relates to the engine defect within the Kia Class Vehicles was performed by Defendant KMA.
- Upon information and belief, Defendant KMA developed the post-purchase 59. owner's manuals, warranty booklets, and information included in maintenance recommendations and/or schedules for the Kia Class Vehicles.
  - 60. KMA engages in continuous and substantial business in California.
- 61. The true names and capacities of the defendants sued herein as DOES 1 through 10, inclusive, are currently unknown to Plaintiffs, who therefore sue such defendants by such fictitious names. Each of the defendants designated herein as a DOE is legally responsible in some manner for the unlawful acts referred to herein. Plaintiffs will

seek leave of Court to amend this Complaint to reflect the true names and capacities of the defendants designated herein as DOES when such identities become known.

3

## **CALIFORNIA LAW APPLIES**

45

62. It is appropriate to apply California law to the nationwide claims because California's interest in this litigation exceeds that of any other state.

6 7 63. As discussed above, Defendant KMA is located in Irvine, California and is the sole entity in the contiguous 48 U.S. states responsible for distributing, selling, leasing and warranting Kia vehicles.

9

10

11

12

8

64. KMA maintains customer relations, engineering, marketing, and warranty departments at their corporate headquarters in this district. KMA's customer service complaint address is Kia Motors America Consumer Affairs Department, P.O. Box 52410, Irvine, California 92619-2410. KMA's customer relations departments are responsible for fielding customer complaints and monitoring customer complaints posted to their respective websites or third-party websites. KMA's warranty and engineering departments are both responsible for the decisions to conceal the engine defect from KMA's prospective customers, and for instituting a policy to systematically deny warranty coverage to those

13

14

15

16

17

who experienced engine failure caused by the defect.

18 19

65.

rise to this action were developed in, and emanated from, KMA's headquarters in Irvine, California. As detailed below, KMA also came to know, or should have come to know, of

Based on the foregoing, such policies, practices, acts, and omissions giving

2021

the engine defect through the activities of their divisions and affiliated entities located

22

within California. Accordingly, the state of California has the most significant relationship

23

to this litigation and its law should govern.

2425

# TOLLING OF STATUTES OF LIMITATIONS

26

66. Any applicable statute(s) of limitations have been tolled by Defendants' knowing and active concealment and denial of the facts alleged herein. Plaintiffs and the members of the Class could not have reasonably discovered the true, latent nature of the engine defect until shortly before this class action litigation was commenced.

- 67. In addition, even after Plaintiffs and Class Members contacted Defendants and/or their authorized dealers for vehicle repairs concerning the engine defect, they were routinely told by Defendants and/or through their dealers that the Class Vehicles were not defective. As described below, the true cause of the premature and catastrophic failure in the Class Vehicles is a defect that results in restricted oil flow.
- 68. Defendants were and remain under a continuing duty to disclose to Plaintiffs and the Members of the Class the true character, quality, and nature of the Class Vehicles, that the manufacturing defect will result in restricted oil flow and catastrophic engine failure, and that the defect will require costly repairs, pose safety concerns, and diminish the resale value of the Class Vehicles. As a result of the active concealment by Defendants, any and all applicable statutes of limitations otherwise applicable to the allegations herein have been tolled.

## FACTUAL ALLEGATIONS

## A. The Defective Engine Components within the Class Vehicles

- 69. Kia Motors Corporation ("KMC"), one of the leading motor vehicle manufacturers in Korea, was established in December, 1944 under the laws of the Republic of Korea to manufacture and sell a range of passenger cars, recreational vehicles and other commercial vehicles in the domestic and international markets. As of December 31, 2016, Kia Motors Corporation's largest shareholder is Hyundai Motor Company, which holds 33.88 percent of KMC's stock.<sup>3</sup>
- 70. KMA is the American sales, marketing, and distribution arm of KMC. KMA offers a complete line of vehicles through more than 755 dealers throughout the United States.

<sup>&</sup>lt;sup>3</sup> <a href="http://www.kia.com/worldwide/about\_kia/investor\_relations/annual\_report.do">http://www.kia.com/worldwide/about\_kia/investor\_relations/annual\_report.do</a> (2016) Annual Report, pg. 67) (last visited August 7, 2017).

# 

71. Upon information and belief, certain GDI Engines, which KMC and Defendant KMA used in the Class Vehicles, were manufactured by Hyundai Motor Company.

## 1. The GDI Engines

- 72. The Theta 2.0 liter and 2.4 liter engines contained in the Class Vehicles contain a gasoline direct-injection ("GDI") fuel delivery system. Kia advertises that "[i]t's the Gasoline Direct Injection engine that helps a Kia deliver outstanding performance—in both power and fuel use. GDI injects highly-pressurized fuel directly into the cylinders during the engine's combustion cycle. The result is an increased quality of combustion and efficiency. By making smarter use of fuel, GDI also reduces emissions. What the driver experiences is still the most critical element of any powertrain technology. And with GDI, the driver enjoys smooth, powerful acceleration and a longer time between refueling."
- 73. As background, the GDI Engines contained in the Class Vehicles use four reciprocating pistons to convert pressure into a rotating motion. Gasoline is mixed with air in the combustion chambers of the engine. To generate such rotating motion, a four-step sequence is used (the "Combustion Cycle"). First, the intake stroke begins with the inlet valve opening and a vaporized fuel mixture is pulled into the combustion chamber. Second, the compression stroke begins with the inlet valve closing and the piston beginning its movement upward, compressing the fuel mixture in the combustion chamber. Third, the power stroke begins when the spark plug ignites the fuel mixture, expanding the gases and generating power that is transmitted to the crankshaft. And fourth, the exhaust stroke begins with the exhaust valve opening and the piston moving back up, forcing the exhaust gases out of the cylinder. The exhaust valve then closes, the inlet valve opens, and the Combustion Cycle repeats itself. A diagram of Combustion Cycle is below:

-14-

74. The pistons are connected to the crankshaft via the connecting rod. As the connecting rod moves up and down during the Combustion Cycle, this causes the crankshaft to rotate, ultimately resulting in power to the drive wheels of the vehicle. During this cycle, the crankshaft rotates many thousands of times per minute within each connecting rod. In order to reduce friction and prolong longevity, this design utilizes a bearing placed between the connecting rod and crankshaft surfaces. The connecting rod bearings allow the crankshaft to rotate within the connecting rods during the Combustion Cycle. An exemplar diagram of the piston, connecting rod, connecting rod bearing and crankshaft are shown below:





Figure 3-70.—Connecting rod bearings.

When the Class Vehicles are in operation, engine oil is used to lubricate the

75.

pistons, cylinder walls, connecting rod bearings and other rotating and moving components as the pistons moves up and down through the four-stroke sequence. Engine oil is necessary to reduce wear on moving parts throughout the engine, improve sealing, and cool the engine by carrying away heat from the moving parts. Engine oil also cleans and transports contaminants away from the engine to the engine oil filter. Oil is pumped and pressurized throughout the engine by the oil pump. The oil pump draws oil from the oil pan, located underneath the piston and crankshaft. The oil pump forces engine oil through the oil filter and then through passages in the engine to properly lubricate and reduce friction in internal moving engine components. The oil then returns to the oil pan through small drainage holes located throughout the engine where it will be recirculated by the oil pump. Below is a diagram illustrating the typical path and channels of engine oil lubrication in an overhead cam engine:



76. The connecting rod bearings are also lubricated with engine oil in order to allow the crankshaft to rotate within the connecting rods. A close-up picture of a functional connecting rod bearing is below:



## 2. Previous GDI Engine Recalls

- In or around September 10, 2015, Hyundai Motor America publicly recalled certain model year 2011-2012 Sonata vehicles manufactured at Hyundai Motor Manufacturing Alabama and equipped with the 2.4 liter and 2.0 liter GDI Engines. (See Exhibit 1.)
- 78. According to the Hyundai GDI Recall, Hyundai determined that metal debris may have been generated from factory machining operations as part of the manufacturing of the engine crankshaft during December 11, 2009, to April 12, 2012. As a result, and according to the Hyundai GDI Recall:

- [i]f the debris is not completely removed from the crankshaft's oil passages, it can be forced into the connecting rod oiling passages restricting oil flow to the bearings. Since bearings are cooled by oil flow between the bearing and journal, a reduction in the flow of oil may raise bearing temperatures increasing the potential of premature bearing wear. A worn connecting rod bearing will produce a metallic, cyclic knocking noise from the engine which increases in frequency as the engine rpm increases. A worn connecting rod bearing may also result in illumination of the oil pressure lamp in the instrument cluster. If the vehicle continues to be driven with a worn connecting rod bearing, the bearing can fail, and the vehicle could stall while in motion.
- 79. Hyundai went on to explain, in Safety Recall Report 15V-568, that it became aware of engine-related warranty claims in the field. Furthermore, "[t]he vast majority of those claims evidenced that customers were responding to substantial noise, or the vehicle's check engine light, and bringing their vehicles to service as a result of those warnings. Many customers also complained after the warranty was no longer available."
- 80. As a result, Hyundai decided to issue a safety recall for approximately 470,000 model year 2011-2012 Sonata vehicles manufactured between December 11, 2009 and April 12, 2012 at Hyundai Motor Manufacturing Alabama and equipped with either a 2.0 liter or 2.4 liter Gasoline Direct Injection engine.
- 81. The recall provided notification to owners of the issue, inspection, and replacement of the engine assembly, as necessary, free of charge. Additionally, Hyundai increased the warranty for the engine sub-assembly (short block) to 10 years/120,000 miles for both original and subsequent owners.
- 82. In a document filed with NHTSA, attached hereto as Exhibit 2, Kia claims the following relevant chronology took place regarding its knowledge of the defect:
  - a. **September 2015:** Kia learns of the Hyundai recall related to engine damage in 2011-2012 MY Sonata vehicles with Theta engines caused by oil blockage from debris left in engines during manufacturing at Alabama plant.
  - b. **January–April, 2016:** Engine remanufacturer Translead conducts detailed review of all recent Kia warranty returned engines. Translead

- identifies oil delivery issue with Theta GDI engines (Optima, Sportage & Sorento). Low claims rate with no accidents/injuries. Decision: monitoring.
- c. **May 5, 2016:** Kia learns of Hyundai Sonata warranty extension program for next two model years after recall (2013 MY-2014 MY).
- d. May 5-25, 2016: Kia Motors America, Inc. (KMA) analyzes field data for Theta engine vehicles. No accidents or injuries. Claims are low but have increased. Customer satisfaction identified as critical complaint factor due to high engine repair costs for vehicles out of warranty (especially used vehicle owners). Decision: extend warranty AND encourage customer repairs before breakage with one customer notice.
- e. **May 25–June 10, 2016:** Kia extends warranty coverage to all 2011-2014 MY Optima owners (original and used) with 2.0L and 2.4L GDI engines to 10 years or 120,000 miles to reduce customer financial burden. Emphasis on customer opportunity to get repair done before engine breakage based on clear knocking noise developing as mutual benefit for both customer and Kia.
- f. **August 24 and 29, 2016:** KMA notifies owners of 2011-2014 Sportage and 2012-2014 Sorento vehicles equipped with 2.0L and 2.4L Theta GDI engines of Warranty Extension Program.
- g. **October 21, 2016:** KMA sees continuing costs related VOQs [Vehicle Owner Questionnaire] and determines dealers are not approving extended warranty repairs due to customer lack of oil maintenance proof. Decision: KMA advises dealers that coverage under the Extended Warranty Program does not require maintenance records.
- h. March 28, 2017: Kia makes decision to conduct a voluntary safety recall based on anticipatory risk concerns.
- 83. As described above, in or around May 25-June 10, 2016, Kia followed Hyundai's lead and notified owners of 2011-14 MY Optima vehicles of issues with the same connecting rod wear which results in knocking noise from the engine. (*See* Exhibits 2 and 3.) As a result, Kia provided all owners with a warranty extension on the "short block" assembly for a period of 10 years starting from the date of first service or 120,000

<sup>&</sup>lt;sup>4</sup> Per Kia's description, the short block consists of the engine block, crankshaft and bearings, connecting rods and bearings and pistons. *See* Exhibit 2.

miles. Kia also alerted owners that if the vehicles continue to be driven with a worn connecting rod bearing, the bearing can fail and may result in engine failure.

- 84. In April 2017, Hyundai and Kia announced that they were recalling an additional 1.4 million vehicles with the GDI Engines because they received widespread reports that the engines could fail and stall, *i.e.* the same reason for the first recall. This recall included the 2013-2014 Hyundai Santa Fe, the 2011-2014 Kia Optima, the 2011-2013 Kia Sportage, and the 2012-2014 Kia Sorento vehicles. (*See also* Exhibit 4.)
- 85. Despite Kia's recall, Defendant Kia has failed to adequately repair the recalled 2011-14 Kia Class Vehicles. Instead, the parts required to conduct the repair are typically unavailable, on nationwide backorder and/or no longer being manufactured. This has resulted in Class Members being without the use of their vehicles for weeks and/or months at a time and incurring additional and unreimbursed expenses such as rental vehicles. Furthermore, when repaired, Kia often utilizes used replacement parts which fail to adequately place Class Members in the same position as prior to such engine failures.
- 86. The model year 2015-16 Kia Class Vehicles have also not been recalled despite being equipped with the same engines as the recalled model year 2011-14 Kia Class Vehicles, as well as Plaintiffs and Members of the Class notifying Kia about their engines stalling and failing while being operated. Kia is also aware that these engines are prone to the same failure and risk to safety as the 2011-14 Class Vehicles yet has failed to provide the appropriate notice to Class Members, as well as, the appropriate and necessary repairs.

## 3. Engine Failures within the Class Vehicles

87. Upon information and belief, the connecting rod bearings in the GDI Engines undergo prolonged failure as metal debris circulates throughout the engine via the engine oil. Over time, and as a result of these contaminants in the oiling system, the connecting rod bearings begin to fracture. Once the connecting rod bearings fracture, large amounts of metal debris begins to accumulate in the engine oil. As a result, the oil

becomes so contaminated with metal debris that the oil filter can no longer remove the plethora of contaminants and maintain the necessary oil pressure within the engine. This contaminated engine oil is recirculated throughout the engine by the oil pump, causing damage to the various engine components and eventually results in sudden and unexpected catastrophic engine failure. If the vehicle is being operated on the highway at the time of the engine failure, it will ultimately result in a high-speed stalling event.

88. Additionally, as the connecting rod bearings continue to fracture, the

- 88. Additionally, as the connecting rod bearings continue to fracture, the acceptable tolerances between the bearings, the connecting rod, and the crankshaft rapidly deteriorate. Eventually, the Class Vehicles begin producing a "knocking" sound originating from the engine as a result of the deteriorating bearings. In some instances, the defective connecting rod bearings may eventually cause the piston to break through the engine block as a result of the deterioration.
- 89. A photograph of a fractured connecting rod bearing removed from a GDI Engine is included below. As shown in the photograph, the bearing has fractured and worn away to the point of laying flush along the inside of the connecting rod. A large fracture is also plainly visible along the bottom left side of the bearing.



14

17

18 19

20 21

22

23 24

25 26

27 28

90. After the connecting rod bearings fail and metal debris is circulated throughout the engine via the engine oil, damage is caused to other key engine components. As pictured below, the main cap – which fastens the crankshaft to the engine – can also be damaged by the metal debris in the engine oil. After the main cap is damaged, play between the main cap and engine develops, which also leads to catastrophic engine failure.



- 91. As a result of the defect, the Class Vehicles suffer from restricted and inadequate engine oil lubrication. As explained above, engines are designed to have oil distributed throughout the engine through lubrication channels. When operating properly, the engine oil is distributed throughout the engine by the oil pump and then flows back to the oil pan where it is redistributed throughout the engine.
- In the Class Vehicles, the lubrication channels become clogged and restricted as a result of the defect, even under normal use and proper maintenance. When the lubrication channels clog, engine oil is unable to be both pumped throughout the engine (through the oil pump) and is also unable to adequately return to the oil pan, causing a condition known as oil starvation. This results in insufficient lubrication throughout the

28 || 3

Class Vehicle's engine, which causes premature wear of the engine components and catastrophic engine failure.

- 93. The engine defect poses serious safety and security issues for operators and occupants of the Class Vehicles. By way of example, the California Department of Motor Vehicles asserts that stalled engines pose a significant safety risk and, as part of its safety curriculum, instructs how to properly respond to a stalled action in order to avoid further risk of injury.
- 94. NHTSA takes a similar view of engine failure during vehicle operation. For instance, according to *Forbes*, in 2011 the NHTSA recalled certain Chrysler and Dodge vehicles due to "engine seizure because of connecting rod bearing failure . . . . Engine seizure could increase the risk of a crash."<sup>5</sup>
- 95. Defendants failed to adequately research, design, test, and/or manufacture the Class Vehicles before warranting, advertising, promoting, marketing, and selling the Class Vehicles as suitable and safe for use in an intended and/or reasonably foreseeable manner.

## B. <u>Defendant KMA's Knowledge of the Engine defect</u>

96. Plaintiffs' experiences are by no means isolated or outlying occurrences. Indeed, the internet is replete with examples of blogs and other websites where consumers have complained of the exact same engine defect within the Class Vehicles and complaints from earlier model year Kia owners and lessees with the same engines. Upon information and belief, Defendant KMA, through (1) their own records of customers' complaints, (2) dealership repair records, (3) records from the National Highway Traffic Safety Administration ("NHTSA"), (4) warranty and post-warranty claims, (5) internal pre-sale durability testing, and (6) other various sources, were well aware of the engine defect but failed to notify consumers of the nature and extent of the problems with the GDI Engines or provide any adequate remedy.

<sup>&</sup>lt;sup>5</sup> <u>http://www.forbes.com/sites/altheachang/2011/09/30/engine-problems-prompt-chrysler-recalls/</u> (last visited August 7, 2017).

- 97. KMA routinely monitors the internet for complaints similar in substance to those quoted below. KMA's customer relations department routinely monitors the internet for customer complaints, and KMA has retained the services of third-parties to do the same. Further, the customer relations division regularly receives and responds to customer calls concerning, *inter alia*, product defects. Through these sources, KMA was made aware of the engine defect. The complaints also indicate KMA's knowledge of the defect and its potential danger.
- 98. KMA is experienced in the design and manufacture of consumer vehicles. As an experienced manufacturer, KMA likely conducts testing on incoming batches of components, including the GDI Engine, to verify that the parts are free from defects and comply with KMA's specifications. Accordingly, KMA knew or should have known that the engine used in the Class Vehicles is defective and likely to fail prematurely, costing Plaintiffs and Class Members thousands of dollars in expenses.
- 99. Moreover, KMA also should have known of the connecting rod bearing defect and insufficient lubrication channels because of the sheer number of reports of engine problems relating to the connecting rod bearings and/or lubrication channels. For instance, KMA's customer relations department, which interacts with Kia-authorized service technicians in order to identify potentially widespread vehicle problems and assist in the diagnosis of vehicle issues, has received numerous reports of engine problems relating to the connecting rod bearings and lubrication channels. Customer relations also collects and analyzes field data including, but not limited to, repair requests made at dealerships and service centers, technical reports prepared by engineers that have reviewed vehicles for which warranty coverage is requested, parts sales reports, and warranty claims data.
- 100. KMA's warranty department similarly reviews and analyzes warranty data submitted by its dealerships and authorized technicians in order to identify defect trends in its vehicles. KMA dictates that when a repair is made under warranty (or warranty coverage is requested), service centers must provide KMA with detailed documentation of the problem and the fix that describes the complaint, cause, and correction, and also save the

broken part in case KMA later determines to audit the dealership or otherwise verify the warranty repair. For their part, service centers are meticulous about providing this detailed information about in-warranty repairs to KMA because KMA will not pay the service centers for the repair if the complaint, cause, and correction are not sufficiently described.

- 101. KMA knew or should have known about the engine defect because of the high number of replacement parts likely ordered from KMA. All Kia service centers are required to order replacement parts, including engines, piston assemblies, and connecting rod bearings directly from KMA. Other independent vehicle repair shops that service Class Vehicles also order replacement parts directly from KMA. KMA routinely monitor part sales reports, and are responsible for actually shipping parts requested by dealerships and technicians. Thus, KMA has detailed, accurate, and real-time data regarding the number and frequency of replacement part orders. The sudden increase in orders for the GDI Engines and engine components used in the Kia Class Vehicles was known to KMA, and should have alerted it to the scope and severity of the engine defect.
- 102. In February 2012, KMA issued a technical service bulletin ("TSB") to its authorized dealerships regarding an engine knocking noise. TSBs are documents used by automotive manufacturers to inform dealership technicians about new information, including vehicle problems, new repair procedures, and improved parts. In TSB No. ENG114R1, KMA acknowledged that the earlier model years of the Class Vehicles with identical engines were defective and experienced a "knocking noise." As a result, KMA directed dealers to blame the engine defect on the use of aftermarket oil filters and instructed the dealers to replace the aftermarket oil filter with a genuine Kia oil filter. The TSB also explained that this "repair" is not covered under warranty. KMA has failed to provide any post-sale notification to owners and lessees regarding the use of only genuine Kia oil filters in the Kia Class Vehicles. Instead, KMA attempts to circumvent warranty obligations related to the engine defect by faulting customers for use of an aftermarket oil filter. The defective connecting rod bearings and oil lubrication channels are not, however, caused by the use of an aftermarket engine oil filter. Despite KMA's knowledge of this

fact, KMA has not informed Plaintiffs of the true cause of the defective connecting rod 1 bearings and insufficient oil lubrication channels. 2 **Complaints by Other Class Members** 3 1. 4 103. Representative examples of complaints on the NHTSA website regarding the 5 Kia Class Vehicles are included below (with emphasis supplied in capitalized bold, underlined letters)<sup>6</sup>: 6 7 KIA GDI Engine Complaints a. 8 Vehicle: 2015 Kia Optima Date Complaint Filed: 05/10/2017 9 Date of Incident: 04/28/2017 10 Component(s): ENGINE NHTSA ID Number: 10984694 11 12 **SUMMARY:** 13 ENGINE LOCKED UP DURRING ACCELERATION TO 40 MPH WHY MERGING INTO TRAFFIC FOUND OUT 14 ENGINE HAS A BENT ROD. OIL AND COOLENT WHERE 15 SUFFICINT BUT KIA WILL NOT FIX OR REPLACE. COULD OF CAUSED MY WIFE TO CRASH OR BE HIT BY 16 **TRAFFIC** 17 18 Vehicle: 2015 Kia Optima 19 Date Complaint Filed: 05/03/2017 20 Date of Incident: 11/26/2016 Component(s): ENGINE 21 NHTSA ID Number: 10983354 22 23 **SUMMARY:** ENGINE LIGHT CAME ON, THEN THE OIL LIGHT. I 24 STOPPED TO CHECK OIL. THERE WAS NO OIL ON THE 25 DIPSTICK. I CHECKED FOR LEAKS. FOUND NONE. I ADDED 2 QUARTS. THE ENGINE WAS KNOCKING. I 26 27 <sup>6</sup> The foregoing complaints are reproduced as they appear on the NHTSA website. Any 28 typographical errors are attributable to the original author of the complaint.

-26-

Consolidated Class Action Complaint Case No. 8:17-cy-00838-JLS-JDE

TOOK IT TO THE DEALERSHIP. MY CAR WAS UNDER WARRANTY. BUT WOULDN'T REPLACE IT. IT WOULD COST ME \$7200. SO I TRIED TO DRIVE IT HOME, AND IT QUIT. THE ENGINE SHUT DOWN. I HAD TO HAVE IT TOWED HOME. THIS WAS IN NOVEMBER 2016. AND IT IS STILL DOWN. THEN I HEARD KIA IS GETTING A CLASS ACTION LAWSUIT AGAINST THEM, FOR OIL FLOW ISSUES. I'M STILL PAYING ON THE CAR. I FINANCED THROUGH MY CREDIT UNION. SO THEY ALREADY GOT THERE MONEY. I THINK THAT IS WHY THEY ARE SCREWING ME OVER. TO BE CLEAR I HAD JUST LEFT THE DEALERSHIP WHEN IT QUIT. IT NEVER MADE A SOUND, THE DEALERSHIP HAD IT 3 DAYS.

Vehicle: 2015 Kia Optima

Date Complaint Filed: 01/09/2017

Date of Incident: 11/01/2016 Component(s): ENGINE

NHTSA ID Number: 10943930

## **SUMMARY:**

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

2015 KIA OPTIMA WAS OUT OF OIL @ 22,000 MILES AND NO INDICATOR LIGHT HAD GONE ON WHEN IT WAS TAKEN TO AN OIL CHANGE. THE OIL CHANGE PLACE WAS THE ONE THAT INDICATED THAT THE VEHICLE HAD NO OIL IN IT. IT STARTED MAKING SOME RATTLING NOISE SPECIALLY GOINT UPHILL SO I TOOK IT IN TO KIA SERVICE DEPARTMENT. THEY DIAGNOSED IT WITH "SLUDGE" IN THE ENGINE AND ENGINE WOULD HAVE TO BE REPLACED. I HAD TO PROVE 3 PREVIOUS RECEIPTS OF OIL CHANGES OTHERWISE THE WARRANTY WOULD NOT COVER IT. I DO NOT HAVE THOSE RECEIPTS AND 16 DAYS LATER TOOK IT TO THE SAME PLACE I DID MOST RECENT OIL CHANGE BECAUSE OIL LIGHT HAD TURNED ON. THE VEHICLE AGAIN HAD NO OIL IN IT. THE TOPPED IT OFF BUT MENTIONED THAT IT WAS NOT NORMAL FOR SUCH A RECENT MODEL TO BE

-27-

1 2 3 4 5 6	BURNING OIL. VEHICLE IS STILL RUNNING BUT MAKES RATTLING NOISE ONCE IN A WHILE, PRODUCES WHITE SMOKE OUT OF EXHAUST PIPE AND I HAVE TO PUT OIL IN IT EVERY COUPLE OF DAYS. I CANNOT AFFORD TO BUY A NEW ENGINE. I AM A SINGLE MOM AND NEEDS A RELIABLE VEHICLE TO GET TO WORK.
7	
8	Vehicle: 2015 Kia Optima
9	Date Complaint Filed: 11/03/2016 Date of Incident: 11/02/2016
10	Component(s): ENGINE
11	NHTSA ID Number: 10923952
12	SUMMARY:
13	THE VEHICLE WAS IN MOTION AND HAD AN OIL CHANGE THE PREVIOUS DAY. THE VEHICLE LOST
14	POWER AND AN AUDIBLE CLICKING OR TAPPING
15	NOISE CAME ON WHILE DRIVING ON THE HIGHWAY.
16	MY WIFE HAD JUST ENOUGH TIME TO PULL OFF INTO A LOCAL BUSINESS AND PARKED THE CAR. I TOOK IT
17	TO KIA AND THEY ADVISED THERE WAS "SLUDGE" IN
	THE ENGINE AND WE HAD NOT BEEN MAINTAIN THE
18	VEHICLE PROPERLY. OFFERED TO PRODUCE RECORDS BUT THEY ADVISED THEY STILL WOULD
19	NOT COVER IT. *TR
20	
21	Vehicle: 2015 Kia Optima
22	Date Complaint Filed: 09/29/2016
23	Date of Incident: 07/22/2016
24	Component(s): ENGINE NHTSA ID Number: 10910586
25	141115/11/2 144111001. 10/10/300
26	SUMMARY:
27	ENGINE FAILURE AT 15 MONTHS OLD AND 42,000 MILES. KIA DENIED WARRANTY COVERAGE
28	BECAUSE I COULD NOT PROVE OIL CHANGES. SAME
	-28-
	Consolidated Class Action Complaint

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

COMPLAINT AS THOUSANDS OF OTHER KIA 1 VEHICLES, HAPPENED ABRUPTLY, CAR STARTING 2 MAKING LOUD RATTLING NOISE ON ACCELERATION 3 WHILE DRIVING, NO WARNING, SLUDGE IN ENGINE. I HAD TO PAY OUT OF POCKET FOR A NEW ENGINE TO 4 BE INSTALLED WITH NO ASSISTANCE FROM KIA OR 5 MY LOCAL DEALERSHIP. 6 7 Vehicle: 2015 Kia Optima 8 Date Complaint Filed: 09/09/2016 Date of Incident: 06/10/2016 9 Component(s): ENGINE 10 NHTSA ID Number: 10905150 11 **SUMMARY**: 12 MY 2015 KIA OPTIMA HAS 23000 MILES.. I COULDN'T 13 REMEMBER WHEN I HAD THE OIL CHANGED, BUT I WAS DRIVING ON 75 COMING FROM FLA. THE AC 14 STOP WORKING AND THEN SHORTLY AFTER THAT 15 THE CAR STARTED TO SLOW DOWN. IT FINALLY CAME TO A COMPLETE STOP, WHEN I GOT IT TO THE 16 KIA DEALERSHIP THEY INFORMED ME THAT THE 17 ENGINE HAD SEIZED .BECAUSE THE SAID I COULD 18 NOT PROVE THAT THE OIL HAD BEEN CHANGED, THE WARRANTY WOULD NOT COVER IT. I BOUGHT THE 19 CAR BRAND NEW, ONLY HAD IT 15 MONTHS, THERE 20 WAS NO WARNING LIGHTS OR ANY SIGNS OF TROUBLE .KIA WILL NOT FIX IT, THEY WANT 21 ALMOST 8.000 TO PUT IN A NEW ENGINE. 22 23 Vehicle: 2015 Kia Optima 24 Date Complaint Filed: 09/07/2016 25 Date of Incident: 09/04/2016 Component(s): ENGINE 26 NHTSA ID Number: 10904330 27 28 **SUMMARY**: -29-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

AS I WAS DRIVING MY 2015 OPTIMA TO THE STORE 1 MY CHECK ENGINE LIGHT CAME ON. THE NEXT DAY I 2 STARTED MY CAR AND HEARD A RATTLING OR 3 TICKING SOUND, THIS WAS ON LABOR DAY, SO I TURNED MY CAR OFF AND CALLED THE 4 DEALERSHIP. DUE TO HOLIDAY THE SERVICE DEPT 5 WAS NOT OPEN. I CALLED THEM AGAIN ON TUESDAY SEPT 6TH AND WAS ADVISED THEY WOULD HAVE IT 6 TOWED. I RECEIVED A PHONE CALL ON TUESDAY 7 EVENING STATING MY MOTOR HAS SLUDGE AND 8 NEEDS TO BE REPLACED. 9 10 Vehicle: 2015 Kia Optima Date Complaint Filed: 09/06/2016 11 Date of Incident: 09/03/2016 12 Component(s): ENGINE 13 NHTSA ID Number: 10904201 14 **SUMMARY:** 15 2015 KIA OPTIMA, ONLY 47K MILES....ENGINE FAILURE...THE DEALERSHIP SAYS ITS SLUDGE... AND 16 I HAVE TO PROVIDE ALL MY MAINTENANCE 17 RECORDS. IT STARTED WITH WHITE SMOKE COMING 18 OUT OF THE TAILPIPE AND LOUD RATTLING NOISE WHEN I ACCELERATED, THEN THIS PAST SATURDAY, 19 IT STARTED TO SHAKE VIOLENTLY AND THE CHECK 20 ENGINE LIGHT WENT ON . I HAD TO GET IT TOWED. THIS IS KIA'S FAULT!!! NOT MINE. I'VE DONE THE 21 SAME ROUTINE MAINTENANCE ON MY TOYOTA AND 22 HONDA WHICH HAD OVER 100K MILES WITH NO 23 PROBLEMS! I AM BEING TOLD BY KIA THAT IT WON'T BE COVERED UNDER THE WARRANTY. 24 25 Vehicle: 2015 Kia Optima 26 Date Complaint Filed: 06/15/2016 27 Date of Incident: 06/04/2016 28 Component(s): ENGINE -30-

Consolidated Class Action Complaint Case No. 8:17-cy-00838-JLS-JDE

NHTSA ID Number: 10874312 1 2 **SUMMARY:** 3 MY 2015 KIA OPTIMA HAS 26,456 MILES. THE LAST OIL CHANGE WAS PERFORMED AT 26,064 MILES. ON 6/4/16 4 WHILE DRIVING APPROX. 50MPH IN 3 LANE TRAFFIC 5 THE ENGINE SEIZED UP, CAR SHUT DOWN AND INTERIOR FILLED WITH SMOKE. HAD VEHICLE 6 TOWED TO KIA. WAS TOLD IT NEEDS A NEW ENGINE 7 DUE TO SLUDGE IN THE OIL. KIA IS REFUSING TO 8 HONOR THE WARRANTY BECAUSE I CANNOT PRODUCE RECEIPTS FOR PREVIOUS OIL CHANGES. I 9 HAVE RESEARCHED AND MANY OTHER KIA 10 VEHICLES ARE HAVING VERY SIMILAR PROBLEMS WITH LOW MILES! THERE HAS TO BE SOMETHING 11 WRONG THAT KIA IS NOT AWARE OF OR IS JUST NOT 12 WILLING TO ADMIT. NOT ONLY WILL THEY NOT FIX 13 MY VEHICLE BUT I FEAR SOMEONE IS GOING TO GET HURT OR EVEN KILLED. I INFORMED KIA OF MY 14 CONCERN BUT THEY DID NOT SEEM TO CARE. 15 16 Vehicle: 2015 Kia Optima 17 Date Complaint Filed: 05/24/2016 18 Date of Incident: 10/15/2015 Component(s): ENGINE 19 NHTSA ID Number: 10870505 20 **SUMMARY:** 21 TL\* THE CONTACT OWNS A 2015 KIA OPTIMA. WHILE 22 DRIVING 60 MPH, SMOKE EMITTED FROM THE 23 ENGINE COMPARTMENT WITHOUT WARNING. THE VEHICLE WAS TAKEN TO THE DEALER. THE 24 TECHNICIAN DIAGNOSED THAT THE NUMBER TWO 25 CYLINDER WAS DEFECTIVE AND NEEDED TO BE REPLACED. THE VEHICLE WAS NOT REPAIRED. THE 26 FAILURE MILEAGE WAS 58,000. 27 28

-31-

3

4

Vehicle: 2015 Kia Sorento

Date Complaint Filed: 04/25/2017

Date of Incident: 04/11/2017 Component(s): ENGINE

NHTSA ID Number: 10980556

5 6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

### **SUMMARY:**

WE STARTED HAVING PROBLEMS AT ABOUT 20,000 MILES.THE CAR WAS PULLING AS WE TRIED TO ACCELERATE AND SMOKE WOULD BLOW OUT OF THE TAILPIPE. WE TOOK IT INTO THE DEALERSHIP IN WHICH THEY STATED WE HAD SLUDGE IN THE ENGINE. THEY STATED TO MAINTAIN REGULAR OIL CHANGES, BUT WE WOULD NEED A NEW ENGINE. 4 MONTHS LATER THEY DID AN OIL CHANGE AND STATED THE OIL WAS CLEAR OF SLUDGE. WITHIN 2 WEEKS, WE HEARD A LOUD BANGING SOUND FROM THE ENGINE, IT GOT LOUDER AND WAS BARELY GOING 5 MILES/HR. WE WERE ON A MAJOR ROAD AND WERE ABLE TO PULL INTO A PARKING LOT. WE HAD IT TOWED TO THE DEALERSHIP (CENTRAL KIA OF PLANO). WITHOUT EVEN LOOKING AT IT, THEY SAID IT WAS THE SLUDGE IN THE ENGINE AND WE NEEDED OUR ENGINE REPLACED (\$7000). THEY WOULD NOT EVEN LOOK UNDER THE HOOD UNTIL WE PAID THEM \$400 TO OPEN IT UP. THEY STATED THE WORK WOULD NOT BE COVERED UNDER OUR WARRANTY EVEN THOUGH WE ARE ONLY 2 YEARS INTO IT AND AROUND 30,000 MILES. I CALLED KIA CONSUMER AFFAIRS (800-333-4542) AND THEY CONTACTED THE DEALERSHIP AND THAT'S WHEN THEY FINALLY OPENED THE HOOD AND FOUND SLUDGE IN THE ENGINE. THEY TOOK PICTURES AND SENT IT TO KIA "TECH" IN WHICH OUR CLAIM WAS DECLINED DUE TO "LACK OF MAINTENANCE". WE PROVIDED RECEIPTS FOR OUR OIL CHANGES. THEY DID NOT ACCEPT 3 OF THEM BECAUSE THEY DID NOT HAVE A "PO#" AND THEY DID NOT ACCEPT 2 OF MY

27

1	CREDIT CARD RECEIPTS. I TOLD KIA CONSUMER
2	AFFAIRS THE 2015'S ARE HAVING THE SAME ISSUES AS THE RECALLS 2011-2014. SHE STATED THE DMV IS
3	COLLECTING INFORMATION ON THE 2015'S.
4	EVERYONE CALL CONSUMER AFFAIRS!! THERE IS AN
5	ENGINE PROBLEM WITH THE 2015'S AND KIA IS NOT STANDING BY THEIR WARRANTY. WE HAVE NOT
6	BEEN PROVIDED A RENTAL CAR. I HAVE ALSO
7	ESCALATED THIS ISSUE TO KIA'S "ESCALATION
8	DEPT" IN WHICH THEY STATED TO GET THEM MORE
	RECEIPTS AND "TECH" CAN REVIEW THE CASE AGAIN! I HAVE GATHERED MORE RECEIPTS
9	INCLUDING HOW OFTEN WE WERE PUTTING OIL IN
10	BETWEEN OIL CHANGES.
11	
12	Vehicle: 2015 Kia Sorento
13	Date Complaint Filed: 08/24/2016
14	Date of Incident: 07/01/2016
15	Component(s): ENGINE NHTSA ID Number: 10898199
16	NHTSA ID Nulliber. 10898199
17	SUMMARY:
	I WAS DRIVING DOWN THE ROAD WITH MY 4
18	
4.0	CHILDREN IN THE CAR AT 45 MPH WHEN ALL OF A
19	SUDDEN MY CAR COMPLETELY LOST POWER. LUCKILY I WAS ABLE TO COAST TO THE SIDE OF THE
19 20	SUDDEN MY CAR COMPLETELY LOST POWER.
	SUDDEN MY CAR COMPLETELY LOST POWER. LUCKILY I WAS ABLE TO COAST TO THE SIDE OF THE ROAD. IT WAS OVER A 100 DEGREES OUTSIDE AND MY 4 KIDS UNDER 6 HAD TO SIT AND WAIT ON A RIDE
20	SUDDEN MY CAR COMPLETELY LOST POWER. LUCKILY I WAS ABLE TO COAST TO THE SIDE OF THE ROAD. IT WAS OVER A 100 DEGREES OUTSIDE AND MY 4 KIDS UNDER 6 HAD TO SIT AND WAIT ON A RIDE IN THE HEAT. THE CAR HAS 40,000 MILES ON IT AND
20 21	SUDDEN MY CAR COMPLETELY LOST POWER. LUCKILY I WAS ABLE TO COAST TO THE SIDE OF THE ROAD. IT WAS OVER A 100 DEGREES OUTSIDE AND MY 4 KIDS UNDER 6 HAD TO SIT AND WAIT ON A RIDE
20 21 22	SUDDEN MY CAR COMPLETELY LOST POWER. LUCKILY I WAS ABLE TO COAST TO THE SIDE OF THE ROAD. IT WAS OVER A 100 DEGREES OUTSIDE AND MY 4 KIDS UNDER 6 HAD TO SIT AND WAIT ON A RIDE IN THE HEAT. THE CAR HAS 40,000 MILES ON IT AND HAS HAD 7 OIL CHANGES, OF WHICH I HAVE PROVIDED THE RECEIPTS FOR. THERE IS ENGINE SLUDGE DESPITE THE FACT THAT THE OIL WAS
20 21 22 23 24	SUDDEN MY CAR COMPLETELY LOST POWER. LUCKILY I WAS ABLE TO COAST TO THE SIDE OF THE ROAD. IT WAS OVER A 100 DEGREES OUTSIDE AND MY 4 KIDS UNDER 6 HAD TO SIT AND WAIT ON A RIDE IN THE HEAT. THE CAR HAS 40,000 MILES ON IT AND HAS HAD 7 OIL CHANGES, OF WHICH I HAVE PROVIDED THE RECEIPTS FOR. THERE IS ENGINE SLUDGE DESPITE THE FACT THAT THE OIL WAS CHANGED MORE FREQUENTLY THAN THE MANUAL
20 21 22 23	SUDDEN MY CAR COMPLETELY LOST POWER. LUCKILY I WAS ABLE TO COAST TO THE SIDE OF THE ROAD. IT WAS OVER A 100 DEGREES OUTSIDE AND MY 4 KIDS UNDER 6 HAD TO SIT AND WAIT ON A RIDE IN THE HEAT. THE CAR HAS 40,000 MILES ON IT AND HAS HAD 7 OIL CHANGES, OF WHICH I HAVE PROVIDED THE RECEIPTS FOR. THERE IS ENGINE SLUDGE DESPITE THE FACT THAT THE OIL WAS

Vehicle: 2015 Kia Sorento

27

-33-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE Date Complaint Filed: 06/23/2017 Date of Incident: 12/01/2014 Component(s): ENGINE

NHTSA ID Number: 11000887

## **SUMMARY:**

(AMENDMENTS TO ODI#S: 10668775 & 10663356 -

**UPDATE**)

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

ON 12/01/2014, I WAS IN A 2015 KIA SORENTO LX (ENTERPRISE INSURANCE RENTAL) TRAVELING ON CRABB RIVER ROAD, (A CITY STREET) SUGARLAND, TEXAS. I FULLY STOPPED AT THE TRAFFIC LIGHTS BECAUSE IT WAS RED. ONCE LIGHTS TURNED GREEN. I PUT THE VEHICLE IN MOTION BY STEPPING ON THE GAS PEDAL TO ACCELERATE BUT THE CAR FELT REALLY SLUGGISH SO I GAVE IT MORE GAS IN ORDER TO GAIN ENOUGH SPEED AS I WAS ABOUT TO GO OVER SOME RAILROAD TRACKS (APPROX. 55+ MPH) WHICH WERE ON A ROAD THAT WAS ON AN INCLINE. RIGHT AS THE CAR REACHED THE TRACKS. THE ENGINE STALLED. THE STEERING WHEEL LOCKED AND I LOST ALL CONTROL OF THE VEHICLE AND IT DOVE INTO A DITCH; PLOWED DIRECTLY INTO A STEEL BILLBOARD POLE WHICH WAS CEMENTED INTO THE GROUND BECAUSE THE BRAKES BECAME UNRESPONSIVE. THERE WERE NO WARNING LIGHTS ON THE DASH PRIOR TO THE CRASH. EVEN THOUGH I WAS FULLY BUCKLED, THE SEATBELT DID NOT PREVENT MY HEAD FROM VIOLENTLY HITTING THE WINDSHIELD AND BOUNCING OFF THE STEERING WHEEL SINCE NONE OF THE 8 AIRBAGS DEPLOYED, I SUFFERED NEAR FATAL INJURIES INCLUDING A BROKEN BACK (L2 FRACTURE), SPINAL CORD, HEAD, EYE, CHIN, JAWS. NECK AND HIP; BROKEN TEETH, PERMANENT DISFIGURATION (18 STITCHES), SOME VISION & HEARING LOSS FROM NERVE DAMAGE AND PTSD, MENTAL ANGUISH, CHRONIC MIGRAINES, EXTREME

STRESS, TERRIBLE RECURRING NIGHTMARES, ETC. 1 I'M A 5'2" WOMAN AND MY CHEST WAS PINNED TO 2 THE STEERING WHEEL UPON THE IMPACT WITH THE 3 POLE AND THE FIRE DEPT. HAD TO FREE ME AND LIFT ME UP TO THE EMTS. I WAS TRANSPORTED TO 4 THE ER OF A HOSPITAL BY AMBULANCE AND LATER 5 TRANSFERRED TO THE TRAUMA UNIT OF MEMORIAL HERMANN HOSPITAL DUE TO THE SEVERITY OF MY 6 INJURIES. 7 8 Vehicle: 2016 Kia Sorento 9 Date Complaint Filed: 10/12/2017 10 Date of Incident: 10/09/2017 11 Component(s): ENGINE NHTSA ID Number: 11033167 12 13 **SUMMARY:** VEHICLE STALLED WHILE DRIVING WITH SPEED ON 14 NORMANDIE AVE IN TORRANCE CALL TRIPLE FOR 15 THEM TO TOW IT TO KIA DEALER. RECEIVED A CALLED FROM DEALER SAYING THE ENGINE BLOWN 16 OUT. AT 50000 MILES. TECHNICIAN FROM KIA 17 MENTIONED IT'S A RECALL. 18 19 Vehicle: 2015 Kia Sportage 20 Date Complaint Filed: 09/13/2017 Date of Incident: 08/23/2017 21 Component(s): ENGINE 22 NHTSA ID Number: 11022956 23 **SUMMARY:** 24 I WAS DRIVING ON THE FREEWAY AT 65 MPH IN THE 25 SLOW LANE WHEN THE CHECK ENGINE LIGHT 26 SUDDENLY CAME ON, THEN ALL THE SERVICE LIGHTS LIT UP AND THE CAR BEGAN LOSING POWER. 27 LUCKILY, I WAS COMING TO AN OFFRAMP AND WAS 28 ABLE TO MAKE IT TO THE END OF THE OFFRAMP -35-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

(SIGNAL) BEFORE THE CAR DIED COMPLETELY. WE 1 HAD TO PUSH THE CAR OUT OF THE ROAD AND 2 AROUND THE CORNER TO A CURB AS WE WERE 3 BLOCKING ONE SIDE OF THE OFFRAMP. HAD I NOT BEEN IN THE SLOW LANE AND NEAR AN OFFRAMP. 4 THE CAR WOULD HAVE DIED ON THE FREEWAY 5 WHICH WOULD HAVE BEEN A MUCH MORE DANGEROUS SITUATION. WAS TOLD BY KIA SERVICE 6 DEPT. THAT THE ENGINE BLEW BECAUSE OF SLUDGE 7 IN THE OIL. 8 9 Previous Model Year Kia GDI Engine Complaints **b**. 10 Vehicle: 2011 Kia Optima Date Complaint Filed: 10/16/2014 11 Component(s): ENGINE 12 Date of Incident: 10/12/2014 13 NHTSA ID Number: 10645013 14 **SUMMARY:** 15 TL\* THE CONTACT OWNS A 2011 KIA OPTIMA. THE CONTACT STATED THAT WHILE DRIVING 75 MPH AT 16 NIGHT WITH THE CRUISE CONTROL ACTIVATED, 17 THERE WAS SMOKE COMING FROM UNDER THE 18 HOOD AND THE VEHICLE ENGULFED INTO FLAMES. THE FIRE DEPARTMENT EXTINGUISHED 19 THE FIRE. A POLICE/FIRE REPORT WAS FILED AND 20 THERE WERE NO INJURIES REPORTED. THE VEHICLE WAS DESTROYED AND THE CAUSE OF THE FIRE WAS 21 NOT DETERMINED. THE MANUFACTURER WAS NOT 22 MADE AWARE OF THE FAILURE. THE FAILURE 23 MILEAGE WAS 51,500. 24 25 Vehicle: 2011 Kia Optima Date Complaint Filed: 04/16/2015 26 Date of Incident: 03/31/2015 27 Component(s): ELECTRICAL SYSTEM, ENGINE 28 NHTSA ID Number: 10706020

-36-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

18

19

20

21

22

23

24

25

26

27

28

## **SUMMARY:**

TL\* THE CONTACT OWNS A 2011 KIA OPTIMA. WHILE TRAVELING AT APPROXIMATELY 50 MPH AND ATTEMPTING TO SLOW DOWN FOR A STOP LIGHT. THE VEHICLE STALLED WITHOUT WARNING AND FAILED TO RESTART. THE VEHICLE WAS TOWED TO AN AUTHORIZED DEALER WHO DIAGNOSED THAT THE STARTER BURNED OUT AND THAT THE ENGINE SEIZED. THE DEALER REPLACED THE STARTER AND WAS NOT ABLE TO DIAGNOSE THE SOURCE OF THE FAILURE. THE CONTACT WAS INFORMED THAT A MORE EXTENSIVE DIAGNOSIS WAS REQUIRED AND THE ENGINE NEEDED TO BE TAKEN APART. THE ENGINE FAILURE WAS NOT REPAIRED BY THE DEALER. THE VEHICLE WAS NOT ABLE TO BE DRIVEN. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS NOT AVAILABLE.

Vehicle: 2011 Kia Optima

Date Complaint Filed: 05/29/2015

Date of Incident: 05/27/2015

Component(s): ENGINE, SERVICE BRAKES

NHTSA ID Number: 10722186

#### **SUMMARY:**

I HAVE A 2011 KIA OPTIMA LX, 2.4 LITER ENGINE. ALWAYS KEEP UP ON THE MAINTENANCE AND OIL CHANGES, CAR IS IN GREAT SHAPE. I WAS NOT EXPERIENCING ANY ISSUES, WARNINGS, NO CHECK ENGINE/OIL LIGHTS, NO NOISES, ABSOLUTELY NOTHING. THEN LAST NIGHT MY CAR JUST SPUTTERED AND CUT OFF WHILE BEING DRIVEN. APPARENTLY WHEN THE ENGINE CUTS OFF, SO DOES THE BRAKES. THERE WAS NO WAY TO PUSH THE BRAKES, SO I HAD TO TRY TO SAFELY COAST TO THE SIDE OF THE ROAD, WITH NO BRAKES AND

-37-

**NO POWER STEERING.** I FINALLY PULLED OVER, 1 TRIED TO RESTART THE CAR AND THERE WAS SUCH 2 A LOUD KNOCKING NOISE, AND SOME SOUEALING 3 NOISES AS WELL. THE CAR WILL NO LONGER START EITHER. I HAD A MECHANIC LOOK AT IT TODAY AND 4 SAYS THE ENGINE IS "JUST GONE." NO 5 EXPLANATIONS AT ALL. I VERIFIED THAT THE KIA OPTIMA AND THE HYUNDAI SONATA ARE THE SAME 6 MANUFACTURER AND USE THE SAME ENGINES. I SEE 7 THERE ARE WAY MORE COMPLAINTS ABOUT THE 8 2011 HYUNDAI SONATA WITH THIS SAME ISSUE. I WILL TRY TO NOTIFY KIA AND SEE IF THEY ARE 9 WILLING TO STEP UP AND CORRECT THIS EVEN WITH 10 THE WARRANTY EXPIRING 7,000 MILES AGO, SINCE I AM THE SECOND OWNER. I HAVE FOUND MANY 11 COMPLAINTS ABOUT THIS SAME THING FOR BOTH 12 THE 2011 OPTIMAS AND SONATAS. THIS IS SO 13 DANGEROUS BECAUSE THERE ARE NO WARNINGS. AND THE ENGINE CUTS OFF IN TRAFFIC, WHICH ALSO 14 CAUSES THE BRAKES AND STEERING TO GO OUT. 15 NOT SAFE AT ALL. 16 17 Vehicle: 2011 Kia Optima 18 Date Complaint Filed: 08/24/2015 Date of Incident: 08/24/2013 19 Component(s): ENGINE 20 NHTSA ID Number: 10778079 21 **SUMMARY:** 22 DRIVING DOWN EXPRESS WHEN ENGINE STARTED TO 23 LOOSE OIL. PULLED OVER ON SHOULDER, NOTICE A CLICKING NOISE AND SMELLED BURNING OIL. 24 DEALER FOUND HOLE IN SIDE OF ENGINE BLOCK. 25 STATED NEEDS NEW ENGINE AND QUOTED AND ESTIMATED PRICE OF \$5,875.64 FOR A USED ENGINE 26 WITH 46,000 MILES INSTALLED. HAD CAR REPAIRED 27 AT ANOTHER PLACE FOR \$5477.06 WITH 41,000 MILES. 28 THIS SHOP SAID THE ENGINE HAD A ROD KNOCK

-38-

THEN LOCKED UP. NEEDS THE ENGINE REPLACED. 1 THIS IS THE SAME 2.4 LITER ENGINE THAT IS 2 BEING RECALLED FOR THE HYUNDAI SONATAS. 3 4 Vehicle: 2011 Kia Optima 5 Date Complaint Filed: 09/29/2015 6 Date of Incident: 06/21/2015 Component(s): ENGINE 7 NHTSA ID Number: 10778375 8 **SUMMARY:** 9 TL\* THE CONTACT OWNS A 2011 KIA OPTIMA. WHILE 10 DRIVING AT APPROXIMATELY 40 MPH, THE CHECK 11 ENGINE WARNING LIGHT ILLUMINATED. THE DRIVER SHUT OFF THE VEHICLE AND IT FAILED 12 TO RESTART. THE VEHICLE WAS TOWED TO A 13 DEALER WHO DIAGNOSED THAT THE ENGINE NEEDED TO BE REPLACED. THE MANUFACTURER 14 WAS NOTIFIED OF THE FAILURE. THE VEHICLE WAS 15 NOT REPAIRED. THE FAILURE MILEAGE WAS 71,106. 16 17 Vehicle: 2011 Kia Optima 18 Date Complaint Filed: 11/09/2015 Date of Incident: 10/31/2015 19 Component(s): ELECTRICAL SYSTEM, ENGINE 20 NHTSA ID Number: 10789435 21 **SUMMARY:** 22 WHILE DRIVING 70 MPH ON THE HIGHWAY MY 23 2011 KIA OPTIMA ENGINE SHUT DOWN AND WOULD NOT ACCELERATE AND THE BRAKES WOULD NOT 24 FUNCTION. LUCKILY, I SAFELY MADE IT TO THE FAR 25 SHOULDER OF THE HIGHWAY ONLY TO FIND THAT 26 MY CAR WAS SMOKING AND SMELLED LIKE SOMETHING WAS BURNING. HAD TO GET THE CAR 27 TOWED TO THE DEALERSHIP AND THEY INFORMED 28 THE ENGINE NEEDS TO BE REPLACED AND THE -39-

STARTER IS ALSO FRIED. I HAVE SEEN FOUR COMPLAINTS SO FAR OF 2011 KIA OPTIMA'S WITH THE SAME ISSUE AND AM SURE I WILL FIND MORE. THAT SEEMS LIKE TOO MUCH OF A COINCIDENCE THAT IT HAPPENS SO FREQUENTLY WITH THESE MODELS AND THERE ISN'T ANY SORT OF RECALL. NO BREAKS AT 70 MPH IS PRETTY DANGEROUS. I HAVE CONTACTED MY ATTORNEY AND HOPE THIS MANUFACTURER WILL DO THE RIGHT THING.

8

9

10

11

12

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

1

2

3

4

5

6

7

Vehicle: 2011 Kia Optima

Date Complaint Filed: 12/13/2015 Date of Incident: 12/06/2015

Component(s): ENGINE

NHTSA ID Number: 10809924

# 13 SUMMARY:

WAS DRIVING DOWN THE INTERSTATE AND THE CAR DIED AFTER PULLING OFF TO THE SHOULDER TRIED TO START THE CAR AND ALL IT WOULD DO WAS CLICK. TOWED THE CAR HOME THINKING IT WAS AN ALTERNATOR OR SOMETHING SIMPLE. NEXT MORNING LOOKED AT THEN CHANGED THE BATTERY AND TRIED TO GET IT STARTED IN SLIGHTLY TURNED OVER BUT NOT ENOUGH TO START CALLED THE DEALER TO DROP IT OFF AND THEY SAID CAR WAS SEIZED OUT OF WARRANTY AND NEEDS THE ENGINE REPLACED. AFTER SEARCHING ON THE INTERNET AND LOOKING AT COMPLAINTS FOUND THAT MY ENGINE WAS BUILT AT THE SAME PLANT AS THE HYUNDAI SONATA SAME ENGINE, WHICH IS RECALLED FOR THIS SAME EXACT PROBLEM . I AM WONDERING WHY KIA ACTED LIKE THE CANT BELIEVE THIS WOULD HAPPEN WHEN THESE CARS SHOULD BE **RECALLED** ALSO. WHAT CAN BE DONE HERE? I WILL NOT LET THIS GO IT IS WRONG KIA'S SHOULD BE LOOKED INTO AND RECALLED

-40-

1 2 Vehicle: 2011 Kia Optima 3 Date Complaint Filed: 02/29/2016 Date of Incident: 05/09/2015 4 Component(s): ENGINE 5 NHTSA ID Number: 10838965 6 **SUMMARY:** 7 TL-THE CONTACT OWNS A 2011 KIA OPTIMA. THE 8 CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 60 MPH, AN ABNORMAL SOUND 9 EMITTED FROM UNDER THE HOOD OF THE 10 VEHICLE AS THE CHECK ENGINE OIL WARNING 11 **LIGHT FLICKERED.** THE VEHICLE WAS TAKEN TO AN INDEPENDENT MECHANIC WHERE IT WAS 12 DIAGNOSED THAT THE CONNECTING ROD FAILED 13 AND THE ENGINE NEEDED TO BE REPLACED. THE VEHICLE WAS NOT REPAIRED. THE MANUFACTURER 14 WAS NOT NOTIFIED OF THE FAILURE. THE FAILURE 15 MILEAGE WAS 92,000. SS 16 17 Vehicle: 2012 Kia Optima 18 Date Complaint Filed: 09/23/2014 Date of Incident: 09/22/2014 19 Component(s): ENGINE 20 NHTSA ID Number: 10638362 21 **SUMMARY:** 22 DRIVING VEHICLE AT 35-40 MPH. ALL OF A SUDDEN 23 ENGINE STOPPED. THERE WAS HEAVY SMOKE COMING FROM UNDER THE HOOD AND SMELLED OF 24 AN ELECTRICAL FIRE. SMOKE DISSIPATED AFTER 15 25 MINUTES. VEHICLE WAS UNABLE TO BE RESTARTED 26 AND HAD TO BE TOWED TO KIA DEALERSHIP IN TURNERSVILLE NJ. SPOKE WITH DEALERSHIP ON 9/23 27 AND WAS TOLD STARTER AND ENGINE NEEDS TO BE 28 REPLACED. \*TR -41-

1 2 Vehicle: 2012 Kia Optima 3 Date Complaint Filed: 09/26/2014 Date of Incident: 09/11/2014 4 Component(s): ENGINE 5 NHTSA ID Number: 10639417 6 **SUMMARY:** 7 TL\* THE CONTACT OWNS A 2012 KIA OPTIMA. THE 8 CONTACT STATED THAT WHILE DRIVING AT APPROXIMATELY 70 MPH, THE ENGINE STALLED 9 WITHOUT WARNING. IN ADDITION, A STRONG 10 ELECTRICAL BURNING ODOR EMITTED INSIDE OF 11 THE VEHICLE. THE VEHICLE WAS TOWED TO A DEALER FOR DIAGNOSIS. THE MECHANIC INFORMED 12 THAT THE STARTER AND ASSOCIATED FUSES WERE 13 COMPLETELY BURNT. THE VEHICLE WAS REPAIRED. THE CONTACT STATED THAT AFTER THE REPAIRS 14 WERE PERFORMED, THE VEHICLE FAILED TO START. 15 THE VEHICLE WAS TAKEN BACK TO THE DEALER WHO RECOMMENDED THE ENGINE NEEDED TO BE 16 REPLACED. THE VEHICLE WAS NOT REPAIRED. THE 17 MANUFACTURER WAS NOTIFIED OF THE FAILURE. 18 THE VIN WAS UNAVAILABLE. THE APPROXIMATE FAILURE MILEAGE WAS 55,000. 19 20 21 Vehicle: 2012 Kia Optima 22 Date Complaint Filed: 09/30/2015 23 Date of Incident: 08/02/2015 Component(s): ENGINE 24 NHTSA ID Number: 10778891 25 26 **SUMMARY:** I WAS DRIVING ON I 95 ON OUR WAY HOME FROM 27 FLORIDA. WE WERE PASSING FAYETTSVILLE, NC 28 WHEN MY CAR ENGINE MADE SOME KNOCKING -42-Consolidated Class Action Complaint

1 2 3 4 5 6	NOISE AND THEN THE ENGINE LIGHT CAME ON, BEFORE I CAN PULL TO THE SHOULDER, THE CAR STALLED, LOST POWER AT 70 MLS PER HR. WE WERE LUCKY NO ONE HIT US AS I WAS SLOWLY NAVIGATING TO THE SHOULDER. I HAD IT TOWED TO A KIA DEALERSHIP IN FAYETTS VILLE, NC. THEY SAID ENGINE SEIZED UP AND NEEDS TO BE REPLACE. THE CAR HAS 71,000MLS BUT KIA DENIED MY WARRANTY CLAIM SO I END UP PAYING \$5,700 FOR A
8	REMANUFACTURED ENGINE.
9 10 11 12 13	Vehicle: 2012 Kia Optima Date Complaint Filed: 12/14/2015 Date of Incident: 11/28/2015 Component(s): ENGINE NHTSA ID Number: 10809989
14 15 16	SUMMARY: THE VEHICLE HIT 63,000 MILES DURING THIS INCIDENT. AS I WAS MERGING ONTO THE EXPRESSWAY AT 50MPH, I GOT THE VEHICLE TO
17 18	60MPH AND THE SPEEDOMETER GAUGE FROZE AT 60MPH. THEN, THE RPM GAUGE DROPPED TO 0.
19	SUDDENLY THE ENGINE LOST POWER, THE BRAKES LOCKED UP AND BEFORE I GOT THE CAR
20	OFF TO THE SHOULDER AT A COMPLETE STOP, THE ENGINE CUT OUT COMPLETELY. THE ENGINE
21	WOULD NOT START AT ALL AFTER IT CUT OUT. I THEN BROUGHT THE VEHICLE TO A DEALERSHIP
22	WHERE THEY DEEMED A NEW ENGINE AS THE
23	CURRENT ENGINE BLEW.
24	
25	Vehicle: 2012 Kia Optima
26	Date Complaint Filed: 01/21/2016 Date of Incident: 01/13/2016
27	Component(s): ENGINE
28	NHTSA ID Number: 10821364
	Consolidated Class Action Complaint

28

## **SUMMARY:**

DRIVING AT APPROXIMATELY 50 MPH ON THE PARKWAY, ENGINE STALLED WITHOUT WARNING AND WOULD NOT RE-START. I HAD THE CAR TOWED TO A SHOP WHERE THEY INFORMED ME THE ENGINE HAD SEIZED. THERE WAS DEFINITELY OIL IN THERE AS I HAD AN OIL CHANGE WITHIN THE LAST COUPLE OF WEEKS,. THE CAR HAS 72K MILES ON IT AND I AM THE SECOND OWNER SO NOT COVERED BY KIA'S NON-TRANSFERABLE 10YR/100K MI WARRANTY. WORKING WITH KIA CUSTOMER SERVICE, WAITING TO HEAR BACK FROM A SUPERVISOR.

Vehicle: 2013 Kia Optima

Date Complaint Filed: 06/14/2013

Date of Incident: 06/12/2013 Component(s): ENGINE

NHTSA ID Number: 10519827

## **SUMMARY:**

DRIVING ON A CITY ROAD DURING NORMAL TRAFFIC (4:30PM EST) MY VEHICLE BEGAN TO MAKE LARGE RATTLING NOISE FROM THE ENGINE COMPARTMENT. AT FIRST I THOUGHT I HAD PICKED UP SOMTHING ON THE ROAD, BUT AS I ACCELERATED/DECCELERATED THE NOISE BECAME LOUDER/SOFTER. I IMMEDIATLEY CONTACTED MY KIA DEALERSHIP. AFTER SPEAKING TO THE SERVICE MANAGER HE TOLD ME TO BRING THE VEHICLE IN NEXT WEEK SINCE THAT WOULD BE THE SOONEST IT COULD BE LOOKED AT. I INFORMED HIM THAT I DID'NT THINK I COULD EVEN MAKE IT HOME LET ALONE WAIT A WEEK TO BRING THE VEHICLE IN. HE STATED I COULD DROP IT OFF, BUT IT WOULD NOT BE LOOKED AT UNTIL NEXT WEEK. EITHER WAY, WITHIN 10 MIUTES OF DRIVING A LARGE BANGING NOISE WENT OFF UNDER THE HOOD, ENGINE OIL SPRAYED

-44-

1 2 3 4 5 6 7 8 9	THROUGHT THE ENGINE COMPARTMENT AND I HAD COMPLETE LOSS OF POWER. KIA ROADSIDE ASSISTANCE TOWED THE VEHICLE TO THE DEALERSHIP WHERE THEY HAVE INFORMED ME THAT THE ENGINE NEEDS TO BE REPLACED. THE VEHICLE IS LESS THAN 2 WEEKS OLD AND HAD 600 MILES WHEN THIS OCCURED. I INFORMED THE DEALERSHIP I WOULD NOT WANT A VEHICLE WITH A REPLACED ENGINE AND THEY HAVE INFORMED ME THAT IS MY ONLY OPTION. I WILL NOT BE PURCHASING FROM KIA AGAIN AS THERE WAS NO SUPPORT FROM THEIR CORPORATE CUSTOMER SERVICE EITHER. *TR
11	
12	Vehicle: 2013 Kia Optima Date Complaint Filed: 08/17/2015
13	Date of Incident: 08/12/2015
14	Component(s): ENGINE
15	NHTSA ID Number: 10749310
16	SUMMARY:
	THE EVENING OF 8/12/15 I WAS DRIVING DOWN A 4
17	LANE CITY ROAD, 2 LANES EACH DIRECTION. THE
18	ENGINE COMPLETELY SHUT OFF LEAVING ME
19	WITH NO POWER AND IN A VERY DANGEROUS
20	SITUATION WITH SUDDEN DECELERATION AND VEHICLES COMING UP FROM BEHIND.
21	FORTUNATELY, NO ONE HIT ME AND I WAS ABLE TO
22	MOVE THE CAR OUT OF TRAFFIC. NO ENGINE
	MAINTENANCE/WARNING LIGHTS CAME ON PRIOR
23	TO THE ENGINE FAILURE. WE HAVE BEEN INFORMED THE ENGINE IS LOCKED UP AND WILL NEED
24	COMPLETELY REPLACE WITH A NEW ENGINE.
25	ROUTINE MAINTENANCE, INCLUDING KIA'S 22,500
26	MILE RECOMMENDED MAINTENANCE WAS
27	PERFORMED ONLY 16 DAYS PRIOR ON 7/27/15. DAVE
28	GREEN, KIA ARAPAHOE SERVICE MANAGER, INFORMED TODAY (8/17/15) THAT THEY HAVE SEEN
20	
	-45-

SEVERAL INSTANCES OF THIS IN THE PAST WEEK. 1 THEY BELIEVE THERE IS A CONNECTION TO THE HOT 2 WEATHER. WHAT EVER THE CAUSE THIS HAS A VERY 3 HIGH POTENTIAL TO CAUSE DEATH OR EXTREME **INJURY** 4 5 Vehicle: 2011 Kia Sorento 6 Date Complaint Filed: 10/11/2011 7 Date of Incident: 07/18/2011 Component(s): ENGINE AND ENGINE COOLING 8 NHTSA ID Number: 10429442 9 10 **SUMMARY:** WHILE DRIVING DOWN THE EXPRESSWAY, WITHOUT 11 WARNING, THERE WAS A CATASTROPHIC ENGINE 12 FAILURE CAUSING ONE OR TWO OF THE CONNECTING RODS TO BLOW THROUGH THE OIL PAN 13 AND START A FIRE FROM THE FRONT OF THE 14 VEHICLE TO THE BACK UNDERNEATH THE 15 CARRIAGE. THE FLAMES CAME UP THE SIDES AND BACK OF THE CAR. NEEDLESS TO SAY IT WAS 16 EXTREMELY FRIGHTENING. LOOKING AT THE 17 DAMAGE OF THE CAR I NEVER EXPECTED THEM TO ATTEMPT TO REPAIR THIS CAR YET THEY DID. THE 18 CAR WAS DOWN FOR ALMOST TWO MONTHS, THE 19 SECOND ENGINE AND POWER STEERING FAILED 20 BEFORE WE EVEN DROVE THE REPAIRED CAR OFF THE LOT. KIA STILL DID NOT WANT TO DO 21 ANYTHING BUT REPAIR THE CAR AGAIN. THEY SAID, 22 "THESE THINGS HAPPEN THATS WHY YOU HAVE A WARRANTY". THESE THINGS HAVE NEVER 23 HAPPENED TO ME OR ANYONE I KNOW IN THE 30 24 YEARS I HAVE BEEN DRIVING. YOU BUY A NEW CAR TO AVOID SUCH PROBLEMS. THE CAR HAS NOW 25 BEEN RETURNED TO ME AND IT IS STILL NOT RIGHT. I 26 JUST TOOK IT IN FOR THEM TO BLOW OUT THE 27 VENTS AND FILTERS. THERE WAS STILL REMNANTS OF THE FIRE EXTINGUISHER COMING OUT WHEN 28

-46-

YOU TURNED ON THE AIR. THIS CAR IS DEFECTIVE

#### AND SHOULD HAVE A SALVAGED TITLE. I WAS 1 FORCED TO PUT IN A LAW SUIT. \*KB 2 3 Vehicle: 2011 Kia Sorento 4 Date Complaint Filed: 08/02/2017 5 Date of Incident: 03/16/2016 6 Component(s): ENGINE NHTSA ID Number: 11012248 7 8 **SUMMARY:** BEGINNING MARCH OF 2016, LOUD BANGING AND 9 CLANKING WHEN STARTING ENGINE. I TOOK IT TO 10 DEALERSHIP WHERE THEY DIAGNOSED IT WITH 11 BEARING PROBLEM WHICH COULD POTENTIALLY CAUSE ENGINE FAILURE. VEHICLE OUT OF 12 WARRANTY SO NO COVERAGE FOR AN ESTIMATED 13 6,000.00 REPAIR. WHEN MENTION OF RECALL CAME OUT I WAS RELIEVED AS I AM STILL DRIVING THE 14 VEHICLE. HOWEVER, IT SEEMS THAT THE RECALL 15 ONLY COVERS 2012 OR NEWER MODELS. THE 2011'S HAVE MAJOR ENGINE ISSUES AS WELL AND NEED TO 16 BE INCLUDED IN THE RECALL 17 18 Vehicle: 2011 Kia Sorento 19 Date Complaint Filed: 05/15/2017 20 Date of Incident: 05/07/2017 Component(s): ENGINE 21 NHTSA ID Number: 10985666 22 **SUMMARY:** 23 TL\* THE CONTACT OWNS A 2011 KIA SORENTO. THE 24 CONTACT STATED THAT A METAL BANGING NOISE 25 WAS HEARD UNDERNEATH THE HOOD OF THE VEHICLE. THE CONTACT TOOK THE VEHICLE TO THE 26 DEALER WHERE IT WAS DIAGNOSED THAT THE 27 MOTOR FAILED AND NEEDED TO BE REPLACED. THE 28 VEHICLE HAD NOT BEEN REPAIRED. THE -47-

MANUFACTURER OPENED CASE NUMBER: K3454763. 1 THE APPROXIMATE FAILURE MILEAGE WAS 63,000. 2 3 Vehicle: 2011 Kia Sorento 4 Date Complaint Filed: 04/20/2017 5 Date of Incident: 03/27/2017 Component(s): ENGINE 6 NHTSA ID Number: 10979469 7 **SUMMARY:** 8 TL\* THE CONTACT OWNS A 2011 KIA SORENTO. 9 WHILE DRIVING 55 MPH, THE ENGINE STALLED AND 10 THE WARNING INDICATOR ILLUMINATED. THE CONTACT PULLED THE VEHICLE OVER TO THE SIDE 11 OF THE ROAD. THE VEHICLE FAILED TO RESTART. 12 THE VEHICLE WAS TOWED TO THE DEALER WHERE IT WAS DIAGNOSED THAT THE ENGINE NEEDED TO 13 BE REPLACED. THE VEHICLE WAS NOT REPAIRED. 14 THE MANUFACTURER WAS MADE AWARE OF THE 15 FAILURE. THE FAILURE MILEAGE WAS 96,000. 16 17 Vehicle: 2011 Kia Sorento Date Complaint Filed: 04/12/2017 18 Date of Incident: 04/07/2017 19 Component(s): ENGINE NHTSA ID Number: 10972008 20 21 **SUMMARY:** 22 THE ENGINE BEGAN TO BE HARD TO START LEAVING WORK FOR HOME. THEN THE NEXT MORNING IT WAS 23 HARD TO START AND WOULD ALMOST STALL AT 24 IDLE. AFTER PARKING AT WORK I ATTEMPTED TO START IT AND DRIVE TO THE KIA DEALERSHIP FOR 25 DIAGNOSIS, IT WOULD NOT KEEP RUNNING MORE 26 THAN A FEW SECONDS. 27 THE ENGINE HAS SUFFERED A CATASTROPHIC 28 FAILURE. THE DEALER SAYS THAT IT IS LIKELY THAT -48-

THE CRANK SHAFT BEARINGS FAILED, OR POSSIBLY 1 THE CONNECTING ROD BEARINGS. THE ENGINE 2 NEEDS TO BE REPLACED. 3 4 Vehicle: 2011 Kia Sorento 5 Date Complaint Filed: 04/10/2017 Date of Incident: 02/10/2017 6 Component(s): ENGINE 7 NHTSA ID Number: 10971641 8 **SUMMARY:** 9 TL\* THE CONTACT OWNS A 2011 KIA SORENTO. THE 10 CONTACT NOTICED SMOKE COMING FROM THE VEHICLE AND DISCOVERED THAT IT WAS LOW ON 11 OIL. THE VEHICLE WAS TAKEN TO THE DEALER 12 WHERE IT WAS DIAGNOSED THAT THE BEARING WAS FAULTY AND CAUSED AN OIL LEAK. THERE WAS 13 SLUDGE IN THE MOTOR, WHICH NEEDED TO BE 14 REPLACED. THE VEHICLE WAS NOT REPAIRED. THE 15 CONTACT REFERENCED NHTSA CAMPIAGN NUMBER: 17V224000 (ENGINE AND ENGINE COOLING) AS A 16 POSSIBLE SOLUTION TO THE FAILURE; HOWEVER, 17 THE VIN WAS NOT INCLUDED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE 18 MILEAGE WAS 55,000. 19 20 Vehicle: 2011 Kia Sorento 21 Date Complaint Filed: 03/21/2017 22 Date of Incident: 02/27/2017 Component(s): ENGINE 23 NHTSA ID Number: 10967659 24 25 **SUMMARY:** ON FEBRUARY 27, 2017, MY 2011 KIA SORENTO'S 26 ENGINE DIED. I HAD ONLY ONE WARNING THAT 27 THERE WAS A PROBLEM AND THAT WAS A LACK OF 28 POWER. I WAS GOING UP A SLIGHT HILL AND I HAD -49-

27

28

TO FLOOR THE GAS PEDAL TO MAINTAIN 20MPH UP IT. I WENT OUT AT 830PM THAT NIGHT TO TAKE IT TO MY MECHANIC AND MY SORENTO WOULD NOT START. I HAD IT TOWED TO GORRING AUTOMOTIVE AT 1030PM. ON MARCH 1, 2017, MR. GORRING CALLED AND TOLD ME I WOULD NEED A NEW ENGINE. I CONTACTED CENTURY 3 KIA AND SPOKE TO THE SERVICE MANAGER DAN. HE STATED THAT I NEEDED TO BRING IT BACK TO THE DEALERSHIP TO HAVE IT LOOKED AT. I ALSO CONTACTED KIA CONSUMER NUMBER AND SPOKE TO ERIC. ERIC TOLD ME THE SAME INFORMATION AND I STATED I DID NOT WANT TO PAY FOR THE DIAGNOSIS AGAIN. I HAD MY SORENTO TOWED TO CENTURY 3 KIA ON MARCH 1. 2017. DAN STATED THAT HE WAS SURPRISED THAT MY VIN WAS NOT ON THE EXTENDED WARRANTY LIST. ON MARCH 3, 2017, DAN FROM CENTURY 3 KIA CALLED ME AND SAID THAT I DID NEED A NEW ENGINE. CHARLES FROM KIA'S CONSUMER NUMBER AND DAN FROM CENTURY 3 KIA BOTH STATED THAT IF I WAS THE ORIGINAL OWNER THEY WOULD REPLACE THE ENGINE AT NO COST TO ME BUT SINCE I AM THE SECOND OWNER OF THE SORENTO, IT WOULD BE MY RESPONSIBILITY. I INQUIRED AT THE COST OF LABOR AND WAS TOLD 15 HOURS AT \$108 AN HOUR. I HAVE LOOKED AROUND AND FOUND THAT MOST ENGINES WITH ROUGHLY THE SAME MILEAGE AS MINE ARE AROUND \$2,500. THE TOTAL COST WILL ROUGHLY BE BETWEEN \$4,500 AND \$6,500 TOTAL WITH ALL THE FLUIDS AND OTHER PARTS NEEDED TO RETURN MY SORENTO TO A FUNCTIONAL STATE. I PURCHASED THE SORENTO WITH 53,857 MILES ON IT AND HAD IT FOR ONE YEAR. I PUT 12,000 MILE ON IT ROUGHLY. MY SORENTO HAD ROUGHLY 65,500 MILES ON IT WHEN THIS HAPPENED. I HAVE DONE SOME RESEARCH AND FOUND THIS TO BE A COMMON PROBLEM WITH THE 2.4L ENGINES. IF THIS IS TRUE, WHY HAS KIA NOT DONE ANYTHING ABOUT IT.

1 2 Vehicle: 2011 Kia Sorento 3 Date Complaint Filed: 01/02/2017 Date of Incident: 12/07/2016 4 Component(s): ENGINE 5 NHTSA ID Number: 10939102 6 **SUMMARY:** 7 THE CAR WAS NOT ALWAYS RESPONDING TO ME 8 WHEN I WANTED TO ACCELERATE, I WOULD HEAR THE RPMS GOING UP BUT THE CAR WOULD NOT GO 9 FASTER, THEN A PUFF OF WHITE SMOKE WOULD 10 COME OUT THE TAIL PIPE. THEN ONE DAY, I WAS 11 DRIVING THE CAR AND IT STARTED MAKING A CLANKING NOISE WHEN I WOULD PUSH THE GAS 12 PEDAL. IT SOUNDED LIKE THE NOISE A ROLLER 13 COASTER MAKES WHEN YOU ARE CLANKING UP THE HILL AT THE BEGINNING. TOOK THE CAR TO THE 14 DEALERSHIP AND THEY TOOK THE ENGINE APART 15 TO FIND THE PROBLEM. THE CAR HAS AN ENGINE DEFECT THAT WAS DIAGNOSED BY A KIA DEALER AS 16 A MANUFACTURERS DEFECT. NOW THE CAR IS NOT 17 DRIVABLE AND KIA IS REFUSING TO PAY FOR A NEW 18 ENGINE. KIA NEEDS TO RECALL ALL VEHICLES WITH THESE ENGINES. THEY ARE BUILT BY HYUNDAI AND 19 THEY RECALLED THEIR VEHICLES WITH THE SAME 20 ENGINES. \*TR 21 22 Vehicle: 2011 Kia Sorento 23 Date Complaint Filed: 07/21/2016 Date of Incident: 07/18/2016 24 Component(s): ENGINE 25 NHTSA ID Number: 10887421 26 **SUMMARY:** 27 ENGINE WAS MAKING A CYCLICAL 28 CLICKING/KNOCKING NOISE. WE TOOK THE VEHICLE -51-Consolidated Class Action Complaint

TO KIA DEALERSHIP AND THEY SAID THEY COULD 1 NOT FIND ANY ISSUES WITH THE CAR. ABOUT A 2 WEEK LATER THE CAR BROKE DOWN WHILE 3 DRIVING AT HIGHWAY SPEEDS. AFTER HAVING IT TOWED TO AN INDEPENDENT GARAGE, WE WERE 4 INFORMED THE ENGINE HAD A CONNECTING ROD 5 FAILURE. THIS IS THE EXACT SAME PROBLEM THE HYUNDAI SONATA HAS WITH THE EXACT SAME 6 THETA 2.4 LITER ENGINE. HYUNDAI HAS ISSUES A 7 RECALL BUT KIA FAILS TO ACKNOWLEDGE THE 8 ISSUE. 9 10 Vehicle: 2011 Kia Sorento Date Complaint Filed: 05/12/2016 11 Date of Incident: 05/02/2016 12 Component(s): ENGINE NHTSA ID Number: 10864508 13 14 **SUMMARY:** 15 AT 68,000 MILES THE OIL PRESSURE SENSOR (PART #94750-37100) FAILED AND CAUSED A SUDDEN AND 16 IMMEDIATE LOSS OF ALL ENGINE OIL. IN THE HALF 17 MILE IT TOOK US TO SAFELY PULL OVER THE OIL PRESSURE LIGHT ACTIVATED AND THE DIP STICK 18 READ BONE DRY. I HAVE RESEARCHED THE ISSUE 19 AND FOUND IT TO BE A COMMON PROBLEM WITH KIA'S, A RECALL SHOULD BE ISSUED TO REPLACE 20 THE PART WITH A BETTER ENGINEERED VERSION. 21 HAD WE NOT BEEN ALERT / AWARE OF WHAT WAS 22 GOING ON THE ENGINE COULD HAVE SEIZED AND ALL POWER COULD HAVE BEEN LOST WHILE IN 23 MOTION. 24 25

Vehicle: 2011 Kia Sorento

Date Complaint Filed: 02/16/2016 Date of Incident: 01/31/2016 Component(s): ENGINE

Consolidated Class Action Complaint Case No. 8:17-cy-00838-JLS-JDE

26

27

28

**NHTSA ID Number: 10836400** 1 2 **SUMMARY:** 3 ON 1-31-16 HEARD A PINGING NOISE ON THE HIGHWAY: THEN THE CAR STALLED AT THE EXIT 4 LIGHT: STARTED IT AGAIN AND LOUD BANG BLOW A 5 ROD AFTER GETTING BACK ON THE HIGHWAY TO DRIVE IT TO A SHOP. DIED ON THE SIDE OF THE 6 HIGHWAY AND HAD TO HAVE IT TOWED TO KIA IN 7 AUBURN WA. KIA STATED THEY WILL NOT FIX 8 UNDER THE WARRANTY BECAUSE THE WRONG OIL FILTER WAS INSTALLED AND I DIDN'T PROVIDE 9 PROPER MAINTENANCE; WHICH I TOOK IT IN EACH 10 AND EVERY TIME FOR OIL CHANGES TO MY AUTO SHOP. SAME OIL FILTER HAS BEEN PUT INTO MY CAR 11 SINCE 2011. WENT BACK TO MY AUTO SHOP 12 INFORMED THEM THEY STARTED THE PROCESS OF 13 SENDING THE OIL FILTER IN TO BE CHECKED FOR DEFECTS. ALSO FOUND ON 3 DIFFERENT WEB SITES 14 THE FILTER CAN BE USED FOR MY MAKE AND 15 MODEL. NOW KIA WANT FIX MY CAR: IT HAS BEEN 3 WEEKS WITHOUT A VEHICLE AND NO WORD FROM 16 KIA; NOT EVEN FROM THEIR HEADOUARTERS. KIA 17 WILL NOT PROVIDE THE WORK ORDER STATING THEY ARE NOT ALLOWED TO GIVE TO THIRD PARTY. 18 19 20 Vehicle: 2011 Kia Sorento Date Complaint Filed: 03/13/2015 21 Date of Incident: 03/02/2015 22 Component(s): ENGINE 23 NHTSA ID Number: 10694186 24 **SUMMARY:** 25 TL\* THE CONTACT OWNS A 2011 KIA SORENTO. WHILE TRAVELING APPROXIMATELY 40 MPH. THERE 26 WAS A LOUD NOISE COMING FROM THE FRONT OF 27 THE VEHICLE. ALSO, THE CONTACT MENTIONED

-53-

THAT SMOKE EMITTED FROM THE ENGINE

28

COMPARTMENT. UPON PULLING THE VEHICLE OVER, IT WAS FURTHER NOTICED THAT THE ENGINE COMPARTMENT WAS ON FIRE. THE VEHICLE WAS TOWED TO AN INDEPENDENT MECHANIC, WHO DIAGNOSED THAT A ROD FRACTURED INTO THE ENGINE AFFECTING THE OTHER COMPONENTS CAUSED A FIRE. ALSO, THE MECHANIC DIAGNOSED THAT THE PISTONS MAY NEED TO BE REPLACED BUT FURTHER EXTENSIVE DIAGNOSIS WAS REQUIRED TO REPAIR THE VEHICLE. THE CONTACT WAS NOT INCLUDED IN NHTSA CAMPAIGN NUMBER: 10V388000 (ELECTRICAL SYSTEM). THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 102,000.

11

12

13

14

15

10

1

2

3

4

5

6

7

8

9

Vehicle: 2012 Kia Sorento

Date Complaint Filed: 10/23/2017

Date of Incident: 02/20/2017 Component(s): ENGINE

NHTSA ID Number: 11035862

16

17

18

19

20

21

22

23

24

25

26

27

28

## **SUMMARY:**

OUR 2012 KIA SORENTO WAS IN MOTION ON THE HIGHWAY WHEN A LOUD KNOCKING SOUND BEGAN. AT THIS POINT THE ENGINE SEIZED AND THE CAR STALLED. IT HAD TO BE TOWED TO THE KIA DEALER AND A NEW ENGINE HAD TO BE PUT IN. WE WERE TOLD BY THE SERVICE MANAGER AT THE KIA DEALERSHIP THAT RECALL SC147 ADDRESSES 2012 KIA SORENTO'S AND THE EXACT SAME ISSUE AS OUR CAR HAD. HOWEVER, THE RECALL DOES NOT INCLUDE HER ENGINE TYPE. GIVEN WHAT HAPPENED TO OUR 17 YEAR OLD DAUGHTER AND THE DANGEROUS SITUATION THAT SHE WAS PUT IN, WE FEEL THAT THESE SORENTO ENGINE TYPES SHOULD ALSO BE INCLUDED IN THE RECALL. KIA CONSUMER AFFAIRS WAS CONTACTED AND THEY REFUSED TO PROVIDE ANY TYPE OF COMPENSATION OR ADD THIS VEHICLE ENGINE TYPE TO THE RECALL.

-54-

1 2 Vehicle: 2012 Kia Sorento 3 Date Complaint Filed: 09/26/2017 Date of Incident: 09/24/2017 4 Component(s): ENGINE 5 NHTSA ID Number: 11030026 6 **SUMMARY:** 7 AFTER 88,000 MILES, THE SORENTO'S ENGINE 8 STARTED MAKING A LOUD SOUND WHILE DRIVING AT HIGHWAY SPEED. THE ENGINE STAYED ON BUT 9 CONTINUED TO MAKE A LOUD SOUND. THE CAR WAS 10 TOWED TO PEAK KIA IN LITTLETON. CO WHERE IT 11 WAS DETERMINED THAT A NEW ENGINE WAS NEEDED AT A COST OF \$7000-\$10,000 DOLLARS. THE 12 VEHICLE HAD REGULAR OIL CHANGES UP TO THIS 13 POINT. THE DEALERSHIP CHECKED AN MY VIN NUMBER AND SAID THAT I DIDN'T QUALIFY FOR THE 14 RECALL FOR ENGINE PARTICLES. AS A SECOND 15 OWNER, I DID NOT HAVE ACCESS TO THE 10 YEAR WARRANTY. I FEEL AS IF THE RECALL NEEDS TO BE 16 EXPANDED AND HONORED. MY 5 YEAR OLD WELL 17 MAINTAINED CAR HAD NO REASON TO HAVE 18 CATASTROPHIC ENGINE FAILURE. I BELIEVE THIS IS A MANUFACTURING DEFECT THAT IS DANGEROUS 19 AND THAT IS EFFECTING OWNERS ACROSS THE 20 COUNTRY. 21 22 Vehicle: 2012 Kia Sorento 23 Date Complaint Filed: 09/11/2017 Date of Incident: 09/10/2017 24 Component(s): ENGINE 25 NHTSA ID Number: 11022610 26 **SUMMARY:** 27 ON 09/10/2017 WHILE DRIVING A 2012 KIA SORENTO 28 DOWN THE HIGHWAY I HEARD A RATTLING NOISE -55-Consolidated Class Action Complaint

FROM THE ENGINE WITH A LOUD BANG A FEW 1 SECONDS LATER. THERE WAS SMOKE COMING FROM 2 UNDER THE HOOD. I RESEARCHED AND FOUND THAT 3 ON 03/17/2017 KIA ANNOUNCED A RECALL FOR 2012 SORENTOS. KIA'S RECALL: SC147: "BEARING WEAR 4 MAY RESULT IN ENGINE SEIZURE" THIS IS ON KIA'S 5 AND NHTSA'S WEBSITES. [ NHTSA CAMPAIGN # 17V224000 "MACHINING ERRORS DURING THE ENGINE 6 MANUFACTURING PROCESS MAY CAUSE 7 PREMATURE BEARING WEAR WITHIN THE ENGINE"] I 8 CONTACTED KIA'S CUSTOMER SERVICE AT 1800-333-4542 AND BETHANY TOLD THAT MY 2012 KIA 9 SORENTO WAS NOT ELIGIBLE FOR THE RECALL 10 BECAUSE THE VIN # WAS NOT PART OF THE RECALL. SHE SAID THAT I COULD TAKE IT TO THE DEALER 11 AND THEY WOULD CHECK THE OTHER 2 RECALL 12 THOUGH. WHEN THE VEHICLE WAS TOWED I 13 LOOKED UNDER THE VEHICLE TO SEE OIL POURING OUT FROM A 3 INCH HOLE IN THE BLOCK, TOWARD 14 THE REAR OF THE VEHICLE, WHERE THE THROWN 15 ROD BROKE THE BLOCK. OIL IS CHANGED EVERY THREE MONTHS AND THE VEHICLE HAS 120.129 16 MILES ON IT. THE COST OF A USED ENGINE ALONE IS 17 NEAR \$3000, PLUS LABOR TO INSTALL A MOTOR 18 THAT COULD DO THE SAME THING. I WOULD LIKE KIA MOTORS TO REPLACE THE DEFECTIVE ENGINE 19 WITH A NEW ENGINE AT NO COST. 20 21 Vehicle: 2012 Kia Sorento 22 Date Complaint Filed: 08/16/2017 23 Date of Incident: 08/10/2017 Component(s): ENGINE 24 NHTSA ID Number: 11015830 25 **SUMMARY:** 26 ON 08/10/12017 WHILE DRIVING MY 2012 KIA SORENTO 27 ON I-40. I HEARD A "RATTLING NOISE" FROM THE 28 ENGINE. AS I SLOWED DOWN THE SOUND GOT

-56-

LOUDER. I TURNED ON A SIDE STREET INTO A SAFE 1 AREA AND PARKED MY VEHICLE. THERE WAS 2 SMOKE COMING FROM UNDER MY HOOD. I OPENED 3 THE HOOD AND SAW 2 SMALL PATCHES OF FIRE. I WAS ABLE TO PUT THEM OUT, THEN RAN TO A BEST 4 WESTERN HOTEL AND ASKED FOR A FIRE 5 EXTINGUISHER IN CASE A FIRE WOULD ERUPT AGAIN. I RESEARCHED AND DISCOVERED THAT ON 6 03/17/2017 KIA ANNOUNCED A RECALL FOR 2012 7 SORENTOS. KIA'S RECALL: SC147: "BEARING WEAR 8 MAY RESULT IN ENGINE SEIZURE" THIS IS ON KIA'S, NHTSA'S, PBS AND FORBES WEBSITES. [ NHTSA 9 CAMPAIGN # 17V224000 "MACHINING ERRORS 10 DURING THE ENGINE MANUFACTURING PROCESS MAY CAUSE PREMATURE BEARING WEAR WITHIN 11 THE ENGINE"] I CONTACTED KIA'S CONSUMER 12 AFFAIRS # AND THE PERSON TOLD THAT MY 2012 KIA 13 SORENTO WAS NOT ELIGIBLE FOR THE RECALL. HE SAID MY VIN # WAS NOT PART OF THE RECALL. I HAD 14 JUST RETURNED WITH MY FAMILY 1 DAY PRIOR 15 FROM A TRIP TO MOBILE, AL. (1500 MILES ROUND TRIP). ON 08/12/17 I HAD MY VEHICLE TOWED TO 16 BATTLEGROUND KIA WHERE THE ADVISOR & 17 TECHNICIAN SHOWED ME THE PROBLEM A "THROWN 18 ROD".THIS HOLE IS 3" TO 4" DIAMETER. (PICTURES ATTACHED). I ASKED WHAT COULD HAVE CAUSED 19 THE ROD TO BE THROWN? I HAD MY OIL CHANGED 20 ON SCHEDULE THE LATEST WAS 07/26/2017. THIS VEHICLE HAS 123,937 MILES ON IT. HE REPLIED HE 21 DIDN'T KNOW WHAT CAUSED IT. ON 08/15/2017 I WAS 22 INFORMED THAT TO REPLACE THE ENGINE WITH A USED ONE WITH 99,000 MILES WAS \$6400 PLUS 23 LABOR. [THAT IS ABOUT 24,000 MILES LESS THAN 24 MINE CURRENT MILEAGE WITH THE SAME 25 POTENTIAL PROBLEM LINGERING TO HAPPEN AGAIN] IT IS OBVIOUS THAT THE PROBLEMS WITH THE 26 RECALL ENGINES ARE IDENTICAL WITH MINE. I 27 WOULD LIKE KIA MANUFACTURING TO REPLACE MY DEFECTIVE ENGINE WITH A NEW ENGINE AND 28

RENTAL VEHICLE AT NO COST TO ME. I'LL LIKE TO 1 PARTNER WITH THE LOCAL DEALERSHIP TO RECTIFY 2 THIS. 3 UPDATED 08/31/2017\*JS 4 5 Vehicle: 2012 Kia Sorento 6 Date Complaint Filed: 08/05/2017 7 Date of Incident: 08/02/2017 Component(s): ENGINE 8 NHTSA ID Number: 11013013 9 **SUMMARY:** 10 AS I CAME AROUND A BEND AT ABOUT 20 MPH, MY 11 2012 KIA SORENTO DIED. THERE WAS NO WARNING, 12 AND NO CHECK ENGINE LIGHT. I WAS ON A CITY STREET. AND HAD JUST PRESSED THE BRAKE PEDAL 13 TO SLOW DOWN FOR THE TURN. THANKFULLY I WAS 14 ABLE TO PULL INTO A PARKING LOT, AND NOT DRIVING ON THE HIGHWAY WITH MY CHILDREN. I 15 TRIED TO CRANK THE CAR AGAIN, AND IT STARTED, 16 RAN FOR A BRIEF MOMENT, SOUNDED NORMAL, THEN DIED. I TRIED TWICE MORE WITH THE SAME 17 RESULT, THEN CALLED A TOW TRUCK TO GET HOME. 18 WE CALLED THE DEALERSHIP THE NEXT DAY TO 19 NOTIFY THEM OF THE ISSUE, AND THEY SENT OUT A TOW TRUCK. WHEN THEY TRIED TO CRANK IT, IT 20 RAN ROUGH AND THEN DIED. WE ARE AWAITING 21 APPROVAL FROM CORPORATE KIA, AS WE BELIEVE THAT THIS IS RELATED TO THE ENGINE RECALL 22 THEY HAVE ISSUED. 23 24 Vehicle: 2012 Kia Sorento 25 Date Complaint Filed: 07/03/2017 26 Date of Incident: 01/14/2017 Component(s): ENGINE 27 NHTSA ID Number: 11002875 28 -58-

**SUMMARY:** 1 TL\* THE CONTACT OWNS A 2012 KIA SORENTO. 2 WHILE DRIVING 90 MPH, THE ENGINE FAILED 3 WITHOUT WARNING. THE CONTACT STATED THAT THERE WAS A KNOCKING NOISE FROM INSIDE THE 4 ENGINE AND THE VEHICLE LOST POWER. IN 5 ADDITION. THE VEHICLE WOULD NOT SWITCH GEARS AND DECREASED IN ACCELERATION UNTIL 6 THE CONTACT REACHED THE DEALER. CATHEDRAL 7 CITY KIA OF CATHEDRAL CITY, CALIFORNIA 8 REPLACED THE ENGINE IN THE VEHICLE. THE MANUFACTURER WAS MADE AWARE OF THE ISSUE 9 AND STATED THAT THE FAILURE WAS INCLUDED IN 10 AN UNKNOWN RECALL; HOWEVER, THE CONTACT'S VIN WAS NOT INCLUDED. THE FAILURE MILEAGE 11 WAS 97,000. 12 13 Vehicle: 2012 Kia Sorento 14 Date Complaint Filed: 06/27/2017 15 Date of Incident: 06/22/2017 Component(s): ENGINE 16 NHTSA ID Number: 11001807 17 **SUMMARY:** 18 MY ENGINE SEIZED WHILE DRIVING ON TO RAMP TO 19 HIGHWAY. MY CAR CUT OFF AND WAS 20 UNRESPONSIVE. I FORCED THE CAR TO THE SIDE OF THE ON-RAMP DURING RUSH HOUR TRAFFIC. AT THIS 21 TIME, I HAD TO HAVE MY VEHICLE TOWED. THERE IS 22 A RECALL ON THE 2012 KIA SORENTO ENGINE FOR IT STALLING WHILE DRIVING. I CALLED KIA 23 CORPORATE FOR ASSISTANCE WITH THIS MATTER 24 AND THEY ARE GIVING US THE RUN-AROUND. I HAVE HAD THE VEHICLE BORE SCOPED, PROVING SEIZING 25 OF THE ENGINE. IN ADDITION, I AM A LICENCES AIR-26 FRAME AND POWER-PLANT MECHANIC SO I KNOW 27 MY WAY AROUND A CAR. THIS WAS VERY DANGEROUS AND UNEXPECTED SITUATION TO BE IN. 28

-59-

1 2 Vehicle: 2012 Kia Sorento 3 Date Complaint Filed: 07/27/2017 Date of Incident: 06/23/2017 4 Component(s): ENGINE 5 NHTSA ID Number: 11001733 6 **SUMMARY:** 7 MY VEHICLE IS AT 117K MILES. IT USES APPROX 6 8 OTS OF OIL/3000 MILES.I CANNOT GET UP TO SPEED ON THE HIGHWAY AS IT WILL NOT AUTO SHIFT 9 DOWN WITH ANY ACCELERATION RPMS RUN AND 10 STAY AT 6.000 WHEN TRYING TO GET TO 70MPH - IT IS 11 INCLUDED IN SC147 RECALL, HOWEVER THE DEALERSHIP IS STATING IT PASSED THE RECALL 12 TEST AND IT'S THE TRANSMISSION NOT THE ENGINE. 13 TRANSMISSION DOES NOT BURN OIL AT 6 QTS/3000 **MILES** 14 15 16 Vehicle: 2012 Kia Sorento Date Complaint Filed: 06/23/2017 17 Date of Incident: 06/14/2017 18 Component(s): ENGINE NHTSA ID Number: 11000841 19 20 **SUMMARY:** 21 TL\* THE CONTACT OWNS A 2012 KIA SORENTO. WHILE DRIVING ON THE HIGHWAY, THE MOTOR 22 SEIZED. THE VEHICLE WAS UNABLE TO BE DRIVEN 23 AND WAS TOWED TO AN INDEPENDENT REPAIR SHOP WHO INDICATED THAT THE VEHICLE NEEDED TO BE 24 SERVICED BY AN AUTHORIZED DEALER. THE 25 CONTACT WAS INCLUDED IN NHTSA CAMPAIGN 26 NUMBERS: 17V224000 (ENGINE AND ENGINE COOLING) AND 15V626000 (POWER TRAIN), BUT THE 27 CONTACT WAS UNABLE TO RECEIVE THE REMEDY 28 AND PARTS FOR THE RECALL REPAIR. THE VEHICLE -60-

WAS TOWED TO MEDVED KIA (11201 W INTERSTATE 1 70 FRONTAGE RD N, WHEAT RIDGE, CO 80033, (303) 2 421-0100). THE CONTACT WAS WAITING ON A 3 RESPONSE FROM THE MANUFACTURER TO PROVIDE A REMEDY FOR THE TWO RECALL REPAIRS. THE 4 MANUFACTURER STATED THAT THEY WOULD 5 RESPOND, BUT THE CONTACT HAD NOT RECEIVED THE REPAIRS SINCE JUNE OF 2016. THE 6 APPROXIMATE FAILURE MILEAGE WAS 104,000. 7 PARTS DISTRIBUTION DISCONNECT. 8 9 Vehicle: 2012 Kia Sorento 10 Date Complaint Filed: 06/19/2017 11 Date of Incident: 03/31/2017 Component(s): ENGINE 12 NHTSA ID Number: 10995819 13 **SUMMARY:** 14 TL\* THE CONTACT OWNS A 2012 KIA SORENTO. THE 15 CONTACT STATED THAT THE ENGINE MADE AN ABNORMAL NOISE AND STALLED SEVERAL TIMES 16 WITHOUT WARNING. THE VEHICLE WAS UNABLE TO 17 BE DRIVEN AND WAS TOWED TO THE DEALER 18 (MORITZ KIA FORT WORTH 501 WEST FWY, FORT WORTH, TX 76116 (817) 560-6000). IT WAS DIAGNOSED 19 THAT THE ENGINE ASSEMBLY NEEDED TO BE 20 REPLACED. THE DEALER INDICATED THAT THEY WERE UNCERTAIN OF WHEN THE PART WOULD BE 21 PRODUCED. THE CONTACT WAS PROVIDED WITH A 22 LOANER VEHICLE, BUT WAS UNABLE TO DETERMINE 23 A REASONABLE TIME FRAME FOR WHEN THE VEHICLE WOULD BE REPAIRED. THE 24 MANUFACTURER WAS NOTIFIED OF THE FAILURE. 25 THE APPROXIMATE FAILURE MILEAGE WAS 78,000. UPDATED 08/30/17\*LJ 26 27 28 Vehicle: 2012 Kia Sorento -61-

Date Complaint Filed: 06/16/2017
Date of Incident: 05/01/2017
Component(s): ENGINE
NHTSA ID Number: 10995476

## **SUMMARY:**

TL\* THE CONTACT OWNS A 2012 KIA SORENTO. WHILE OPERATING THE VEHICLE, A LOUD TICKING NOISE WAS PRESENT COMING FROM THE ENGINE AND THE VEHICLE SUDDENLY SHUT OFF. THE VEHICLE WAS TOWED TO SOUTHWEST KIA OF ROUND ROCK, TEXAS WHERE IT WAS DIAGNOSED THAT THE ENGINE WAS FAULTY AND NEEDED TO BE REPLACED. THE VEHICLE WAS NOT REPAIRED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 103,000.

Vehicle: 2012 Kia Sorento

Date Complaint Filed: 06/12/2017

Date of Incident: 05/06/2017 Component(s): ENGINE

NHTSA ID Number: 10994530

## **SUMMARY:**

ON TUESDAY MAY 16TH, 2017 AT ABOUT 10:30 PM I WAS DRIVING DOWN THE HIGHWAY IN MY KIA ALL OF A SUDDEN LOST POWER. THERE WAS NO INDICATION THAT A PROBLEM EXISTED. I WAS DRIVING EAST ON THE INTERSTATE AT ABOUT 70 MPH BUT I WAS ABLE TO MANEUVER TO THE SIDE OF THE ROAD AFTER THE LOSS OF POWER AND AVERTED BEING HIT FROM BEHIND FROM A SEMI. I HAD 5 OTHER OCCUPANTS IN THE CAR AS WE WERE COMING HOME FROM A BALL GAME. A GOOD SAMARITAN HAPPENED ALONG AND TOOK THE OCCUPANTS TO A WAFFLE HOUSE WHILE I WAITED WITH MY WIFE FOR A TOW TRUCK. WE TOOK THE CAR TO MY MECHANIC WHO INFORMED ME THAT

-62-

THE ENGINE HAD SEIZED. HE NOTICED THAT THERE 1 WERE BITS OF METALLIC IN THE OIL AND SAID IT 2 WOULD BE BEST TO HAVE IT REPLACED. WE HAD 3 STARTED INVESTIGATING THE COST OF A USED ENGINE WHEN I READ ABOUT A CLASS ACTION SUIT 4 INVOLVING KIA AND OWNERS OF CARS WITH A 2.4 5 GDI ENGINE. THEIR COMPLAINTS PARALLELED WHAT I HAD JUST WITNESSED. THE RECALL NUMBER 6 FOR THIS IS IS NHTSA 17V-224. 7 8 Vehicle: 2012 Kia Sorento 9 Date Complaint Filed: 06/01/2017 10 Date of Incident: 05/19/2017 11 Component(s): ENGINE NHTSA ID Number: 10992669 12 13 **SUMMARY:** TL\* THE CONTACT OWNS A 2012 KIA SORENTO. 14 WHILE DRIVING 45 MPH, THE CRANK CASE BEARING 15 IN THE ENGINE DISINTEGRATED AND RUINED THE MOTOR. THE VEHICLE WAS TOWED TO OXONDALE 16 KIA IN FLAGSTAFF ARIZONA WHERE IT WAS 17 DIAGNOSED THAT METAL FRAGMENTS ENTERED 18 INTO THE ENGINE OIL DEPOSIT, WHICH CAUSED FURTHER DAMAGE TO THE VEHICLE. THE SERVICE 19 MANAGER AT THE DEALER STATED THAT THERE 20 WAS A RECALL FOR THE FAILURE, BUT THE CONTACT'S VIN WAS NOT INCLUDED. THE 21 MANUFACTURER WAS MADE AWARE OF THE 22 FAILURE. THE RECALL DETAILS WERE NOT 23 PROVIDED. THE FAILURE MILEAGE WAS APPROXIMATELY 81,000. 24 25 26 Vehicle: 2012 Kia Sorento Date Complaint Filed: 03/31/2017 27 Date of Incident: 03/30/2017 28 Component(s): ENGINE -63-

NHTSA ID Number: 10992492 1 2 **SUMMARY:** 3 5/30/2017 I WAS DRIVING AND I WAS MERGING ONTO THE FREEWAY SO I GAVE MY CAR ABOUT HALF 4 THROTTLE AND AS SOON AS THE CAR STARTED TO 5 ACCELERATE THE ENGINE STOPPED ACCELERATING WHILE MY FOOT WAS STILL ON THE GAS AND ALL OF 6 THE LIGHT WENT ON ON MY DASHBOARD AND THE 7 ENGINE COMPLETELY SHUT OFF. THE RPM'S 8 DROPPED COMPLETELY BUT EVERYTHING ELSE STAYED ON, LIGHTS, STEERING, BRAKES, INTERIOR 9 ELECTRONICS, EVERYTHING BUT THE ENGINE ITSELF 10 REMAINED ON. I WENT TO START THE CAR AFTER I CAME TO A COMPLETE STOP AND IT MAKE SOME 11 WEIRD TICKING NOISES BEFORE IT ACTUALLY 12 TURNED ON AND IT IDLED, BUT AS SOON AS I GAVE 13 IT SOME GAS THE ENGINE SHUT OFF. 14 DEALER SAID ENGINE WAS SEIZED AND THERE WAS SLUDGE IN THE OIL, DID NOT PHYSICALLY SEE THIS 15 **MY SELF** 16 17 Vehicle: 2012 Kia Sorento 18 Date Complaint Filed: 05/24/2017 19 Date of Incident: 05/15/2017 Component(s): ENGINE 20 NHTSA ID Number: 10991363 21 22 **SUMMARY:** TL\* THE CONTACT OWNS A 2012 KIA SORENTO. THE 23 CONTACT STATED THAT WHILE DRIVING AT 24 APPROXIMATELY 60 MPH, ALL THE WARNING INDICATORS ILLUMINATED AND THE VEHICLE LOST 25 ACCELERATION POWER. THE CONTACT COASTED TO 26 THE SIDE OF THE ROAD. THE VEHICLE WAS TOWED 27 TO THE RESIDENCE. THE FOLLOWING DAY THE VEHICLE WAS TOWED TO THE DEALER WHERE IT 28 WAS DIAGNOSED THAT THE ENGINE NEEDED TO BE -64-

REPLACED. THE VEHICLE WAS NOT REPAIRED. THE 1 MANUFACTURER WAS NOTIFIED OF THE FAILURE. 2 THE APPROXIMATE FAILURE MILEAGE WAS 82,000. 3 4 Vehicle: 2012 Kia Sorento 5 Date Complaint Filed: 05/16/2017 Date of Incident: 03/16/2017 6 Component(s): ENGINE 7 NHTSA ID Number: 10985936 8 **SUMMARY:** 9 I HAVE CONTACTED THE KIA DEALERSHIP THREE 10 TIMES ABOUT THIS CAR BURNING OIL. THEY TOLD ME THIS IS NORMAL FOR A VEHICLE THAT HAS 90,000 11 MILES ON IT. ONE TIME I HAD TO PUT 2 OUARTS OF 12 OIL IN IT AND THEN AFTER DRIVING 400 MILES I HAD TO PUT ANOTHER 1 QUART OF OIL IN IT. I 13 UNDERSTAND THEY COULD BE A PROBLEM WITH 14 THE 2.4 ENGINE IN THIS VEHICLE. ALL I AM ASKING 15 IS FOR THEM TO DO A COMBUSTION TEST ON THE ENGINE WHILE IT IS STILL UNDER WARRANTY. 16 17 Vehicle: 2012 Kia Sorento Date Complaint Filed: 05/08/2017 18 Date of Incident: 05/01/2017 19 Component(s): ENGINE 20 NHTSA ID Number: 10984187 21 **SUMMARY:** 22 TL\* THE CONTACT OWNS A 2012 KIA SORENTO. THE 23 CONTACT STATED THAT THERE WAS A SUDDEN LOSS OF POWER WHEN APPLYING THE ACCELERATOR 24 PEDAL. THE DRIVER NOTICED THAT SMOKE WAS 25 EMITTING UNDER THE HOOD OF THE VEHICLE, THE CHECK ENGINE WARNING LIGHT ILLUMINATED AND 26 A FIRE ERUPTED UNDER THE HOOD, A PASSERBY 27 STAYED WITH THE DRIVER UNTIL A STATE TROOPER WAS PRESENT AS THE VEHICLE WAS ON FIRE AND 28 -65-

1 2 3 4 5 6 7	THE FLAMES WENT OUT OVER TIME. THE DRIVER WAS ABLE TO EXIT THE VEHICLE. THE VEHICLE WAS TOWED TO A MECHANIC YARD. THE VEHICLE WAS NOT INCLUDED IN NHTSA CAMPAIGN NUMBER: 17V224000 (ENGINE AND ENGINE COOLING). THE CONTACT WAS WAITING TO DETERMINE A RESPONSE FROM THE MANUFACTURER TO DIAGNOSE HOW THE FAILURE OCCURRED. THE APPROXIMATE FAILURE MILEAGE WAS 103,000UPDATED 06/27/17 *BF
8	W.1: 1. 2012 W. C
9	Vehicle: 2012 Kia Sorento Date Complaint Filed: 04/27/2017
10	Date of Incident: 04/01/2017
11	Component(s): ENGINE
12	NHTSA ID Number: 10981104
13	SUMMARY:
14	CAR NEVER GAVE A WARNING THAT ANYTHING WAS
15	WRONG, TOOK IT TO GET REGULAR OIL CHANGES AS
	NEEDED AND SUDDENLY IN TRAFFIC WHILE MOVING
16	FORWARD, THE CAR BEGAN BUCKING AND JUMPING, THE NOISE SOUNDED LIKE A CLUCK. I THOUGHT
17	SOMETHING HAD FALLEN OFF AS THE CAR WAS
18	ORIGINALLY DRIVING SMOOTHLY. I HAD IT TOWEDT
19	TO KIA AND IT WAS SAID THE ENGINE WAS NO
20	GOOD. NO WARNING LIGHTS OR ENGINE LIGHTS
	EVER CAME ON TO FOREWARN OF ANY ISSUES EVER WITH THE CAR.
21	WITH THE CAR.
22	
23	Vehicle: 2012 Kia Sorento
24	Date Complaint Filed: 04/19/2017 Date of Incident: 04/17/2017
25	Component(s): ENGINE
26	NHTSA ID Number: 10979270
27	SUMMARY:
	BOUGHT MY SORENTO BRAND NEW. HAVE HAD FOR
28	5 YEARS AND HAVE 1 YEAR LEFT ON LOAN. I HAVE
	Consolidated Class Action Complaint

RECORDS OF TAKING VEHICLE TO DEALERSHIP AND 1 HAD SEVERAL COMPLAINTS OF HEARING RATTLE 2 LIKE A PAINT CAN.. YET THEY BLEW ME OFF. GAVE 3 ME POOR EXCUSES FOR REASONING AND STATED THIS WAS NORMAL SOUND.. I FELT THAT THERE WAS 4 AN ISSUE YET BELIEVED THE TECHNICIAN OVER MY 5 CONCERNS.. NOISES CONT FOR COUPLE YEARS YET NOTHING GOT WORSE. THEN SHE. I WAS AT 128 K 6 MILES KIA SENDS OUT THE EXTENDED WARRANTY 7 LETTER AND I TOOK MY VEHICLE TO ANOTHER 8 DEALER TO GET AN UNDERSTANDING THAT THIS ISN'T A NORMAL SOUND AND THAT THERE WAS 9 SOMETHING SERIOUSLY WRONG YET THEY 10 BELIEVED A ENGINE FLUSH WOULD GET RID OF CARBON BUILD UP AND ALL WOULD BE GOOD.. 11 AFTER PAYING OUT OF POCKET FOR THIS NOTHING 12 CHANGED AND I GOT LITTLE TO NO ASSISTANCE W 13 THE NEW DEALER I TRAILED. I DON'T TO DRIVE THE VEHICLE BC I HAD NO OPTIONS. NO MONEY LEFT TO 14 FIX MY CAR IN WHICH CAST ME MONTHLY... 15 REPAIRED ALL THINGS NEEDED BY THE KIA BOOK AND AS REOUIRED BY SERVICING W FUEL 16 ADDITIVES AS RECOMMENDED YET NOW I HAVE A 17 COMPLETE BLOWN ENGINE. STILL OWE AND NOW 18 FIGHTING TO GET KIA TO HELP ME. THE RECALL LETTER ISN'T OUT YET THERE IS EXPECTED A 19 RECALL.. I NOW HAVE 141K MILES AND NEED HELP.. 20 I'M LUCKY THAT WE WERE NOT HURT.. OUR ENGINE BLEW IN THE MOUNTAINS.. TOOK ME AAA.. 150 21 **BUCKS AND 6HRS TO GET HOME W FRIENDS** 22 ASSISTANCE.. 23 24

Vehicle: 2012 Kia Sorento

Date Complaint Filed: 04/07/2017

Date of Incident: 08/07/2014 Component(s): ENGINE

NHTSA ID Number: 10971238

28

25

26

27

## **SUMMARY:**

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

I USED MOBILE ONE 5W30, I USED KIA OIL FILTERS (2 GENERIC), I HAD 44,516K MILES ON IT ON AUGUST 7. 2014. I DID 8 OIL CHANGES. MY CAR WAS RUNNING PERFECTLY FINE. NO WHITE OR BLACK SMOKE, NO DASHBOARD LIGHTS, NOT SLUGGISH, NOTHING AND THE ENGINE SEIZED WITHOUT WARNING. I WAS ON THE HIGHWAY DOING ABOUT 65 WHEN I HEARD A FLUTTERING NOISE THAT VERY QUICKLY TURNED INTO A KNOCKING NOISE. I COULD BARELY PULL OVER WITHOUT ALMOST GETTING HIT TWICE. I HAD IT TOWED TO THE DEALERSHIP AND THEY SAID I NEVER DID ANY OIL CHANGES AND THERE WAS APPROXIMATELY 20K MILES WORTH OF SLUDGE IN MY ENGINE. MY OIL WAS CHANGED AROUND MARCH 7, 2014. KIA MOTORS DOWN RIGHT REFUSED TO EVEN LOL AT IT. I HIRED AND ATTORNEY WHO WROTE A DEMAND LETTER AND 4 MONTHS LATER THEY DOWN RIGHT REFUSED TO FIX IT UNDER THE WARRANTY. MY CAR SAT IN MY DRIVEWAY FOR OVER 15 MONTHS. I REPORTED THIS TO NHTSA BACK IN LATE 2012 EARLY 2013. I WORE A LETTER TO THE OWNER OF THE DEALERSHIP AND SHE PUT A USED ENGINE IN IT AND PAID FOR HALF. NEEDLESS TO SAY I'M HAPPY I HAVE MY CAR BACK BUT I DON'T TRUST IT. I HAVE THE TOP OF THE LINE SX AWD AND I ALSO ADDED THE AMBIENT LIGHTING AND TINTED THE FRONT WINDOWS. I LOVE MY CAR BUT FEEL I SHOULD BE COMPENSATED FOR THE SHEAR HELL AND HUGE FINANCIAL BURDEN IT HAS CAUSED MY FAMILY. I'VE HAD IT BACK SINCE NOVEMBER 12, 2016 AND THE FINANCIAL BURDEN IS STILL HAUNTING MY FAMILY.

Vehicle: 2012 Kia Sorento

Date Complaint Filed: 03/03/2017 Date of Incident: 02/24/2017 Component(s): ENGINE

-68-

NHTSA ID Number: 10958352 1 2 **SUMMARY:** 3 COMPLETE ENGINE FAILURE. WHILE PASSING A LARGE TRUCK ON A NARROW TWO LANE HIGHWAY 4 THE ENGINE COMPLETELY SHUT DOWN MIDWAY 5 THROUGH THE PASS. MOMENTUM ALLOWED THE CAR TO COMPLETE THE PASS, BUT DUE TO THE 6 SPEED AND WITHOUT POWER STEERING IT WAS 7 VERY DIFFICULT TO MANEUVER. FORTUNATELY I 8 WAS FAMILIAR WITH THE ROAD AND ABLE TO MAKE IT SAFELY TO A PULL OFF. MY LOCAL REPAIR 9 GARAGE DETERMINED THE ENGINE IS SEIZED, WITH 10 METAL FRAGMENTS IN THE OIL. HAVE MADE MULTIPLE ATTEMPTS TO CONTACT THE DEALER 11 WHERE THE CAR WAS PURCHASED. TO DATE, NO 12 RESPONSE. CAR IS CURRENTLY NOT DRIVABLE. 13 14 Vehicle: 2012 Kia Sorento 15 Date Complaint Filed: 03/02/2017 Date of Incident: 03/02/2017 16 Component(s): ENGINE 17 NHTSA ID Number: 10958256 18 **SUMMARY:** 19 VEHICLE WAS ON THE HIGHWAY AT 20 APPROXIMATELY 55 MPH, READY TO GET OFF OFF RAMP WHEN VEHICLE STARTED RUNNING ROUGH 21 AND TURNED OFF, ON 2-28-17 IN THE MORNING. WE 22 TOWED IT TO THE KIA SERVICE. THEY DIAGNOSED 23 SLUDGE IN THE ENGINE AND THAT IT HAS TO BE REPLACED. THE VEHICLE ONLY HAS 84K MILES AND 24 THE OIL CHANGES HAVE BEEN DONE EVERY 3 TO 4 K. 25 THEY REQUESTED ALL THE OIL SERVICE RECORDS. 26 27 Vehicle: 2012 Kia Sorento 28 Date Complaint Filed: 02/18/2017 -69-Consolidated Class Action Complaint

Date of Incident: 06/04/2016 1 Component(s): ENGINE 2 NHTSA ID Number: 10955428 3 **SUMMARY:** 4 ENGINE FAILURE ENGINE STOPPED IN MIDDLE OF 5 HIGHWAY TRAVELING AT 55 MPH STRAIGHT HIGHWAYPUT FAMILY IN DANGER 2016 JUNE OIL 6 LEAKING ALL OVER GROUND AND ELECTRICAL 7 FAILURE PUSHED CAR TO SIDE OF HIGHWAY .140000 8 MILE PAST WARRANTY KIA REFUSE TO FIX. 9 10 Vehicle: 2012 Kia Sorento 11 Date Complaint Filed: 01/06/2017 Date of Incident: 12/30/2016 12 Component(s): ENGINE 13 NHTSA ID Number: 10940101 14 **SUMMARY:** 15 I NOTICED THAT UPON STARTING, MY KIA LET OUT BLUE SMOKE. I SAW NO WARNING LIGHTS, NO OIL 16 ON THE GROUND, NO INDICATION OF A SERIOUS 17 PROBLEM OTHER THAN THE SMOKE. 18 I HAVE A LITTLE OVER 95,000 MILES ON THE CAR 19 AND A 100,000 MILE WARRANTY 20 I MADE AN APPOINTMENT TO SERVICE THE CAR AND 21 HAVE IT LOOKED AT. EVERYTHING WAS RUNNING 22 FINE AND DRIVING FINE. 23 THREE DAYS LATER, THE CHECK ENGINE LIGHT 24 CAME ON. NO OTHER INDICATORS WERE PRESENT. I 25 DROVE THE CAR A SHORT DISTANCE AND IT SEIZED UP WHILE I WAS TRAVELING AT ABOUT 45 MPH. 26 27 I CHANGED THE OIL ON A REGULAR BASIS & DID THE 28 NORMAL SERVICE WORK. -70-

DAUGHTER, SON-IN-LAW AND GRANDBABY. WHILE GOING DOWN THE HWY 65 MILES PER HOUR, WE

-71-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

28

HEARD A LOUD NOISE, I FELT A THUMP UNDER MY 1 FOOT ON THE PASSENGER SIDE. WE LATER LEARNED 2 IT WAS THE ROD THAT WENT THROUGH THE ENGINE. 3 THANK GOD MY HUSBAND COSTED THE CAR OVER TO THE SIDE, IT WOULD NOT START. WE CALLED FOR 4 HELP FROM A FRIEND THEY PICKED US UP. TOWED 5 THE CAR TO KIA DEALERSHIP IN MYRTLE BEACH. 6 WE HAVE JUST LEARNED THEY ARE NOT GOING TO 7 PAY FOR A NEW MOTOR. THEY HAVE DETERMINED IT 8 WAS NOT THEIR FAULT!! HOW IS THIS POSSIBLE?? WITH ALL THESE COMPLAINTS. WHY IS THERE NOT A 9 CLASS ACTION LAW SUITE? 10 11 Vehicle: 2012 Kia Sorento 12 Date Complaint Filed: 09/22/2016 13 Date of Incident: 09/22/2016 Component(s): ENGINE 14 NHTSA ID Number: 10908736 15 **SUMMARY:** 16 TL\* THE CONTACT OWNS A 2012 KIA SORENTO. 17 WHILE DRIVING VARIOUS SPEEDS, AN ABNORMAL 18 SOUND WAS HEARD COMING FROM THE BOTTOM OF THE VEHICLE. THE VEHICLE STALLED WITHOUT 19 WARNING. THE CONTACT PULLED OVER TO THE 20 SHOULDER, BUT THE VEHICLE FAILED TO RESTART. THE VEHICLE WAS TOWED TO THE DEALER WHERE 21 IT WAS DIAGNOSED THAT THERE WAS A HOLE IN 22 THE ENGINE BLOCK, THE RODS CAME APART, AND 23 THERE WAS NO OIL IN THE VEHICLE. THE DEALER STATED THAT THE ENGINE BLOCK WOULD HAVE TO 24 BE REPLACED. THE VEHICLE WAS NOT REPAIRED. 25 THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE 26 WAS 14,000. 27

-72-

28

Vehicle: 2012 Kia Sorento 1 Date Complaint Filed: 09/22/2016 2 Date of Incident: 09/02/2016 3 Component(s): ENGINE **NHTSA ID Number: 10908752** 4 5 **SUMMARY:** TL\* THE CONTACT OWNS A 2012 KIA SORENTO. 6 WHILE DRIVING 80 MPH, THE VEHICLE 7 DECELERATED AND STALLED WITHOUT WARNING. 8 THE VEHICLE WAS TOWED TO THE DEALER WHERE IT WAS DIAGNOSED THAT A ROD WENT THROUGH 9 THE ENGINE BLOCK. THE VEHICLE WAS NOT 10 REPAIRED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 11 144,000. 12 13 Vehicle: 2012 Kia Sorento 14 Date Complaint Filed: 08/12/2016 15 Date of Incident: 08/07/2016 Component(s): ENGINE 16 NHTSA ID Number: 10895275 17 18 **SUMMARY:** WHILE DRIVING 70MPH ON THE HIGHWAY THE 19 ENGINE SHUT DOWN NO WARNING LIGHTS. NO 20 CHECK ENGINE LIGHTS, NO WARNING WHAT SO EVER. WE HAD A NEAR MISS WITH THE PERSON 21 BEHIND US BUT WERE ABLE TO GET TO THE SIDE OF 22 THE ROAD WITHOUT INCIDENT. THE VEHICLE 23 WOULD NOT START. AFTER WAITING 15 MINUTES I WAS ABLE TO GET THE VEHICLE TO START, IT NOW 24 HAS A LOUD CLANK COMING FROM THE ENGINE AND 25 STILL NO POWER. WE WERE STRANDED UNABLE TO DRIVE IT. WE HAD IT TOWED TO THE DEALERSHIP. 26 THE SERVICE DEPARTMENT LOOKED AT IT AND 27 FOUND METAL SHAVINGS IN THE MOTOR, SAID HE 28 HAS HAD TO FIX MANY OF THESE ISSUES ON THIS -73-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

PARTICULAR MOTOR, GDI 2.4 L AND THAT IT IS A 1 MANUFACTURING ISSUE NOTHING WE DID. THE 2 CAUSE WAS FROM METAL SHAVINGS BLOCKING OIL 3 PASSAGE TO THE RODS AND THE ROD BEARINGS WENT OUT CAUSING A CATASTROPHIC ENGINE 4 FAILURE WITHOUT WARNING. 5 6 Vehicle: 2012 Kia Sorento 7 Date Complaint Filed: 08/06/2016 8 Date of Incident: 08/02/2016 Component(s): ENGINE 9 NHTSA ID Number: 10893682 10 11 **SUMMARY:** THE CAR WOULD LOSE POWER WHILE DRIVING THEN 12 ACCELERATE TO SPEED. THIS WAS FOLLOWED BY 13 SMOKE FROM THE TAIL PIPE. I HAVE RETURNED TO THE YONKERS KIA DEALERSHIP ON CENTRAL PARK 14 AVENUE IN YONKERS NY ON AUGUST 5TH, 2016 TO 15 LOOK INTO A PROBLEM. A DIAGNOSTIC WAS DONE AND IT WAS DETERMINED THE ENGINE WAS RUINED 16 DO TO SLUG BUILD UP. I WAS TOLD THAT A 17 REPLACEMENT WOULD COAST ABOUT \$10,000. ODD 18 FOR ME BECAUSE MY WIFE AND I TOOK THE CAR IN FOR REGULAR OIL CHANGES AND NO INDICATION OF 19 ENGINE ISSUES DISPLAYED ON THE DASHBOARD. 20 AFTER SPEAKING TO A SERVICE REPRESENTATIVE 21 HE STATED THAT I WOULD HAVE TO SUPPORT PROOF 22 OF MAINTENANCE ON MY CAR WHICH WOULD 23 ALLOW MY REPAIRS DONE UNDER OUR WARRANTY. I BECAME EXTREMELY DISILLUSIONED AFTER 24 BRINGING THE CAR INTO KIA DUE TO AN ISSUE THAT 25 CAN BE TIED TO THE MANUFACTURER. WE WERE DENIED SERVICE UNDER THE WARRANTY WHICH WE 26 ARE STILL UNDER. OUR CAR IS FAIRLY NEW WITH

-74-

LESS THAN 25K MILES. WE CARRIED OUT ALL OF THE

STEPS THUS FAR INCLUDING TAKING CARE OF OUR

27

28

INVESTMENT, PROVING OUR CAR HAS BEEN TAKEN 1 CARE OFF INCLUDING KEEPING METICULOUS 2 ANNOTATIONS (KEPT IN THE LOG PROVIDED BY KIA) 3 AND RECEIPTS TO DATE. THIS IS ANOTHER EXAMPLE OF BIG COMPANIES LOOKING FOR LOOPHOLES AND 4 USING TACTICS TO SWINDLE PEOPLE OF THEIR HARD 5 EARNED PAYCHECKS. 6 HOWEVER, KIA DOES NOT WANT TO HONOR US. OUR 7 PAPERWORK/LOG/RECEIPTS ARE BEING TAKEN 8 APART WITH PREJUDICE IN ORDER TO NOT PROVIDE SERVICES AND RECTIFY THIS ISSUE THAT IS PROVEN 9 TO BE A DEFECT. 10 WE ARE CONCLUDING THAT BASED ON THE POOR 11 HANDLING OF OUR CASE AND MANY OTHERS LIKE 12 OURS, KIA AND ITS AFFILIATES /DEALERS AND 13 CORPORATE, ARE NOT ABOUT SAFETY AND CUSTOMER SATISFACTION. ALL WE ASK IS THAT KIA 14 HONORS ITS WARRANTY RATHER THAN FINAGLE 15 USE ON THE FABRICATED NOTION THAT WE ARE AT FAULT RATHER THAN POOR ENGINEERING. 16 17 18 Vehicle: 2012 Kia Sorento Date Complaint Filed: 07/29/2016 19 Date of Incident: 07/05/2016 20 Component(s): ENGINE NHTSA ID Number: 10891685 21 22 **SUMMARY:** 23 TL\* THE CONTACT OWNS A 2012 KIA SORENTO. WHILE DRIVING 70 MPH, THE VEHICLE RANDOMLY 24 STALLED WITHOUT WARNING. THE VEHICLE WAS 25 UNABLE TO BE DRIVEN DUE TO THE FAILURE AND WAS TOWED TO THE DEALER. THE DEALER 26 INDICATED THAT THE ENGINE FRACTURED AND 27 FRAGMENTS ENTERED INTO OTHER AREAS OF THE 28 VEHICLE. THE DEALER REPLACED THE ENGINE -75-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE ASSEMBLY. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE AND PROVIDED NO SOLUTION. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE MILEAGE WAS 67,000. UPDATED 09/23/16\*LJ

Vehicle: 2013 Kia Sorento

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

Date Complaint Filed: 10/05/2017

Date of Incident: 09/22/2017 Component(s): ENGINE

NHTSA ID Number: 11031971

#### **SUMMARY:**

KIA REPLACED MY ENGINE TWICE. DUE TO OIL CONSUMPTION. A MONTH AFTER THE FIRST ENGINE REPLACEMENT, I HAD THE SAME PROBLEMS.. SMOKE COMING OUT OF EXHAUST, LOSS OF POWER, STALLING AND OIL CONSUMPTION. I WAS IN AND OUT OF KIA'S SERVICE DEPARTMENT. THEY TOLD ME NOTHING WAS WRONG! I MOVED FROM CO TO NE, MY HUSBAND AND I HAD TO ADD OIL EVERY 100 MILES, WITH SMOKE COMING OUT OF EXHAUST AND STALLING. LINCOLN NE KIA FOUND AN OIL LEAK AT THE EXHAUST MANIFOLD RIGHT AWAY! KIA INSTRUCTS THEN TO REPLACE MY ENGINE AGAIN! ONCE THEY REPLACED ENGINE, THEY STILL SAW THE LEAK AT THE EXHAUST MANIFOLD WITH RESULTED IN MORE GUESSING AND PARTS. THE DAY AFTER I PICKED IT UP, MY HUSBAND AND I WENT OUT TO DINNER AND MY SORENTO DIED IN THE MIDDLE OF THE ROAD. RIGHT AWAY CALLED AND GOT IT BACK IN. AT FIRST THEY COULD NOT DUPLICATE, HOWEVER AFTER TAKING IT 50 MILES, IT DIED 3 TIMES. THEY STILL CAN'T FIND ANYTHING, BUT FEEL IT MAY BE THE THROTTLE BODY. THEY PUT A USED ONE ON AND HAVE ME DRIVE IT A FEW WEEKS, IT DIDN'T DIE DURING THAT TIME, SO THEY ORDERED A NEW ONE AND INSTALLED. A MONTH LATER I DRIVE TO CO, I BREAK DOWN, IT'S TOWED

-76-

BACK AND KIA CAN'T FIND ANYTHING. I DRIVE IT AND IT DIES 1/2 DOZEN MORE TIMES, EACH TIME I TAKE IT RIGHT IN, BUT THE CODE HAS CLEARED AND THEY CAN'T FIND ANYTHING! FINALLY, IT DOES AND THE LIGHT STAYS ON, IT SHOWS IT'S THE MAP SENSOR. KIA HAS A SPECIALIST COME OUT TO INSTALL THAT AND INSPECT MY CAR. THEY SAY IT'S FIXED AND SAFE. I DRIVE TO CO ON 9/22/17, 2 MONTHS LATER AND MY ENGINE CATCHES ON FIRE. I LOSS MY BRAKES, CAN'T PUT IT IN PARK AND EMERGENCY BRAKE WON'T WORK. FLAMES ARE EVERYWHERE, SMOKE FILLING MY CAR. I JUMP OUT OF MY BURNING, MOVING CAR AND SECONDS LATER THE WHOLE THING ENGULFS IN FLAMES! MOST HORRIFIC. AWFUL THING EVER! I WAS LUCKY ENOUGH TO HAVE MINOR INJURIES. MY MENTAL AND EMOTIONAL STATE ARE A MESS! KIA WON'T DO **ANYTHING!** 

Vehicle: 2013 Kia Sorento

Date Complaint Filed: 09/14/2017 Date of Incident: 06/26/2017

Component(s): ENGINE

NHTSA ID Number: 11023453

#### **SUMMARY:**

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

MILITARY STATIONED OVERSEAS WITH AN UPCOMING MOVE TO THE USA (MOVED AUGUST 2017). ENGINE LIGHT ILLUMINATED ON JUNE 25 2017. ENGINE KNOCK STARTED ON JUNE 26. TOWED TO DEALERSHIP IN ENGLAND ON JULY 11. CAR WAS RULED INOPERABLE WITH ENGINE FAILURE ON JULY 12. WE WERE FORCED TO LEAVE OUR CAR IN ENGLAND DUE TO PARTS AVAILABILITY AND LACK OF ASSISTANCE FROM KIA. WE STILL HAVE NOT HEARD ABOUT PARTS AVAILABILITY NOR ARE WE IN POSSESSION OF OUR CAR. NEARING 3 MONTHS WITHOUT OUR VEHICLE HAS PUT US IN FINANCIAL

-77-

1 2	DISTRESS.
3 4 5 6 7 8 9	Vehicle: 2013 Kia Sorento Date Complaint Filed: 07/2/2017 Date of Incident: 07/16/2017 Component(s): ENGINE NHTSA ID Number: 11010999  SUMMARY: CAR HAS 45K MILES. TOTAL LOSS DUE TO ENGINE FIRE. OIL PAN FAILURE. CAUSE AND ORIGIN REPORT
10	PENDING
$\begin{bmatrix} 11 \\ 12 \end{bmatrix}$	Vehicle: 2013 Kia Sorento
13	Date Complaint Filed: 07/11/2017 Date of Incident: 06/30/2017
14	Component(s): ENGINE
15	NHTSA ID Number: 11004374
16	SUMMARY:
17	MY HUSBAND AND I WERE DRIVING NORTH ON I-49
18	IN LOUISIANA WHEN OUR 2013 KIA SORENTO (APPROXIMATELY 86,000 MILES) BEGAN MAKING A
19	CLICKING/KNOCKING NOISE UPON ACCELERATION,
20	THE CHECK ENGINE LIGHT BEGAN BLINKING, AND
	THE ENGINE IMMEDIATELY SHUT DOWN. WE PULLED
21	OVER TO THE SHOULDER, TURNED THE VEHICLE OFF, AND ATTEMPTED TO RESTART THE VEHICLE;
22	HOWEVER, THE ENGINE FAILED TO RESTART. WE
23	TURNED OUR EMERGENCY LIGHTS ON FOR
24	CAUTIONARY PURPOSES, BUT AFTER
25	APPROXIMATELY 30 MINUTES, THE LIGHTS
26	COMPLETELY STOPPED WORKING. THERE WAS EVIDENCE OF OIL LEAKAGE UNDERNEATH THE
	VEHICLE, AS WELL AS OIL SPLATTER UNDERNEATH
27	THE HOOD OF THE VEHICLE NEAR THE ENGINE AND
28	OVER THE ENTIRE EXTERIOR OF THE VEHICLE, FROM
	-78-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE THE FRONT HOOD TO THE BACK WINDOW. WE HAD THE VEHICLE TOWED TO THE NEAREST KIA DEALERSHIP AND WERE TOLD BY THE SERVICE DEPARTMENT THAT THE BEARINGS IN THE ENGINE HAD FAILED, WHICH RESULTED IN "CATASTROPHIC ENGINE FAILURE," AND THAT ENGINE WILL NEED TO BE REPLACED. WE WERE ALSO INFORMED THAT THE ENGINE IN OUR VEHICLE IS A 2.4-L MPI ENGINE. WHICH IS NOT PART OF THE CURRENT RECALL; HOWEVER, INDIVIDUALS AT THE DEALERSHIP AND WITH KIA CUSTOMER SERVICE CONFIRMED THAT THE PROBLEMS WE EXPERIENCED ARE THE EXACT SAME PROBLEMS THAT HAVE BEEN REPORTED WITH THE 2.4-L GDI ENGINES THAT ARE PART OF THIS RECALL. WE HAVE BEEN EXTREMELY DILIGENT WITH OIL CHANGES, AND HAD APPROXIMATELY 2000 MILES UNTIL OUR NEXT OIL CHANGE, WHICH WE CAN SUPPORT WITH DOCUMENTATION. KIA HAS DENIED OUR REQUEST FOR ASSISTANCE BECAUSE OUR VEHICLE IS NO LONGER UNDER WARRANTY.

Vehicle: 2013 Kia Sorento

Date Complaint Filed: 09/08/16

Date of Incident: 08/3016 Component(s): ENGINE

NHTSA ID Number: 10904585

#### **SUMMARY:**

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

ON TUESDAY, AUGUST 30TH, 2016, MY HUSBAND WAS DRIVING IN OUR 2013 KIA SORENTO WITH OUR TWO TODDLERS WHEN THE CAR JUST STOPPED RUNNING WITH NO WARNING WHATSOEVER. HE WAS GOING APPROXIMATELY 45 MPH DRIVING STRAIGHT WHEN THE FAILURE OCCURRED. WE LOST ALL POWER INCLUDING POWER STEERING SO IT TOOK ALL HE HAD TO COAST AND PULL OVER SAFELY. HE CALLED KIA WHO GOT A TOW TRUCK EN ROUTE TO TOW THE VEHICLE TO OUR DEALERSHIP. MY DAD HAD TO

-79-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

COME BY TO PICK UP MY FRIGHTENED GIRLS WHILE MY HUSBAND WAITED WITH THE VEHICLE (IT TOOK TWO HOURS). WE HAVE NEVER HAD ANY MAJOR ISSUES BEFORE WITH THIS VEHICLE AND FAITHFULLY HAD IT MAINTAINED THROUGH THE DEALERSHIP. THE NEXT DAY, THE SERVICE DEPARTMENT GAVE US NEWS WE WERE NOT EXPECTING; THE ENGINE WAS BLOWN AS WE BROKE A CRANKSHAFT. THIS VEHICLE ONLY HAS 36,000 MILES ON IT!! LUCKILY THIS IS COVERED UNDER THE WARRANTY SINCE THEY VERIFIED THAT IT WAS PROPERLY MAINTAINED BY THEM. FAST FORWARD A WEEK AND WE GET THE CALL TONIGHT THAT KIA HAS YET TO RELEASE A NEW ENGINE TO BE INSTALLED AND THEY HAVE NO TIME FRAME.

Vehicle: 2014 Kia Sorento

Date Complaint Filed: 08/21/2017

Date of Incident: 08/16/2017 Component(s): ENGINE

NHTSA ID Number: 11018645

#### **SUMMARY:**

MY CAR STARTING TO BEGIN TO SHOW LACK OF POWER AT FIRST, WHICH I HAD MENTIONED IN ADVANCE IN SERVICE APPOINTMENTS. TWO DAYS BEFORE MY ONE YEAR OF OWNING IT, THE CAR BEGAN TO STALL OUT WHEN I STOPPED FOR TRAFFIC LIGHTS WITHIN THE SAME DAY A OIL LIGHT WARNING FLASHED, AND THE CAR STARTED TO HAVE A KNOCKING NOISE. I WENT AND ADDED TWO QUARTS OF OIL. ONCE THE OIL LIGHT DISAPPEARED BUT THE KNOCKING CONTINUED. I TOOK THE CAR TO MY REGULAR KIA SERVICE PROVIDER THE SAME DAY AND IN THE PROCESS OF GOING THERE THE ENGINE LIGHT CAME ON. I WAS TOLD TO BRING IT IN THE NEXT DAY, THE ATTENDANT TOLD ME THAT HE COULD HEAR THE KNOCKING, WHICH SOUNDED

-80-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

1 2 3 4 5 6 7 8 9 10 11	CONCERNING. I BROUGHT THE CAR BACK THE NEXT DAY AS INSTRUCTED AND WAS TOLD THAT I SHOULD BE ABLE TO PICK IT UP AT END OF DAY. TIME PASSED BY AND IT WAS GETTING LATE TOWARDS CLOSING, SO I CALLED THE SHOP. I WAS TOLD THAT THE ENGINES HAD SEIZED AND THAT THE OIL BAY WAS DRY. I HAVE NEVER SEEN SOMETHING HAPPEN SO FAST. I HAD NO WARNING OF ANY KIND OF OIL ISSUES UNTIL THE DAY BEFORE, AND I HAD BEEN TAKING THE CAR IN FOR IT'S REGULAR SERVICES. THE CAR WAS IN THE KIA SERVICE SHOP, AND MOVED BY THEM. IT WAS RUNNING WHEN I BROUGHT IT IN BUT I AM BEING TOLD THAT THE ENGINE IS SHOT.
12	Vehicle: 2011 Kia Sportage
13	Date Complaint Filed: 02/13/2017
14	Date of Incident: 02/03/2017 Component(s): ENGINE
15	NHTSA ID Number: 10954281
16	SUMMARY:
17	2011 KIA SPORTAGE - ENGINE FAILED WITHOUT
18	WARNING WITH TWO TODDLERS IN CAR. LUCKILY
19	THIS HAPPENED AS I TURNED OFF A HIGHWAY AND WAS ABLE TO STOP ON THE SHOULDER.
20	MANUFACTURER REFUSES TO FIX BECAUSE I DON'T
21	HAVE MAINTENANCE RECORD. I HAVE A FRIEND
22	WHO HAS BEEN CHANGING OIL/SERVICING CAR. I HAVE LEARNED THAT MANY OWNERS OF THIS
23	YEAR/MODEL CAR HAVE SIMILAR EXPERIENCES. I
24	FEEL THE MANUFACTURER SHOULD DEAL WITH A
25	PROBLEM AS SEVERE AS THIS IMMEDIATELY!
26	
27	Vehicle: 2011 Kia Sportage
	Date Complaint Filed: 06/20/2016
28	Date of Incident: 06/15/2016
	-81-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

Component(s): ENGINE 1 NHTSA ID Number: 10875228 2 3 **SUMMARY:** ENGINE SHUT DOWN IN THE HIGHWAY CAUSING 4 LOSS OF POWER STEERING/BRAKES. CAR HAS LESS 5 THAN 80K MILES, ALL OIL CHANGES PERFORMED PER SPEC RECENTLY ADTER SWITCHING TO FULL 6 SYNTHETIC OIL CHANGED EVERY 5000 MILES. 7 ENGINE SEIZED. VERY SIMILAR TO HYUNDAI RECALL 8 ISSUED 9/25/2015. SAME ENGINE MANUFACTURED IN THE SAME PLANT WITH A DIFFERENT NAME BADGE. 9 10 11 Vehicle: 2011 Kia Sportage Date Complaint Filed: 10/01/2014 12 Date of Incident: 08/30/2014 13 Component(s): ENGINE NHTSA ID Number: 10640483 14 15 **SUMMARY:** SECOND CATASTROPHIC FAILURE OF 2.0 LITER 16 TURBOCHARGED ENGINE IN LESS THAN 30,000 MILES 17 SERVICE. \*TR 18 19 Vehicle: 2012 Kia Sportage 20 Date Complaint Filed: 10/18/2017 Date of Incident: 10/06/2017 21 Component(s): ENGINE 22 NHTSA ID Number: 11034261 23 **SUMMARY:** 24 MY DAUGHTER WAS DRIVING ON THE HIGHWAY 25 AND THE CAR JUST STOPPED, NO WARNING, 26 NOTHING. LUCKILY WAS ABLE TO GET TO SIDE OF ROAD, TOWED AND MECHANIC SAID THE ENGINE IS 27 COMPLETELY BLOWN/SEIZED. WON'T START, STILL 28 AT MECHANICS IN ANOTHER STATE. NO WARNINGS -82-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

OR PRIOR ISSUES. CONSISTENT W/OIL CHANGES AND UPKEEP

Vehicle: 2012 Kia Sportage

Date Complaint Filed: 07/03/2017

Date of Incident: 02/12/2017 Component(s): ENGINE

NHTSA ID Number: 11002799

#### **SUMMARY:**

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

DRIVING DOWN THE ROAD AT APPROXIMATELY 45-50 MPH AND THE ENGINE BEGAN KNOCKING, LOST ALL POWER TO THE CAR. A FEW MOMENTS LATER, THE CAR STOPPED COMPLETELY IN THE MIDDLE OF A BUSY INTERSECTION. I GOT OUT OF THE CAR AND PUSHED IT INTO A GAS STATION PARKING LOT. THE CAR WOULD CRANK BUT THE KNOCKING OF THE ENGINE WAS BECOMING WORSE. I HAD THE CAR TOWED TO A SHOP WHERE THE PROBLEM WAS DIAGNOSED AS "ROD KNOCK" WHICH IS CAUSED BY A FAULTY MOTOR, ALLOWING METAL SHAVINGS TO ENTER AND BLOCK THE FLOW OF OIL TO THE MOTOR. NOT WANTING TO BELIEVE THAT I WAS GOING TO HAVE TO PAY \$5,000 TO REPLACE THE ENGINE, I GOT A SECOND OPINION FROM A KIA DEALERSHIP IN MY HOME TOWN. NOT ONLY DID THEY CONFIRM WHAT THE INITIAL MECHANIC HAD DIAGNOSED. BUT WERE VERY RUDE WHEN ASKING US TO "REMOVE OUR CAR FROM THEIR PARKING LOT BECAUSE UNLESS WE WERE GOING TO PAY THEM TO FIX IT, IT HAD NO BUSINESS BEING THERE." ALL OIL CHANGES HAVE BEEN DONE REGULARLY AND I HAVE DOCUMENTATION FOR THEM ALL. OUR VEHICLE HAD 74,000 MILES ON IT AND WAS KEPT IN EXCELLENT CONDITION. AS OF NOW, KIA HAS DONE NOTHING TO EXPLAIN WHY NOTHING HAS BEEN DONE ABOUT OUR PROBLEM, AS WELL AS MANY OTHERS WHO HAVE HAD THIS SAME PROBLEM.

-83-

1 2 Vehicle: 2012 Kia Sportage 3 Date Complaint Filed: 05/27/2017 Date of Incident: 05/24/2017 4 Component(s): ENGINE 5 NHTSA ID Number: 10991919 6 **SUMMARY:** 7 DRIVING DOWN THE FREEWAY AT 80MPH (SPEED 8 LIMIT IN IDAHO), RPMS STARTED TO REV OVER 6K. HEARD A TICKING SOUND, THEN A VERY LOUD 9 BANG, FOLLOWED BY A BIG PUFF OF BLACK SMOKE. 10 ALL IN THE SPAN OF AROUND 20 SECONDS. CAR DIED 11 ON THE FREEWAY, HAD TO COAST TO GET IN EMERGENCY LANE. THEN THE CHECK ENGINE LIGHT 12 CAME ON. THERE WAS NO INDICATION OF ENGINE 13 ISSUES UNTIL IT WAS FAR TOO LATE. THANKFUL THE CARS BEHIND ME WERE PAYING ATTENTION OR I 14 WOULD HAVE BEEN IN AN AWFUL ACCIDENT WITH 15 AN 18 WHEELER. MECHANIC FOUND THAT ENGINE HAD THROWN A ROD AND PUT A HOLE IN THE 16 ENGINE BLOCK. 106K MILES ON THE VEHICLE, DID 17 NOT EXPECT TO HAVE ENGINE FAILURE THIS EARLY. 18 THIS VIN IS NOT PART OF THE CURRENT RECALL, I BELIEVE IT SHOULD BE, AS IT HAS BEEN PROPERLY 19 MAINTAINED AND SHOULD NOT HAVE FAILED ON 20 THE FREEWAY WITH NO INDICATION OF PROBLEMS UNTIL IT WAS TOO LATE. 21 22 23 Vehicle: 2012 Kia Sportage Date Complaint Filed: 05/22/2017 24 Date of Incident: 04/24/2017 25 Component(s): ENGINE NHTSA ID Number: 10991094 26 27 **SUMMARY:** 28 CRUISING ALONG AT FREEWAY SPEED, 75 MPH, -84-Consolidated Class Action Complaint

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

VEHICLE MOMENTARILY LOST POWER AS IF IT WAS 1 GOING TO STALL OR DOWN SHIFT. UPON RESUMING 2 SPEED, HEARD A TAPPING NOISE AND A LOUD BANG. 3 SAW SMOKE COMING OUT THE BACK OF THE VEHICLE AND OBJECTS TOSSED OUT. SAW A 4 VEHICLE FOLLOWING IN MY LANE. SWERVE AS IF 5 AVOIDING AN OBJECT BUT DID NOT STOP. COASTED TO THE SIDE OF THE FREEWAY, NOTICED A TRAIL OF 6 OIL. UPON PARKING, CHECKED UNDERNEATH THE 7 ENGINE COMPARTMENT, NOTICED OIL DRIPPING 8 AND METAL PIECES, AND WHAT APPEARED TO BE A HOLE IN THE OIL PAN. VEHICLE WAS TOWED TO A 9 DEALERSHIP AND WAS TOLD, A COUPLE OF DAYS 10 LATER, THAT THE VEHICLE MAY BE SUBJECT TO A RECALL FOR SIMILAR DEFECTS. DOING AN ONLINE 11 QUERY, I NOTICED THAT THE 2.4 ENGINE FOR THIS 12 MODEL WAS NOT A PART OF THE RECALL 13 CAMPAIGN, ALTHOUGH OTHER MODELS WITH THE 2.4 ENGINE WERE. 14 15 FORTUNATELY, IT APPEARS THAT NO FOLLOWING VEHICLES WERE HIT WITH ANY OF THE DEBRIS 16 COMING OFF THE VEHICLE. UPON CHECKING THE 17 SIDE OF THE FREEWAY, I PICKED UP WHAT 18 APPEARED TO BE A PIECE OF THE ENGINE'S CONNECTING ROD. HAD THIS PIECE HIT A 19 FOLLOWING VEHICLE, IT COULD'VE RESULTED IN 20 PROPERTY DAMAGE OR UNKNOWN INJURIES TO ITS OCCUPANTS. 21 22 23 Vehicle: 2012 Kia Sportage Date Complaint Filed: 04/09/2014 24 Date of Incident: 04/03/2014 25 Component(s): ENGINE NHTSA ID Number: 10578489 26 **SUMMARY:** 27 DRIVING ON THE INTERSTATE, THE ENGINE OF THE 28 CAR GAVE OUT. I WAS GIVEN ZERO WARNING -85-

Consolidated Class Action Complaint Case No. 8:17-cy-00838-JLS-JDE

BEFORE THE ENGINE COMPLETELY DIED AND I WAS 1 FORCED TO PULL MY CAR OFF TO THE SIDE OF THE 2 ROAD. I WAS LUCKY THAT THE CAR BEHIND ME DID 3 NOT HIT ME. THE CAR IS ONLY 2 YEARS OLD WITH ABOUT 30,000 MILES AND THIS SHOULD NOT HAVE 4 HAPPENED. IT PUT MY LIFE AND THAT OF MY 11 5 MONTH OLD SON AT RISK. THE PUBLIC NEEDS TO BE AWARE OF THIS ISSUE! NO ONE SHOULD HAVE TO 6 WORRY ABOUT BEING IN A FATAL ACCIDENT DUE TO 7 KIA'S FAULTY PARTS. \*TR 8 9 Vehicle: 2012 Kia Sportage 10 Date Complaint Filed: 03/24/2014 Date of Incident: 03/20/2014 11 Component(s): ENGINE 12 NHTSA ID Number: 10574623 13 **SUMMARY:** 14 AT APPROXIMATELY 5:30AM, I WAS DRIVING DOWN 15 THE FREEWAY. MY KIA SPORTAGE SUDDENLY MADE A LOUD BANG, AND THE ENGINE STALLED. IT ALSO 16 SHUT OFF THE HEADLIGHTS, AND DISABLED THE 17 POWER STEERING, WHILE ON A CURVE, GOING 18 70MPH. THE POWER ASSISTED BRAKES WERE ALSO NOT WORKING, BECAUSE THE ENGINE SHUT DOWN. I 19 MANAGED TO PULL THE VEHICLE OVER WITHOUT 20 INCIDENT, BUT WAS ALMOST HIT BY SEVERAL VEHICLES THAT COULD NO LONGER SEE ME. 21 BECAUSE MY LIGHTS WERE OFF. THE ENGINE 22 WOULD NOT START UP AGAIN, AND I HAD TO HAVE 23 THE VEHICLE TOWED HOME. THIS IS THE 3RD TIME THIS VEHICLE HAS DONE THIS, AND KIA REFUSES TO 24 REPAIR THE VEHICLE. \*TR 25 26 Vehicle: 2013 Kia Sportage 27 Date Complaint Filed: 09/19/2017 28 Date of Incident: 09/08/2017

-86-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

Component(s): ENGINE

NHTSA ID Number: 11024230

#### **SUMMARY:**

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

JUST BEFORE REACHING TRYON, NC, COMING FROM CHARLESTON, SC, WE BEGAN TO HEAR A DISTINCT KNOCKING NOISE COMING FROM UNDER THE HOOD, AND WERE UNABLE TO ACCELERATE ANY FURTHER THAN AROUND 55 MPH. EVENTUALLY THE ENGINE FAILED AND WE WERE ABLE TO JUST PULL OFF TO THE SIDE OF THE ROAD JUST YARDS FROM WHERE THE SHOULDER ENDED, AND WE ALMOST HIT A STATIONARY VEHICLE JUST IN FRONT OF US ON THE SHOULDER. WE WERE TRYING TO EVACUATE FROM THE HURRICANE WITH MY 7 MONTH OLD GRANDDAUGHTER.. AFTER THE ENGINE HAD COOLED, WE CHECKED AND MADE SURE THAT MY OIL WAS OVER HALF FULL, AND IT WAS. A RENTAL PLACE STAYED OPEN A FEW EXTRA HOURS FOR US, AND WE MANAGED TO GET TO OUR DESTINATION THREE HOURS AWAY FROM THE INCIDENT, BECAUSE WE WERE IN DESPERATE NEED OF SOMEWHERE THAT ALLOWED DOGS. ON MONDAY, WE FOUND OUT FROM THE MECHANIC THE CAR HAD EVENTUALLY BEEN TOWED TO THAT THE ENGINE WAS SHOT. THE MECHANIC LET US KNOW THAT THIS WAS AN EXTREMELY COMMON ISSUE WITH OUR MAKE AND MODEL, AND THAT WE SHOULD HAVE HAD A RECALL ISSUED FOR SAFETY MEASURES. WHILE IN ASSEMBLY THERE WAS A MANUFACTURING ERROR WHICH WOULD NOT BE NOTICED UNLESS THE DRIVER WAS GOING LONG DISTANCE ON THE HIGHWAY. THERE WERE TINY METAL SHAVINGS WITHIN THE ENGINE THAT BLOCKED THE OIL FROM PROPERLY CIRCULATING THROUGH THE ROD BEARINGS TO CRITICAL PARTS OF THE ENGINE. WE CONTACTED CORPORATE, AND THEY TOLD US OUR CAR WAS NOT LISTED UNDER THE WARRANTY BECAUSE IT WAS ASSEMBLED IN A DIFFERENT

-87-

LOCATION THAN THE ONES RECALLED. THEY THEN 1 TOLD US I HAD A 60,000 MILE WARRANTY INSTEAD 2 OF A 100,000 MILE, WHICH WAS A FLAT OUT LIE. WE 3 CONTACTED OUR DEALER AND THEY CONFIRMED WE HAD A 100K. NOW AFTER COLLECTING ALL OF 4 OUR SERVICE RECORDS, THE DEALERSHIP IS TRYING 5 TO TELL US THEY WILL NOT COVER THE 7,000 DOLLAR COST BECAUSE MY OIL WAS LOW, WHICH IS 6 ANOTHER FLAT OUT LIE. I DON'T WANT TO MAKE 7 ANY MONEY OFF THEM, I JUST WANT MY REPAIRS 8 COVERED. 9 10 Vehicle: 2013 Kia Sportage Date Complaint Filed: 08/18/2017 11 Date of Incident: 06/26/2017 12 Component(s): ENGINE 13 NHTSA ID Number: 11016229 **SUMMARY:** 14 2013 KIA SPORTAGE ENGINE FAILURE IN JUNE OF 15 2017. I WAS DRIVING THE VEHICLE EASTBOUND AT 75MPH ON INTERSTATE 10 BEAR BLYTHE, AZ IN 16 SIGNIFICANT TRAFFIC. THE ENGINE SHUT OFF AND 17 POWER STEERING FAILED. I ABLE TO AVOID A 18 COLLISION BUT SPUN OUT INTO THE INTERSTATE MEDIAN. 19 20 I HAD THE VEHICLE TOWED TO A KIA DEALERSHIP IN AVONDALE, AZ, KIA DEALERSHIP CONFIRMED THE 21 ENGINE HAD SEIZED. KIA DENIED WARRANTY 22 COVERAGE FOR ENGINE CLAIMING IT IS NOT PART 23 OF THE KIA ENGINE SAFETY RECALL CAMPAIGN SC147. KIA CLAIMS THE ENGINE WAS 24 MANUFACTURED IN KOREA SO IT IS NOT INCLUDED. 25 HOWEVER, THERE ARE AT LEAST 6 OTHER "NOT COVERED" SPORTAGE'S PARKED IN SERVICE LOT 26 AWAITING REPAIR. SERVICE MANAGER REPORTED 27 TO ME THAT KIA IS DENYING THE COVERAGE WHEN 28 HE "KNOWS" THE ENGINE PROBLEM IS CAUSED BY A

-88-

#### DEFECTIVE MANUFACTURING PROCESS.

Vehicle: 2014 Kia Sportage

Date Complaint Filed: 08/28/2016

Date of Incident: 08/03/2016 Component(s): ENGINE

NHTSA ID Number: 10902014

#### **SUMMARY:**

WHILE DRIVING MY LEASED 2014 KIA SPORTAGE, THERE WAS NONSTOP CONTINUOUS HESITATION "BUCKING", WITH WHITE SMOKE BLOWING OUT OF THE TAILPIPE, LOSS OF SPEED THEREFORE HAVING TO PRESS HARD ON GAS PEDAL TO AVOID ACCIDENT BY TRYING PULL OFF ROAD. THIS HAPPENS ON CITY ROADS AND HIGHWAY. NO DASHBOARD LIGHT INDICATED THERE WAS A PROBLEM. THE SERVICE ADVISOR AT DESTINATION KIA SAID MY MODEL DOES NOT COME WITH WARNING LIGHTS.

IT APPEARS TO BE AN OIL PROBLEM. OIL LEVEL GOES DOWN WITH NO VISIBLE SIGNS OF LEAKING. I ONLY HAVE 24,000 ON MY KIA SPORTAGE, WITH ONE YEAR LEFT ON MY LEASE. I AM NOT ABLE TO DRIVE THE VEHICLE AS I AM IN FEAR OF STALLING IN TRAFFIC CAUSING MYSELF OR OTHERS TO BE INJURED.

104. Upon information and belief, Defendants regularly monitor these NHSTA databases as part of its ongoing obligation to identify potential defects in its vehicles. NHTSA complaints establish that KMA knew, or should have known, of the engine defect *at least* as early as October 11, 2011 based on publicly available information, years before the Class Vehicles at issue in this litigation were sold. Upon information and belief,

<sup>&</sup>lt;sup>7</sup> NHTSA ID No. 10429442, *supra* at p. 44.

Defendants became aware of the engine defect earlier than June 2013 via: (1) Defendants' own records of customers' complaints, (2) dealership repair records, (3) records from NHTSA, (4) warranty and post-warranty claims, (5) pre-sale durability testing and part sales, and (6) other various sources.

#### C. <u>Pre-Sale Durability Testing</u>

- 105. Defendants are experienced in the design and manufacture of consumer vehicles. As experienced manufacturers, Defendants conduct tests, including pre-sale durability testing, on incoming components, including the engine, to verify the parts are free from defects and align with Defendants' specifications.
- 106. Kia conducts expansive presale durability testing on its vehicles to make they "endure over a long time without fault." This presale testing includes seven different types of durability tests: (1) an item durability test; (2) a module durability test; (3) a Belgian road test; (4) a high-speed test; (5) a corrosion test; (6) a P/T test; and (7) a vehicle test. Kia conducts these tests "in extreme weather conditions including desert with blazing sunlight and coldness of 40 degrees below zero."
- 107. Specifically, regarding testing its engines, Kia states that it puts "our engines through rigorous testing in the highest, hottest and coldest places that a car can possibly be before we use them in our cars."
- 108. In addition, Kia conducts extensive "driving test[s]" in which it puts "our cars to endurance test under diverse harsh conditions that can be encountered on Earth" because "[a]ny fault in your car can affect your safety." Kia expands on six different road tests that it conducts, including a durability test on a road "so rough that driving around 10,000 miles on it gives the same effect of driving around 60,000 on regular roads. Cars that survive the test only can be presented to customers."
  - 109. In addition, John Juriga, the Director of Powertrain at Kia in 2015, stated

<sup>&</sup>lt;sup>8</sup> <a href="http://www.kia.com/worldwide/experience\_kia/rnd/performance.do">http://www.kia.com/worldwide/experience\_kia/rnd/performance.do</a> (last visited Nov. 20, 2017).

that Kia's validation testing is among the toughest in the automotive industry. Among other things, this validation testing runs the engine at maximum throttle (the maximum speed the engine can operate under) while under full load "so we're stressing the components as much as possible and we run it virtually nonstop for 300 hours." After, Kia does an "overrun spec" where it runs it over spec for 10-20 hours to make sure it can survive past the red line limits in order to "make sure these products stay durable in the customers' hands."

- 110. Moreover, Kia also uses "the most extreme and rigorous vehicle testing program ever devised by the company." As part of this test, Kia stimulates stop-and-go driving repeated over several times to "put additional strain on the engine, transmission and HVAC systems and eliminate any possible flaws." In addition, at its Mojave Proving Grounds test site, Kia utilizes a "high-speed oval, gravel off-road tracks, high-vibration road surfaces, brake test facilities and different gradients. These each enable engineers to evaluate and refine the ride, handling, brakes and NVH of prototype and production vehicles."
- 111. As a result, Kia was well aware of the engine defect prior to the Class Vehicles being sold to Class Members.

#### D. <u>Defendants' Warranty-Related Practices</u>

- 112. KMA issued two relevant warranties with each Kia Class Vehicle: a "New Vehicle Limited Warranty," and a "Powertrain Warranty."
- 113. Under the basic New Vehicle Limited Warranty, KMA agreed to repair defects reported within the earlier of 5 years or 60,000 miles.

<sup>&</sup>lt;sup>9</sup> https://www.youtube.com/watch?v=GNPB3RtHN2M (last visited Nov. 21, 2017).

<sup>&</sup>lt;sup>10</sup>http://www.hyundaimotorgroup.com/MediaCenter/News/Press-Releases/kmc-hot-weather-test-all-new-Kia-Sportage-150917.hub#.WhRXYziourF (last visited Nov. 21, 2017).

114. Under the Powertrain Warranty, KMA agreed to repair defects affecting various powertrain components through 10 years and 100,000 miles. According to the Warranty and Consumer Information Manual, Powertrain Coverage Components include:

**In the Engine:** Cylinder block, cylinder head and all internal parts, timing gear, seals and gaskets, valve cover, flywheel, oil pump, water pump and turbo charger.

**In the Transaxle:** Transmission case and all internal parts, torque converter, drive shafts, universal joints, front hubs, bearings, seals and gaskets.

**In the Transmission**: Transmission case, transfer case, torque converter and all internal parts, seals, and gaskets.<sup>11</sup>

- 115. KMA instructs vehicle owners and lessees to bring their vehicles to a Kia dealership for the warranty repairs. Many owners and lessees have presented Kia Class Vehicles to Kia dealerships with complaints related to the engine defect.
- 116. In addition to the above warranties, KMA has also issued a 10 year/120,000 mile warranty on the short blocks contained in all 2011-14 Kia Class Vehicles. (*See* Section A.2, *supra*).
- 117. KMA has evaded its warranty obligations by failing to tell consumers that their vehicles are defective and by representing that the cause of the defect is the owner's neglect to properly maintain the engine oil and/or engine oil level. This representation, however, is false as the engine is inherently defective and will inevitably fail. *See* Exhibit 2 ("October 21, 2016 KMA sees continuing cost related VOQs [Vehicle Owner Questionnaire] and determines dealers are not approving extended warranty repairs due to customer lack of oil maintenance proof.").
- 118. In addition, KMA has also evaded its warranty obligations by requiring consumers to produce the entire maintenance history of the Kia Class Vehicles, including a mandate that all oil changes be completed at a Kia dealership, before determining whether

<sup>&</sup>lt;sup>11</sup> See, e.g., <a href="http://www.kia.com/us/k3/content/media/all/warranty/2014\_warranty.pdf">http://www.kia.com/us/k3/content/media/all/warranty/2014\_warranty.pdf</a> (last visited August 7, 2017).

15

17

18

20

21 22

23

24

25

26 27

28

to make the necessary repairs under warranty. See Id. KMA, however, knows that the defect in the Kia Class Vehicles' engines manifests even if the owner or lessee has followed Kia's oil change guidelines. Even if consumers produce their vehicles' maintenance history, KMA blames the defect and engine failure on the consumer, refuses to cover the necessary repairs under warranty, and charges as much as \$10,000 to repair/replace the engine.

119. Kia also advertises that it offers "an industry-leading Kia 10-year or 100,000mile warranty program." With respect to the powertrain warranty, however, Kia publicizes the existence of 10 year/100,000 mile powertrain warranty but fails to mention that subsequent owners only receive powertrain warranty coverage for 5 years/60,000 miles. As such, subsequent owners are left to discover the limited warranty coverage after purchasing their vehicle. Kia's failure to cover repairs under the powertrain warranty between 5 years/60,000 miles and 10 years/100,000 miles is therefore unconscionable and the warranty reduction should be unenforceable. A typical Kia advertisement touting its warranty is pictured below:



120. In many instances, consumers have incurred and will continue to incur expenses for the diagnosis of the defect (despite such defect having been contained in the Kia Class Vehicles when manufactured by Defendants), repair and replacement of the GDI

8

### 9 10

11

12 13

14

15

16 17

18

19

20

21 22

23

24

25

26

27 28 Engine and the unnecessary and premature replacement of the connecting rods, crank shaft, oil pump, and other engine components.

121. Furthermore, a number of Class Members who presented their Kia Class Vehicles to Kia dealerships because of issues related to the defective connecting rod bearings and insufficient engine oil lubrication channels were denied warranty repairs and, instead, were informed that nothing was wrong with their vehicles. As a result, after expiration of the warranty period, Class Members are forced to pay costly repairs to correct the defect.

#### **CLASS ALLEGATIONS**

122. Plaintiffs bring this action on their own behalf, and on behalf of a nationwide class pursuant to Federal Rules of Civil Procedure 23(a), 23(b)(2), and/or 23(b)(3).

#### **Nationwide Class:**

All persons or entities in the United States who are current or former owners and/or lessees of a Class Vehicle.

123. In the alternative to the Nationwide Class, and pursuant to Federal Rule of Civil Procedure 23(c)(5), Plaintiffs seek to represent the following state classes only in the event that the Court declines to certify the Nationwide Class above. Specifically, the state classes consist of the following:

#### **California Class:**

All persons or entities in California who are current or former owners and/or lessees of a Class Vehicle for primarily personal, family or household purposes, as defined by California Civil Code § 1791(a).

#### **Maine Class:**

All persons or entities in Maine who are current or former owners and/or lessees of a Class Vehicle.

124. Together, the California Class, the Maine Class, and the Nationwide Class shall be collectively referred to herein as the "Class." Excluded from the Class are KMA,

their affiliates, employees, officers and directors, persons or entities that purchased the Class Vehicles for resale, and the Judge(s) assigned to this case. Plaintiffs reserve the right to modify, change, or expand the Class definitions based on discovery and further investigation.

- 125. <u>Numerosity</u>: Upon information and belief, the Class is so numerous that joinder of all members is impracticable. While the exact number and identities of individual members of the Class are unknown at this time, such information being in the sole possession of Defendant and obtainable by Plaintiffs only through the discovery process, Plaintiffs believe, and on that basis allege, that hundreds of thousands of Class Vehicles have been sold and leased in each of the states that are the subject of the Class.
- 126. Existence and Predominance of Common Questions of Fact and Law: Common questions of law and fact exist as to all members of the Class. These questions predominate over the questions affecting individual Class Members. These common legal and factual questions include, but are not limited to, whether:
  - a. The Class Vehicles were sold with a defect;
  - b. Defendants knew of the defect but failed to disclose the problem and its consequences to their customers;
  - c. A reasonable consumer would consider the defect or its consequences to be material;
  - d. Defendants have failed to provide free repairs as required by their New Vehicle Limited Warranty and/or Powertrain Warranty;
  - e. Defendants should be required to disclose the existence of the defect; and
  - f. Defendants' conduct violates the California Legal Remedies Act, California Unfair Competition Law, and the other statutes asserted herein.
- 127. <u>Typicality</u>: All of Plaintiffs' claims are typical of the claims of the Class because Plaintiffs purchased Class Vehicles with the same engine defect, defective vehicle design, and defective engine, as did each member of the Class. Furthermore, Plaintiffs and -95-

all Members of the Class sustained monetary and economic injuries including, but not limited to, ascertainable losses arising out of Defendants' wrongful conduct. Plaintiffs are advancing the same claims and legal theories on behalf of themselves and all absent Class Members.

- 128. Adequacy: Plaintiffs are adequate representatives because their interests do not conflict with the interests of the Class that they seek to represent, they have retained counsel who are competent and highly experienced in complex class action litigation, and they intend to prosecute this action vigorously. The interests of the Class will be fairly and adequately protected by Plaintiffs and their counsel.
- efficient adjudication of the claims of Plaintiffs and Members of the Class. The injury suffered by each individual Class member is relatively small in comparison to the burden and expense of individual prosecution of the complex and extensive litigation necessitated by Defendants' conduct. It would be virtually impossible for Members of the Class individually to redress effectively the wrongs done to them. Even if the Members of the Class could afford such individual litigation, the court system could not. Individualized litigation presents a potential for inconsistent or contradictory judgments. Individualized litigation increases the delay and expense to all parties, and to the court system, presented by the complex legal and factual issues of the case. By contrast, the class action device presents far fewer management difficulties, and provides the benefits of single adjudication, an economy of scale, and comprehensive supervision by a single court. Upon information and belief, members of the Class can be readily identified and notified based on, *inter alia*, Defendants' vehicle identification numbers, warranty claims, registration records, and database of complaints.
- 130. Defendants have acted, and refused to act, on grounds generally applicable to the Class, thereby making appropriate final equitable relief with respect to the Class as a whole.

#### FIRST CAUSE OF ACTION

#### VIOLATIONS OF CALIFORNIA'S CONSUMER LEGAL REMEDIES ACT

("CLRA") (Cal. Civ. Code § 1750, et seq.)

#### (On Behalf of the Nationwide Class or, Alternatively, the California Class)

- 131. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 132. Plaintiffs bring this claim on behalf of themselves and on behalf of the Nationwide Class. Alternatively, Plaintiffs Stanczak, Centko, and Lazar bring this claim on behalf of themselves and on behalf of the California Class against Defendants.
- 133. Defendants are persons as that term is defined in California Civil Code § 1761(c).
- 134. Plaintiffs and the Class Members are "consumers" as that term is defined in California Civil Code §1761(d).
- 135. Defendants engaged in unfair and deceptive acts in violation of the CLRA by the practices described above, and by knowingly and intentionally concealing from Plaintiffs and Class Members that the Class Vehicles suffer from a defect(s) (and the costs, risks, and diminished value of the vehicles as a result of this problem). These acts and practices violate, at a minimum, the following sections of the CLRA:
  - (a)(2) Misrepresenting the source, sponsorship, approval or certification of goods or services;
  - (a)(5) Representing that goods or services have sponsorships, characteristics, uses, benefits or quantities which they do not have, or that a person has a sponsorship, approval, status, affiliation or connection which he or she does not have;
  - (a)(7) Representing that goods or services are of a particular standard, quality, or grade, or that goods are of a particular style or model, if they are of another; and
  - (a)(9) Advertising goods and services with the intent not to sell them as advertised.

- 136. Defendants' unfair or deceptive acts or practices occurred repeatedly in Defendants' trade or business, were capable of deceiving a substantial portion of the purchasing public, and imposed a serious safety risk on the public.
- 137. Defendants knew that the Class Vehicles and GDI Engines were defectively designed or manufactured, would fail prematurely, and were not suitable for their intended use.
- 138. Defendants were under a duty to Plaintiffs and the Class Members to disclose the defective nature of the Class Vehicles and the defective nature of the connecting rod bearings and insufficient engine oil lubrication channels because:
  - Defendants were in a superior position to know the true state of facts about the safety defect and associated repair costs in the Class Vehicles and their engines;
  - b. Plaintiffs and the Class Members could not reasonably have been expected to learn or discover that the Class Vehicles and their engine had dangerous safety defect until manifestation of the defect;
  - c. Defendants knew that Plaintiffs and the Class Members could not reasonably have been expected to learn or discover the safety and security defect and the associated repair costs that it causes until the manifestation of the defect; and
  - d. Defendants actively concealed the safety and security defect and the associated repair costs by asserting to Plaintiffs and Class Members that the cause of their engine problems was the result of Plaintiffs' and the Class Members' inability to maintain the proper engine oil levels despite knowing the repairs needed to correct the defect.
- 139. In failing to disclose the engine defect and the associated safety risks and repair costs that result from it, Defendants have knowingly and intentionally concealed material facts and breached their duty to disclose.

- 140. The facts concealed or not disclosed by Defendants to Plaintiffs and the Class Members are material in that a reasonable consumer would have considered them to be important in deciding whether to purchase Defendants' Class Vehicles or pay a lesser price. Had Plaintiff and the Class known about the defective nature of the Class Vehicles and their engines, they would not have purchased the Class Vehicles or would have paid less for them.
- 141. On or about June 2, 2016, Plaintiffs' counsel provided Defendant KMA with notice of their violations of the CLRA pursuant to California Civil Code § 1782(a) regarding the engine defect in the MY 2011-13 Kia Sportage, 2011-14 Kia Optima and 2012-14 Kia Sorento vehicles.
- 142. On or about March 8, 2017, Plaintiffs' counsel, in the Centko matter, provided Defendant KMA with notice of their violations of the CLRA pursuant to California Civil Code § 1782(a) regarding the engine defect contained in the MY 2010-17 Kia vehicles equipped with the GDI engine.
- 143. On or about June 8, 2017, Plaintiffs' counsel, in the Stanczak matter, provided Defendant KMA with notice of their violations of the CLRA pursuant to California Civil Code § 1782(a) regarding the engine defect contained in the MY 2015-16 Kia Sportage, Optima and Sorento vehicles.
- 144. Plaintiffs and the other Class Members' injuries were proximately caused by Defendants' fraudulent and deceptive business practices.
- 145. Therefore, Plaintiffs and the other Class Members seek all relief available under the CLRA.

#### **SECOND CAUSE OF ACTION**

#### VIOLATIONS OF THE CALIFORNIA UNFAIR COMPETITION LAWS

(Cal. Bus. & Prof. Code § 17200)

#### (On Behalf of the Nationwide Class or, Alternatively, the California Class)

146. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.

- 147. Plaintiffs bring this claim on behalf of themselves and on behalf of the Nationwide Class. Alternatively, Plaintiffs Stanczak, Centko, and Lazar bring this claim on behalf of themselves and on behalf of the California Class against Defendants.
- 148. The California Unfair Competition Law ("UCL") prohibits acts of "unfair competition," including any "unlawful, unfair or fraudulent business act or practice" and "unfair, deceptive, untrue or misleading advertising." Cal. Bus. & Prof. Code § 17200.
- 149. Defendants have engaged in unfair competition and unfair, unlawful or fraudulent business practices by the conduct, statements, and omissions described above, and by knowingly and intentionally concealing from Plaintiffs and the Class Members that the Class Vehicles suffer from a defect (and the costs, safety risks, and diminished value of the vehicles as a result of these problems). Defendants should have disclosed this information because they were in a superior position to know the true facts related to the defect, and Plaintiffs and Class Members could not reasonably be expected to learn or discover the true facts related to the defect.
- 150. The defective connecting rod bearings and insufficient engine oil lubrication channels constitute a safety issue that triggered Defendants' duty to disclose the safety issue to consumers.
- 151. These acts and practices have deceived Plaintiffs and are likely to deceive the public. In failing to disclose the defect and suppressing other material facts from Plaintiffs and the Class Members, Defendants breached their duties to disclose these facts, violated the UCL, and caused injuries to Plaintiffs and the Class Members. The omissions and acts of concealment by Defendants pertained to information that was material to Plaintiffs and the Class Members, as it would have been to all reasonable consumers.
- 152. The injuries suffered by Plaintiffs and the Class Members are greatly outweighed by any potential countervailing benefit to consumers or to competition, nor are they injuries that Plaintiffs and the Class Members should have reasonably avoided.

153. Defendants' acts and practices are unlawful because they violate California Civil Code §§ 1668, 1709, 1710, and 1750 *et seq.*, and California Commercial Code § 2313.

154. Plaintiffs seek to enjoin further unlawful, unfair and/or fraudulent acts or practices by Defendants, to obtain restitutionary disgorgement of all monies and revenues generated as a result of such practices, and all other relief allowed under California Business & Professions Code § 17200.

#### **THIRD CAUSE OF ACTION**

#### VIOLATION OF CALIFORNIA FALSE ADVERTISING LAW

(Cal. Bus. & Prof. Code § 17500, et seq.)

#### (On Behalf of the Nationwide Class or, Alternatively, the California Class)

- 155. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 156. Plaintiffs bring this claim on behalf of themselves and on behalf of the Nationwide Class. Alternatively, Plaintiffs Stanczak, Centko, and Lazar bring this claim on behalf of themselves and on behalf of the California Class against Defendants.
- 157. California Business & Professions Code § 17500 states: "It is unlawful for any . . . corporation . . . with intent directly or indirectly to dispose of real or personal property . . . to induce the public to enter into any obligation relating thereto, to make or disseminate or cause to be made or disseminated . . . from this state before the public in any state, in any newspaper or other publication, or any advertising device, . . . or in any other manner or means whatever, including over the Internet, any statement . . . which is untrue or misleading, and which is known, or which by the exercise of reasonable care should be known, to be untrue or misleading."
- 158. Defendants caused to be made or disseminated through California and the United States, through advertising, marketing and other publications, statements that were untrue or misleading, and which were known, or which by the exercise of reasonable care

should have been known to Defendants, to be untrue and misleading to consumers, including Plaintiffs and the other Class Members.

- 159. Defendants have violated section 17500 because the misrepresentations and omissions regarding the safety, reliability, and functionality of their Class Vehicles as set forth in this Complaint were material and likely to deceive a reasonable consumer.
- 160. Plaintiffs and the other Class Members have suffered an injury in fact, including the loss of money or property, as a result of Defendants' unfair, unlawful, and/or deceptive practices. In purchasing or leasing their Class Vehicles, Plaintiffs and the other Class Members relied on the misrepresentations and/or omissions of Defendants with respect to the safety and reliability of the Class Vehicles. Defendants' representations were untrue because the Class Vehicles are distributed with defective connecting rod bearings and insufficient engine oil lubrication channels. Had Plaintiffs and the other Class Members known this, they would not have purchased or leased their Class Vehicles or would not have paid as much for them. Accordingly, Plaintiffs and the other Class Members overpaid for their Class Vehicles and did not receive the benefit of their bargain.
- 161. All of the wrongful conduct alleged herein occurred, and continues to occur, in the conduct of Defendants' businesses. Defendants' wrongful conduct is part of a pattern or generalized course of conduct that is still perpetuated and repeated, both in the state of California and nationwide.
- 162. Plaintiffs, individually and on behalf of the other Class Members, request that this Court enter such orders or judgments as may be necessary to enjoin Defendants from continuing their unfair, unlawful, and/or deceptive practices and to restore to Plaintiffs and the other Class Members any money Defendants acquired by unfair competition, including restitution and/or restitutionary disgorgement, and for such other relief set forth below.

#### **FOURTH CAUSE OF ACTION**

#### VIOLATION OF MAINE UNFAIR TRADE PRACTICES ACT

(On Behalf of the Maine Class)

- 163. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 164. Plaintiff Creps brings this claim on behalf of herself and on behalf of the Maine Class against Defendants.
- 165. Plaintiff Creps and the Maine Class are persons as that term is defined by Me. Rev. Stat. Ann. tit. 5, § 206(2).
- 166. Defendants are engaged in "trade" and "commerce" as those terms are defined by Me. Rev. Stat. Ann. tit. 5, § 206(3).
- 167. Maine's Unfair Trade Practices Act prohibits "[u]nfair methods of competition and unfair or deceptive acts or practices in the conduct of any trade or commerce." Me. Rev. Stat. Ann. tit. 5, § 207.
- 168. Defendants have engaged in unfair competition and unfair, unlawful or fraudulent business practices by the conduct, statements, and omissions described above, and by knowingly and intentionally concealing from Plaintiff Creps and the Class Members that the Class Vehicles suffer from a defect (and the costs, safety risks, and diminished value of the vehicles as a result of these problems). Defendants should have disclosed this information because they were in a superior position to know the true facts related to the defect, and Plaintiff Creps and Class Members could not reasonably be expected to learn or discover the true facts related to the defect.
- 169. The defective connecting rod bearings and insufficient engine oil lubrication channels constitute a safety issue that triggered Defendants' duty to disclose the safety issue to consumers.
- 170. These acts and practices have deceived Plaintiff Creps and are likely to deceive the public. In failing to disclose the defect and suppressing other material facts from Plaintiff Creps and the Class Members, Defendants breached their duties to disclose

these facts, violated Maine's Unfair Trade Practices Act, and caused injuries to Plaintiff Creps and the Class Members. The omissions and acts of concealment by Defendants pertained to information that was material to Plaintiff Creps and the Class Members, as it would have been to all reasonable consumers.

- 171. The injuries suffered by Plaintiff Creps and the Class Members are greatly outweighed by any potential countervailing benefit to consumers or to competition, nor are they injuries that Plaintiff Creps and the Class Members should have reasonably avoided.
- 172. The facts concealed or not disclosed by Defendants to Plaintiff Creps and the Class Members are material in that a reasonable consumer would have considered them to be important in deciding whether to purchase Defendants' Class Vehicles or pay a lesser price. Had Plaintiff Creps and the Class known about the defective nature of the Class Vehicles and their engines, they would not have purchased the Class Vehicles or would have paid less for them.
- 173. Plaintiff Creps' and the other Class Members' injuries were proximately caused by Defendant's fraudulent and deceptive business practices.
- 174. Plaintiff Creps has provided Defendants with notice of these violations pursuant to Me. Rev. Stat. Ann. tit. 5, § 213(1-A).
- 175. Plaintiff seeks all relief available under Maine's Unfair Trade Practices Act, including the recovery of attorneys' fees and costs pursuant to Me. Rev. Stat. Ann, tit. 5, § 213(2).

#### **FIFTH CAUSE OF ACTION**

#### **BREACH OF EXPRESS WARRANTY**

## (On Behalf of the Nationwide Class or, Alternatively, the California Class and Maine Class)

- 176. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 177. Plaintiffs bring this claim on behalf of themselves and on behalf of the Nationwide Class or, alternatively, on behalf of each of the state subclasses.

- 178. Defendants provided all purchasers and lessees of the Class Vehicles with the express warranties described herein, which became part of the basis of the bargain. Accordingly, Defendants' warranties are express warranties under state law.
- 179. The parts affected by the defect, including the rotating assembly and engine block, were distributed by Defendants in the Class Vehicles and are covered by the warranties Defendants provided to all purchasers and lessors of Class Vehicles.
- 180. Defendants breached these warranties by selling and leasing Class Vehicles with the defect, requiring repair or replacement within the applicable warranty periods, and refusing to honor the warranties by providing free repairs or replacements during the applicable warranty periods.
- 181. Plaintiffs notified Defendants of the breach within a reasonable time, and/or were not required to do so because affording Defendants a reasonable opportunity to cure their breaches of written warranty would have been futile. Defendants also knew of the defect and yet have chosen to conceal it and to fail to comply with their warranty obligations.
- 182. As a direct and proximate cause of Defendants' breach, Plaintiffs and the other Class Members bought or leased Class Vehicles they otherwise would not have, overpaid for their vehicles, did not receive the benefit of their bargain, and their Class Vehicles suffered a diminution in value. Plaintiffs and Class Members have also incurred and will continue to incur costs related to the diagnosis and repair of the defective connecting rod bearings and insufficient engine oil lubrication channels.
- 183. Defendants' attempt to disclaim or limit these express warranties vis-à-vis consumers is unconscionable and unenforceable under the circumstances here. Specifically, Defendants' warranty limitation is unenforceable because they knowingly sold a defective product without informing consumers about the defect.
- 184. The time limits contained in Defendants' warranty period were also unconscionable and inadequate to protect Plaintiffs and members of the Class. Among other things, Plaintiffs and Class Members had no meaningful choice in determining these

time limitations, the terms of which unreasonably favored Defendants. A gross disparity in bargaining power existed between Defendants and the Class Members, and Defendants knew or should have known that the Class Vehicles were defective at the time of sale and would fail well before their useful lives.

185. Plaintiffs and the Class Members have complied with all obligations under the warranty, or otherwise have been excused from performance of said obligations as a result of Defendants' conduct described herein.

### SIXTH CAUSE OF ACTION

#### **BREACH OF IMPLIED WARRANTY**

## (On Behalf of the Nationwide Class or, Alternatively, the California Class and Maine Class)

- 186. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 187. Plaintiffs bring this claim on behalf of themselves and on behalf of the Nationwide Class or, alternatively, on behalf of each of the state subclasses.
- 188. Defendants were at all relevant times the manufacturer, distributor, warrantor, and/or seller of the Class Vehicles. Defendants knew or had reason to know of the specific use for which the Class Vehicles were purchased.
- 189. Defendants provided Plaintiffs and the other Class members with an implied warranty that the Class Vehicles and any parts thereof are merchantable and fit for the ordinary purposes for which they were sold. However, the Class Vehicles are not fit for their ordinary purpose of providing reasonably reliable and safe transportation at the time of sale or thereafter because, *inter alia*, the Class Vehicles and their engines suffered from defective connecting rod bearings and insufficient engine oil lubrication channels at the time of sale that causes the vehicles to experience premature and catastrophic engine failure. Therefore, the Class Vehicles are not fit for their particular purpose of providing safe and reliable transportation.

190. Defendants impliedly warranted that the Class Vehicles were of merchantable quality and fit for such use. This implied warranty included, among other things: (i) a warranty that the Class Vehicles and their engines were manufactured, supplied, distributed, and/or sold by Defendants were safe and reliable for providing transportation and would not experience premature and catastrophic engine failure; and (ii) a warranty that the Class Vehicles and their engines would be fit for their intended use while the Class Vehicles were being operated.

- 191. Contrary to the applicable implied warranties, the Class Vehicles and their engines at the time of sale and thereafter were not fit for their ordinary and intended purpose of providing Plaintiffs and the other Class Members with reliable, durable, and safe transportation. Instead, the Class Vehicles suffer from a defective design(s) and/or manufacturing defect(s).
- 192. Defendants' actions, as complained of herein, breached the implied warranty that the Class Vehicles were of merchantable quality and fit for such use.

#### **SEVENTH CAUSE OF ACTION**

## BREACH OF WRITTEN WARRANTY UNDER THE MAGNUSON-MOSS WARRANTY ACT (15 U.S.C. § 2301, et seq.)

## (On behalf of the Nationwide Class or, Alternatively, the California Class, and Maine Class)

- 193. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 194. Plaintiffs bring this claim on behalf of themselves and on behalf of the Nationwide Class or, alternatively, on behalf of the state subclasses.
- 195. Plaintiffs and the Class are "consumers" within the meaning of the Magnuson-Moss Warranty Act, 15 U.S.C. § 2301(3).
- 196. Defendants are suppliers and warrantors within the meaning of 15 U.S.C. §§ 2301(4)-(5).

6

9

11

13

16

20

22

26

27 28

- 197. The Class Vehicles are "consumer products" within the meaning of 15 U.S.C. § 2301(1).
- 198. Defendants' 5 year/60,000 miles Basic Warranty and 10 year/100,000 miles Powertrain Warranty are "written warranties" within the meaning of 15 U.S.C. § 2301(6).
  - 199. Defendants breached the express warranties by:
    - Providing a 5 year/60,000 miles Basic Warranty and a 10 a. year/100,000 miles Powertrain Warranty with the purchase or lease of the Class Vehicles, thereby warranting to repair or replace any part defective in material or workmanship at no cost to the owner or lessee;
    - b. Selling and leasing Class Vehicles with engines that were defective in materials and/or workmanship, requiring repair or replacement within the warranty period; and
    - Refusing and/or failing to honor the express warranties by c. repairing or replacing, free of charge, the engine or any of its component parts in order to remedy the defective connecting rod bearings and insufficient engine oil lubrication channels.
- 200. Plaintiffs and the other Class Members relied on the existence and length of the express warranties in deciding whether to purchase or lease the Class Vehicles.
- 201. Defendants' breach of the express warranties has deprived Plaintiffs and the other Class Members of the benefit of their bargain.
- 202. The amount in controversy of Plaintiffs' individual claims meets or exceeds the sum or value of \$25.00. In addition, the amount in controversy meets or exceeds the sum or value of \$50,000 (exclusive of interests and costs) computed on the basis of all claims to be determined in this suit.
- 203. Defendants have been afforded a reasonable opportunity to cure their breach of the written warranties and/or Plaintiffs and the other Class Members were not required to do so because affording Defendants a reasonable opportunity to cure their breach of

written warranties would have been futile. Defendants were also on notice of the alleged defect from the complaints and service requests it received from Class Members, as well as from their own warranty claims, customer complaint data, and/or parts sales data.

204. As a direct and proximate cause of Defendants' breach of the written warranties, Plaintiffs and the other Class Members sustained damages and other losses in an amount to be determined at trial. Defendants' conduct damaged Plaintiffs and the other Class Members, who are entitled to recover actual damages, consequential damages, specific performance, diminution in value, costs, including statutory attorney fees and/or other relief as deemed appropriate.

### EIGHTH CAUSE OF ACTION

#### **COMMON LAW FRAUD**

## (On Behalf of the Nationwide Class or, Alternatively, the California Class and Maine Class)

- 205. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 206. Plaintiffs bring this claim on behalf of themselves and on behalf of the Nationwide Class or, alternatively, on behalf of the state subclasses.
- 207. Defendants made material omissions concerning a presently existing or past fact. For example, Defendants did not fully and truthfully disclose to their customers the true nature of the inherent defect with the GDI Engine, which was not readily discoverable until years later, often after the New Vehicle Limited Warranty or the Powertrain Warranty has expired. As a result, Plaintiffs and the other Class Members were fraudulently induced to lease and/or purchase the Class Vehicles with the said defect and all of the resultant problems.
- 208. These omissions were made by Defendants with knowledge of their falsity, and with the intent that Plaintiffs and the Class Members rely on them.
- 209. Plaintiffs and the Class Members reasonably relied on these omissions, and suffered damages as a result.

## 45

## 6

### 7 8

### 9

## 10

#### 11

### 12

## 1314

### 15

### 16

#### 17

#### 18

#### 19

#### \_\_\_

### 20

## 2122

#### 23

### 24

## 2526

### 27

## 28

#### **NINTH CAUSE OF ACTION**

#### BREACH OF THE DUTY OF GOOD FAITH AND FAIR DEALING

# (On Behalf of the Nationwide Class or, Alternatively, the California Class and Maine Class)

- 210. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 211. Plaintiffs bring this claim on behalf of themselves and on behalf of the Nationwide Class or, alternatively, on behalf of the state subclasses.
- 212. All contracts in California and Maine contain an implied covenant of good faith and fair dealing. The implied covenant of good faith and fair dealing is an independent duty and may be breached even if there is no breach of a contract's express terms.
- 213. Defendants breached the covenant of good faith and fair dealing by, *inter alia*, failing to notify Plaintiffs and Class Members of the defective connecting rod bearings and insufficient engine oil lubrication channels in the Class Vehicles, and failing to fully and properly repair this defect.
- 214. Defendants acted in bad faith and/or with a malicious motive to deny Plaintiffs and the Class Members some benefit of the bargain originally intended by the parties, thereby causing them injuries in an amount to be determined at trial.

#### TENTH CAUSE OF ACTION

## VIOLATION OF THE SONG-BEVERLY ACT – BREACH OF IMPLIED WARRANTY

(Cal. Civ. Code §§ 1792, 1791.1, et seq.)

## (On Behalf of the Nationwide Class or, Alternatively, the California Class and Maine Class)

- 215. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 216. Plaintiffs bring this claim on behalf of themselves and on behalf of the Nationwide Class or, alternatively, on behalf of the state subclasses.

- 217. At all relevant times hereto, Defendants were the manufacturer, distributor, warrantor, and/or seller of the Class Vehicles. Defendants knew or should have known of the specific use for which the Class Vehicles were purchased.
- 218. Defendants provided Plaintiffs and the Class Members with an implied warranty that the Class Vehicles, and any parts thereof, are merchantable and fit for the ordinary purposes for which they were sold. The Class Vehicles, however, are not fit for their ordinary purpose because, *inter alia*, the Class Vehicles and their engines suffered from an inherent defect at the time of sale that causes the Class Vehicles to experience premature and catastrophic engine failure.
- 219. The Class Vehicles are not fit for the purpose of providing safe and reliable transportation because of the defect.
- 220. Defendants impliedly warranted that the Class Vehicles were of merchantable quality and fit for such use. This implied warranty included, *inter alia*, the following: (i) a warranty that the Class Vehicles and their engines were manufactured, supplied, distributed, and/or sold by Defendants were safe and reliable for providing transportation and would not prematurely and catastrophically fail; and (ii) a warranty that the Class Vehicles and their engines would be fit for their intended use providing safe and reliable transportation while the Class Vehicles were being operated.
- 221. Contrary to the applicable implied warranties, the Class Vehicles and their engines at the time of sale and thereafter were not fit for their ordinary and intended purpose. Instead, the Class Vehicles are defective, including, but not limited to, the engine defect and/or manufacture of the GDI Engines.
- 222. Defendants' actions, as complained of herein, breached the implied warranty that the Class Vehicles were of merchantable quality and fit for such use in violation of California Civil Code §§ 1792 and 1791.1.

**PRAYER FOR RELIEF** 1 2 WHEREFORE, Plaintiffs, on behalf of themselves and members of the Class, 3 respectfully request that this Court: A. determine that the claims alleged herein may be maintained as a class action 4 5 under Rule 23 of the Federal Rules of Civil Procedure, and issue an order certifying one or more Classes as defined above; 6 B. appoint Plaintiffs as the representatives of the Classes and their counsel as Class 7 8 counsel: C. award all actual, general, special, incidental, statutory, punitive, and 9 consequential damages and restitution to which Plaintiffs and the Class Members 10 11 are entitled; 12 D. award pre-judgment and post-judgment interest on such monetary relief; E. grant appropriate injunctive and/or declaratory relief, including, without 13 limitation, an order that requires Defendants to repair, recall, and/or replace the 14 Class vehicles and to extend the applicable warranties to a reasonable period of 15 time, or, at a minimum, to provide Plaintiffs and Class Members with appropriate 16 17 curative notice regarding the existence and cause of the engine defect; F. award reasonable attorneys' fees and costs; and 18 19 G. grant such further relief that this Court deems appropriate. Respectfully submitted, 20 Dated: November 30, 2017 21 /s/ David C. Wright By:\_\_ 22 Richard D. McCune 23 David C. Wright MCCUNE WRIGHT AREVALO LLP 24 3281 Guasti Road, Suite 100 25 Ontario, California 91761 26 Telephone: (909) 557-1250 Facsimile: (909) 557-1275 27 Email: rdm@mccunewright.com 28 dcw@mccunewright.com -112-

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE

#### Joseph G. Sauder 1 Matthew D. Schelkopf\* 2 Joseph B. Kenney 3 MCCUNE WRIGHT AREVALO LLP 555 Lancaster Avenue 4 Berwyn, Pennsylvania 19312 5 Telephone: (909) 557-1250 Email: jgs@mccunewright.com 6 mds@mccunewright.com 7 jbk@mccunewright.com 8 Bonner Walsh 9 WALSH PLLC 10 21810 Pine Crest Dr. Bly, Oregon 97622 11 Telephone: (541) 359-2827 12 Facsimile: (866) 503-8206 13 Email: bonner@walshpllc.com 14 Adam Gonnelli 15 THE SULTZER LAW GROUP, PC 280 Highway 35, Suite 304 16 Red Bank, NJ 07701 17 Telephone: (732) 741-4290 Facsimile: (888) 749-7747 18 Email: gonnellia@thesultzerlawgroup.com 19 20 \*Pro Hac Vice Applications to be Submitted Attorneys for Plaintiffs and Putative Class 21 22 23 24 25 26 27 28 -113-Consolidated Class Action Complaint

Case No. 8:17-cv-00838-JLS-JDE

Case 8:17-cv-00838-JLS-JDE Document 54 Filed 11/30/17 Page 113 of 114 Page ID

**JURY DEMAND** Plaintiffs, on behalf of themselves and the putative Class, demand a trial by jury on all issues so triable. McCune Wright Arevalo LLP By: /s/ David C. Wright David C. Wright Attorneys for Plaintiffs and Putative Class -114-Consolidated Class Action Complaint

Consolidated Class Action Complaint Case No. 8:17-cv-00838-JLS-JDE